

*Questions for exam of course rate
"Technology of mechanical engineering", part 1*


Name: _____ Gr. _____ Date: _____

1. How to check and set the indicating hole gage?

2. For what purposes are the gage blocks used? Describe the procedure for building the gage block combinations (for example, 125.673 mm).

3. For what are the purposes limits gages used? Enumerate its principal kinds.

4. Explain the following symbols:



A _____

B _____

C


D

E

F

G

5. Explain the following symbols:



A

B

C

D

E

F

6. Explain the following symbols:



A _____

B _____

C _____

D _____

7. Complete the following sentences:

1) The roughness average is

Ra =

2) The standard values of the roughness sampling length ℓ are (mm):

3) The height of the profile roughness by ten points is

Rz =

8. How to measure a part ($d=75.1$ mm) by the method of relative measurements?

9. Define the minimum and maximum clearances for the fit 20H7/g6

10. Define the limiting interferences for the fit 80H7/s7

11. Define the limiting interference and clearance for the fit 50H7/n6

12. Define the deviations of limit gages to check the shaft and the hole of the fit 30H7/g6.

13. Define limit diameters of a screw and a nut for the thread junction M16 x 2-7H/6g.

14. What does 7-6-7-Ca/V -128 mean?

Answer (question 12): 30H7 NOT-GO \rightarrow 30.023 $_{-0.004}$ mm
30H7GO \rightarrow 30.005 $_{-0.004}$ mm
30H7GO_{wear} \rightarrow 30.005 $_{-0.007}$ mm
30g6 NOT-GO \rightarrow 29.978 $^{+0.004}$ mm
30g6 GO \rightarrow 29.988 $^{+0.004}$ mm
30g6 GO_{wear} \rightarrow 29.988 $^{+0.007}$ mm

Answer (question 13): $D_{\min} = 16$ mm

$$d = 16^{-0.038}_{-0.318} \text{ mm}$$

$$D_2 = 14.701^{+0.265} \text{ mm}$$

$$d_2 = 14.701^{-0.038}_{-0.163} \text{ mm}$$

$$D_1 = 13.835^{+0.475} \text{ mm}$$

$$d_{1\max} = 13.707 \text{ mm}$$