

**TOMSK POLYTECHNIC UNIVERSITY**

**V. F. Skvortsov**

**FUNDAMENTALS OF MECHANICAL  
ENGINEERING**

**Tomsk Polytechnic University Publishing House  
2013**

UDC 621  
BBC 00000  
S00

**Skvortsov V.F.**

S00 Fundamentals of Mechanical Engineering: study aid / V.F. Skvortsov;  
Tomsk Polytechnic University. – Tomsk: TPU Publishing House, 2013, 234 p.

The book presents theoretical foundations of mechanical engineering, examines planning of the manufacturing and assembly processes, the review questions are given in the end of the chapters.

The book is prepared by the Department of Automated Mechanical Manufacturing Engineering Department of Tomsk Polytechnic University and is intended for English-speaking students following the Bachelor Degree Program in Mechanical Engineering.

**UDC 621**  
**BBC 00000**

*Linguistic Advisor*  
Senior lecturer of the  
Department of Foreign Languages of the Institute of Cybernetics, TPU  
*A.I. Chudinova*

*Reviewers*

Doctor of Science (Technical)  
Associate professor of the  
Department of Automation and Robotisation in Mechanical Engineering, TPU  
*M.G. Goldshmidt*

President of Industrial Company “MION”, Limited Liability Company  
*Yu.V. Volkov*

© STE HPT TPU, 2013  
© Skvortsov V.F., 2013  
© Design. Tomsk Polytechnic University  
Publishing House, 2013

## Preface

Mechanical engineering is the most important economic sector. Mechanical engineering products, machines for different purposes, are supplied to all industries, agriculture, transportation, determining the level of their development. Mechanical engineering plays an extremely important role in providing national defense.

The process of creating a machine is divided into two stages. The first step involves engineering design of a machine and involves creation of the drawings necessary for manufacture. The second step is development and implementation of manufacturing and assembly of the machine that is the main task of mechanical engineering. These steps are closely interrelated. Indeed, it is impossible to develop a good design of the machine without taking technology of its production into account. The adopted processes of manufacturing and assembling determine machine quality and production costs. The technological development allows for new design solutions, providing increase in the quality of the machines and reduction of their costs.

The modern view on the mechanical engineering has formed on the basis of research and development of many generations of Russian and foreign scientists and engineers who contributed to its establishment as a branch of engineering science. Mechanical engineering studies laws of the machinery manufacture, in order to use these laws to ensure required quality of the machines and minimum cost of the production.

A great contribution to the establishment and development of mechanical engineering was made by Russian scientists B.S. Balakshin, V.M. Kovan, I.M. Kolesov, V.S. Korsakov, A.A. Matalin, S.P. Mitrofanov, A.P. Sokolovsky and many others.

The proposed book for the course of "Fundamentals of Mechanical Engineering" is intended for students that follow the Bachelor Degree Program 150700 "Mechanical Engineering". The book covers all major topics of the course and reflects experience of teaching at Tomsk Polytechnic University.

The first section of the book provides basic concepts of mechanical engineering production.

The second section covers fundamentals of locating and dimensional chains theory. Methods for ensuring accuracy of resulting dimensions and tolerance analysis for the developed manufacturing processes are given.

The third section is devoted to questions of ensuring properties of the part material and part accuracy. Considerable attention is focused on formation of

the surface layer quality. The basic causes of machining errors, methods of their estimation and elimination are examined.

The fourth section examines the ways to improve machining productivity and reduce cost of parts production.

The fifth section presents fundamentals of the manufacturing processes design.

The sixth section considers types and forms of organization of assembly, and sequence and content of the main stages of the assembly process design.

The author expresses his deep gratitude to the scientific editor and reviewers for their helpful comments, and to academic assistant L.A. Ogol, TPU, for her help in preparing the manuscript for publication.

## CONTENTS

Preface.....	3
CONTENTS.....	5
<b>1. Basic Concepts and Definitions of Mechanical Engineering Production</b>	<b>8</b>
1.1. Product and Product Life Cycle .....	8
1.2 Product Quality .....	11
1.3 Production and Manufacturing Processes.....	14
1.4 Standard Time.....	18
1.5 Methods of Production .....	22
1.6 Productivity .....	25
1.7 Prime Cost of a Product .....	26
Review Questions .....	28
<b>2. Dimensional Chains and Principles of Part Locating</b> .....	<b>29</b>
2.1 Fundamentals of Part Locating .....	29
2.1.1 General Concepts of Datums and Locating.....	29
2.1.2 Classification of Datums.....	33
2.2 Fundamentals of Dimensional Chain Theory .....	38
2.2.1 Basic Concepts and Definitions.....	38
2.2.2 Basic Equations .....	43
2.2.3 Methods of Ensuring Accuracy of Resulting Dimensions.....	49
2.2.3.1 Complete Interchangeability Method .....	49
2.2.3.2 Incomplete Interchangeability Method .....	52
2.2.3.3 Method of Group Interchangeability .....	54
2.2.3.4 Fitting Method.....	59
2.2.3.5 Adjustment Method .....	60
2.2.4 Tolerance Analysis of Manufacturing Processes .....	61
Review Questions .....	72
<b>3. Ensuring Material Properties and Accuracy of a Part</b> .....	<b>73</b>
3.1 Ensuring Material Properties .....	73
3.1.1 General Ideas on Formation of Material Properties during Manufacturing .....	73
3.1.2 Surface Layer Quality and its Influence on Part Performance Characteristics.....	79
3.1.2.1 Components of Surface Layer Quality .....	79
3.1.2.2 Measurement of Surface Layer Quality Parameters ...	80
3.1.2.3 Influence of Surface Layer Quality on Part Performance Characteristics.....	83

3.1.3	Ensuring Surface Layer Quality during Manufacturing.....	86
3.1.3.1	Ensuring Surface Layer Quality during Machining .....	86
3.1.3.2	Ensuring Surface Layer Quality by Cold Working Processes .....	95
3.1.3.3	Ensuring Surface Layer Quality by Electrochemical Machining and Vacuum Annealing.....	97
3.2	Ensuring Part Accuracy .....	98
3.2.1	Causes of Machining Errors. Ensuring Accuracy during Machining .....	98
3.2.1.1	Geometrical Errors of Machine Tools .....	99
3.2.1.2	Elastic Deformations of Technological System due to Cutting Forces .....	103
3.2.1.3	Cutting Tool Wear .....	111
3.2.1.4	Thermal Deformation of Technological System .....	115
3.2.1.5	Warping of Workpieces due to Residual Stresses .....	120
3.2.1.6	Error of Sizing Tool Manufacturing and Error of Theoretical Machining Scheme .....	125
3.2.1.7	Error of Workpiece Mounting.....	127
3.2.1.8	Error of Manufacturing System Setting .....	135
3.2.1.9	Determination of Total Machining Error of Processing Step .....	143
3.2.2	Ensuring Accuracy During Manufacturing Process .....	144
	Review Questions .....	146
4.	Improving Technical-Economic Efficiency of Manufacturing.....	148
4.1	Technological Ways of Increasing Machining Productivity .....	148
4.1.1	Operation Cycle per Part Minimization .....	148
4.1.2	Setup Time Minimization. Multiple Machining.....	154
4.2	Prime Cost Minimization .....	158
4.2.1	Multiple-machine Manning.....	158
4.2.2	Reduction of Materials Cost.....	160
4.2.3	Reduction of Costs for Manufacturing Process Planning. Typification of Manufacturing Processes .....	161
	Review Questions .....	163
5.	Fundamentals of Manufacturing Process Design .....	164
5.1	General Concepts. Principles and Sequence of Manufacturing Process Design .....	164
5.2	Analysis of Drawing Specifications and Identification of Part Manufacturing Objectives.....	167
5.3	Production Method Identification .....	168
5.4	Analysis of a Drawing for Manufacturability .....	169
5.5	Selection of a Workpiece .....	175

5.6 Selection of Manufacturing Datums .....	180
5.6.1 Principles of Manufacturing Datums Selection .....	180
5.6.2 Selection of Manufacturing Datums for the First Operation	185
5.6.3 Selection of Manufacturing Datums for most Operations .....	190
5.7 Selection of Machining Routes for Individual Surfaces of a Part.	191
5.8 Design of Manufacturing Process Route. Selection of Manufacturing Equipment and Operations.....	193
5.9 Tolerance Analysis of Developed Manufacturing Process.....	196
5.9.1 Identification of Tolerances for Manufacturing Dimensions	197
5.9.2 Identification of Minimum Tolerances for Manufacturing ...	202
5.9.3 Calculation of Manufacturing Dimensions.....	209
5.10 Selection of Cutting Parameters and Standards of Time .....	213
5.11 Definition of Technical-Economic Parameters of Manufacturing Process.....	215
Review Questions .....	217
6. Fundamentals of Product Assembling Processes.....	218
6.1 General Concepts. Classification of Joining Methods. Types of Assembly .....	218
6.2 Forms of Assembly Organization.....	220
6.3 Fundamentals of Assembling Process Design .....	222
6.3.1 Input data and Sequence of Assembling Process Design .....	223
6.3.2 Analysis of Assembly Drawings for Manufacturability .....	224
6.3.3 Design of Assembly Sequence. Assembling Process Design...	226
Review Questions .....	231
References .....	232

# 1. Basic Concepts and Definitions of Mechanical Engineering Production

## 1.1. Product and Product Life Cycle

*Product* is a finished item of the mechanical production. It can be a machine, an assembly unit, a workpiece or a component.

*Machine* – a mechanism or a combination of mechanisms that perform actions to transform energy, materials or to execute work. At present, almost all the machines are mechatronic systems. The mechanical part of the systems is made at manufacturing plants, electronics are manufactured at enterprises of electronics industry.

A *workpiece*, in mechanical engineering, is a product used for parts manufacture. The workpiece that is used in the first machining operation is called the *initial workpiece*.

A *part* or a *component* is an item made from a homogeneous, by name and grade, material without assembly operations. Examples of parts are: shaft made from one piece of metal, molded case, bimetallic plate, plastic flywheel (without reinforcing elements). The same parts but with coatings (protective or decorative) are also considered as parts, as well as parts manufactured with the use of local welding, soldering, gluing, for example, a tube, soldered or welded from one piece of sheet material.

An *assembly unit* is a product, parts of which are to be joined at the manufacturing plant by means of assembling operations. The assembly unit may consist of individual components or subassemblies of higher order and components. The assembly unit of the first order is fitted directly into the machine. The first-order assembly unit may consist of individual components or subassemblies of the second-order and components. The second-order assembly unit may include a third-order sub-assemblies and components, etc. The assembly unit of the highest order consists of the individual components only.

Thus, the composition of the product (machine) can be represented as the diagram shown in Fig. 1.1.

In addition to these kinds of products, the complexes and sets are distinguished in mechanical engineering.






Fig. 1.1 Composition of a mechanical product

*Complex* – two or more specified products that are not joined at the manufacturing plant by assembly operations but designed to perform interrelated maintenance functions (such as automatic line of machine tools, drilling rig, ship, etc.).

*Set* – two or more items that are not joined together at the manufacturing plant by assembly operations, and represent a set of products that share a common operational purpose of accessory character (e.g., spare parts kit, tool kit, etc.).


Products, according to their purpose are divided into the products of main and auxiliary production. The first are intended for sale, the second are for the internal needs of the enterprise.

A set of interrelated processes of serial change of the product state, from the formulation of initial product requirements and to the end of its operation, is called product *life cycle*.

The life cycle for the mechanical product is schematically shown in Fig. 1.2.

At the start, company studies market demand for the product and its consumer properties, then performs R&D and engineering activities and creates competitive product. Almost at the same time the engineering design and manufacturing process planning is carried out. The engineering design involves product designing and issue of the technical documentation (drawings, parts lists, etc.). Process planning consists in designing the processes of product assembly and processes of the product parts manufacture, designing and manufacturing of cutting tools, measuring instruments, fixture and other equipment, and preparation of the relevant documentation. Along with design-engineering

preparation and process planning a prototype product is produced, tested and undergone research work in order to improve prototype design and production process. After completion of the design-engineering preparation and process planning the mass production begins.



*Fig. 1.2 Life cycle of a mechanical product*

The product usage is accompanied by its maintenance and operating repair, then overhaul, and a partial disposal afterwards. Upon reaching the period of depreciation or obsolescence the product is recycled or disposed.

## 1.2 Product Quality

*Product quality* is the group of product properties that determine its ability to meet certain requirements in accordance with its use.

The quality of mechanical products is assessed with the system of parameters that are usually divided into:

- the parameters of engineering level;
- performance parameters;
- engineering and manufacturing parameters (or the parameters of construction manufacturability).

The parameters of engineering level are: *power, productivity, coefficient of efficiency, accuracy, degree of mechanization and automatization, efficiency, environmental friendliness* etc.

Performance parameters are: reliability; *ergonomic characteristic*, i.e. the level of taken into account group of hygienic, physiological and other human needs in the system human – product (machine) – environment; *aesthetic estimate*, i.e. design perfection, product exterior design etc.

The most important product quality parameter is its reliability. It is a complex parameter, which consists of failure-free performance, durability, repairability and storageability.

*Reliability* is the property of a product to maintain values of all parameters, which characterize the ability to perform the required functions under the given regimes, application conditions, maintenance and transportation during the definite time period and within the prescribed limits.

*Failure-free performance* is the property of a product to maintain continually the operable state in the course of time. The indicator of failure-free performance can be, for example, mean time to failure.

*Durability* is the property of a product to maintain the operable state before the beginning of maximum permissible state under the adopted system of maintenance and repair. The example of durability parameter can be mean service life.

*Repairability* is the property of a product to be adapted for preventing, finding and correct the failures and malfunctions through the servicing.

*Storageability* is the property of a product to maintain the operable state


during and after storage and (or) transportation.

Engineering and manufacturing parameters of product quality (the parameters of manufacturability) reflect technological rationality of product design.

*Manufacturability* is the group of properties of product design that determine its adaptability to achieve the economic cost during manufacturing, maintenance for the specified quality parameters, production volume and work conditions. Manufacturability of product designs is assessed qualitatively (“good” – “bad”, “rational” – “irrational”, “technological” – “non-technological”) and quantitatively.

Bearing housing, for example, can have different designs (Fig. 1.3, *a*, *b*). The length of the machined surface and its machining costs reduce in design (Fig. 1.3, *b*), that is why this design is the only rational. The structural element of the cover can have different versions (Fig. 1.3, *c*, *d*). Unbalanced radial force appears when drilling hole at an angle and this force can cause breakage of the drill. That is why configuration of the cover element shown in Fig. 1.3, *d* is rational.

The main quantity parameters of manufacturability of industrial product are labour intensity, material consumption and manufacturing cost.



*Fig. 1.3 Examples of poor and good designs in terms of manufacturability*

*Labour intensity* of product manufacturing is represented by labour spent on executing processes of its manufacturing.

*Material consumption* is the amount of material necessary for manufacturing and operation.

*Manufacturing cost* of the product includes the expenses of the enterprise in monetary form for manufacturing one unit of production.

Product optimization for manufacturability is made while designing, i.e. it is made by design engineers. Manufacturing engineers carry out *technological inspection* of design documentation about meeting requirements for manufacturability while developing manufacturing processes.

The questions of ensuring manufacturability of product designs are considered in more details in Sections 5 and 6.

The most important parameter of product quality is its geometrical accuracy. The accuracy of products is characterized by dimension tolerances, tolerances of form and location. Accuracy of products is characterized by the accuracy of relative motion or the position of the working surfaces that depends on the accuracy of components and the accuracy of assembling these products. So, for example, one of the characteristics of geometrical accuracy of a lathe are tolerances of the spindle axis parallelism with respect to the direction of slides travel in vertical and horizontal planes.

The accuracy of manufacturing engineering products is constantly improving. It has been improved in about 50 times for the last 100 years; dimension tolerances of separate parts now are 1  $\mu\text{m}$  and less. It can be explained either by increased speed of machines or by the tendency to enhance their reliability. With machine speed increasing, the dynamic loading of its parts grow inevitably and their longevity decreases. Usually, these forces can be reduced only by improving the accuracy of parts and assembly of the machine. In constant operating conditions, raise of accuracy of parts enhances their reliability. For example, improving accuracy of parts for a ball bearing and reducing radial clearance from 20 to 10  $\mu\text{m}$  increases the service life of the ball bearing from 740 to 1200 hours.

The accuracy of parts is also of great importance for the process of their manufacturing. Improving the accuracy of parts increases the level of interchangeability and eliminates fitting in the process of machines assembly. Improving the accuracy of workpieces decreases the amount of mechanical machining and makes it cheaper.

Two main tasks for accuracy are solved in mechanical engineering:

- the required accuracy of a machine and its parts is determined;
- this accuracy is ensured in the process of manufacturing.

The first task is solved by design engineers and the second one is solved by manufacturing engineers.

Determination of the necessary accuracy is the critical stage in the work of design engineers. It is performed on the basis of the analysis of machine operating conditions with regard to dynamic phenomena, the experience of operating machines of a similar type, geometry analysis and tolerance analysis and also on the basis of specially set up experiments and tests on product proto-

type.

To ensure defined accuracy, manufacturing engineers develop corresponding manufacturing processes for manufacturing parts and assembling the machines, they define necessary methods and means of accuracy inspection, analyze practical accuracy of manufacture, they reveal causes of intolerable errors when manufacturing if needed, and look for the ways to improve accuracy of products.

### 1.3 Production and Manufacturing Processes

*Production process* is a set of all actions of people and tools needed at the enterprise for manufacturing and repairing products. The process covers: preparation of means of production and organization of workplace maintenance; receipt and storage of materials and semi-finished products; all stages of manufacturing process, products assembly; transportation of materials, workpieces, components and finished products; technical inspection at all stages of production; packaging of finished products and other activities related to the production of products. The most important element of the production process is the process planning, which includes engineering design of the product and manufacturing process planning, and production scheduling as well.

*Manufacturing process* is a part of the production process, that incorporates actions aimed at changing and (or) defining the state of the subject of labour. Various kinds of products are referred to the subjects of labour.

Manufacturing processes are divided into the processes of machining, assembling, casting, heat treatment, coating, etc.

For implementation of any process a set of means of labour, called the *means of manufacturing*, is required.

Means of manufacturing are divided into manufacturing equipment and manufacturing tooling. *Manufacturing equipment* is the means of manufacturing, in which materials and workpieces, as well as the tools, are placed to perform a certain part of the manufacturing process. Examples of manufacturing equipment are machine tools, presses, casting machines, furnaces, electroplating baths, etc.

Means of manufacturing, which are supplementary to the manufacturing equipment, are known as manufacturing tooling (cutting tools, dies, fixtures for mounting workpieces, measuring instruments, etc.).

Manufacturing processes are performed at the work places. A *workspace* is an elementary unit of the company structure that incorporates various work-

ers, manufacturing equipment or part of a production line, as well as tooling and (for a limited period of time) articles of manufacture.

Manufacturing processes are divided into operations. *Manufacturing operation* is a finished part of the manufacturing process that is accomplished on a single workplace. Operation involves all actions of equipment and worker (or workers) upon one or more simultaneously machined or assembled subjects of production. During machining on a machine tool, operation comprises all actions of a machine operator, as well as automatic motions of the machine carried out until workpiece is unloaded from the machine.

Operations are characterized by continuous action upon the subjects of production. Let us take, for example, turning of a batch of stepped shafts which are cut from a rolled bar into workpieces a little bit longer than the length of a finished shaft. If each shaft is turned at one end first, then reclamped and turned at the other end, then the turning of the shafts is a single operation. If all the shafts of a batch are turned at first end and then these shafts are turned at the other end, then the turning of the shafts constitutes two operations.

The content of operations may vary widely – from work performed on a single machine to the work performed on the production line.

Names for operations are given according to the technological equipment on which these operations are performed. The examples are: turning, milling, automatic, pressing, etc.

The operations are numbered in arithmetic progression (5, 10, 15,...). Zeros can be added to the left of the numbers.

Operation is an essential part of the manufacturing process in terms of organizational and economics. Operations are assigned by the standards of time, which determine work-intensiveness of the manufacturing process, required number of production workers and required means of production (equipment, fixtures, tools, etc.).

Operations are divided into set-ups, positions, processing steps and cutting passes.

*Set-up* is a part of a manufacturing operation performed with the machined workpiece or assembled unit being constantly clamped.

For example, if the stepped shaft during turning operation is clamped and turned at one end and then reclamped and turned at the other end, thus, the operation consists of two set-ups.

Set-ups are denoted by capital letters of the alphabet (A, B, C, ...).

*Position* is a fixed orientation of a workpiece or an assembly unit being constantly clamped together with the fixture, relative to the tool or stationary part of the machine during a part of a manufacturing operation.

Fig. 1.4 shows a drilling operation performed on the two-spindle drilling machine with a rotary table. The table is equipped with three three-jaw chucks

for holding the workpieces. The workpiece is clamped in a chuck in the first position (*I*), and then rotated by the table to the second (*II*) and the third (*III*) position, in which the hole is drilled and enlarged respectively. Afterwards, the workpiece comes back to the first position where it is unloaded from the machine and replaced with the next workpiece.

Thus, the constantly clamped workpiece successively takes three different positions relatively to the cutting tool, i.e., the operation comprises three positions. For the purposes of denoting positions the Roman numerals (*I*, *II*, *III*, ...) are used.




Fig. 1.4 Machining of a workpiece on the dual-spindle machine

*Processing step* is a finished part of the manufacturing operation performed by the same means of technological equipment with the technological parameters and clamping being unchanged.

Processing step is characterized by application of the same type of a tool, or machining/assembling the same surfaces of parts, as well as constant technological parameters.

Turning operation, shown in Fig. 1.5 *a*, contains two processing steps (turning of the surface *1* is the first step and turning of the surface *2* is the second step). When a single surface is cut by a single instrument, the processing step is called *simple* or *elementary*. Fig. 1.5 *b* shows turning operation carried out at a single processing step with two surfaces being turned (*1* and *2*) with two cutting tools. Such processing step, when several tools are used simultaneously is called *complex processing step* (Fig. 1.5, *b*).

When the parts are machined on the CNC machines, a set of surfaces can be successively cut by a single cutting tool (by a cutter, for example) as it moves along a path defined by the program. In this case the processing step is called an *instrumental step*.



The names of processing steps are given in the imperative mood (turn the surface ..., cut the thread ..., broach the slot ...). Processing steps are numbered by natural numbers (1, 2, 3 ...).




Fig. 1.5 Sketches of turning operations: a – simple; b – complex processing steps

Structure of a manufacturing operation is defined by composition, content and sequence of implementation of the processing steps.

Manufacturing operation can be composed either on the basis of *concentration* or *differentiation* of processing steps. The concentration implies that the maximum possible number of processing steps is included in the operation. In the extreme case, the process of parts manufacturing may consist of only a single operation. When the differentiation principle is used, the number of processing steps within an operation tends to minimum. In the extreme case, the manufacturing operation may include only one processing step.

Along with the processing steps, auxiliary steps are implemented.

*Auxiliary step* is a finished part of the manufacturing operation that consists of actions of a worker and (or) equipment that are not accompanied with changing the properties of the subjects of labour, but are necessary for processing step execution.

Examples of auxiliary steps include setting up the workpiece, tool change, for example, by indexing the lathe tool post, etc.

Processing steps are divided into cutting passes.

*Cutting pass* is a finished part of the processing step and consists of a single movement of the cutting tool relative to the workpiece, accompanied by change in shape, size, surface quality and properties of the workpiece.

*Action* is a finished set of worker activities performed during the processing step or its part, united by one purpose. For example, to set the workpiece into the fixture it is necessary to perform the following actions: take the

workpiece from the container, place it into the fixture and clamp the workpiece in the fixture.

## 1.4 Standard Time

As it was already noted, the manufacturing operation is the main element of the manufacturing process. Time and cost of the operation are an important criterion of its effectiveness for a given production plan.

*Production plan* is a list of products, for a given enterprise, that are manufactured or repaired with the specified production volume for a planned period of time. *Production volume* is the amount of products of certain types, sizes and designs, manufactured or repaired by the enterprise within the planned period of time (usually – during one year). Volume of production is crucial for the manufacturing process planning and layout.

For a given volume of production the products, in most cases, are manufactured in batches or lots.

The *production batch* is the portion of products that is launched into manufacture in a certain period of time. Production batch or its part that is delivered to the workplace for machining operation is called operation batch.

Any manufacturing operation requires a certain amount of working time of equipment and workers. Calendar period of time from the start to the end of the operation, regardless of the number of simultaneously machined or repaired products, is called the *operation cycle*.

The period of time equal to the ratio of the operation cycle to the number of simultaneously machined or repaired products or equal to calendar time of assembling operation is called the *operation cycle per part (OCP)*.

In non-automated production the OCP is defined by the following equation:

$$t_{oc} = t_m + t_a + t_w + t_r,$$

where  $t_m$  is the machining time;  $t_a$  is the auxiliary time;  $t_w$  is the workplace maintenance time;  $t_r$  is the worker rest time'

The *machining time* is spent on the change and (or) the subsequent definition of the state of the subject of labour. This time can be of machine, machine-manual or manual type. The machining time for each processing step is calculated as follows:

$$t_m = \frac{Li}{S_m},$$

where  $L$  is the estimated cutting distance (length of the cutting tool travel, mm);  $i$  is the number of passes of the given processing step;  $S_m$  is the feed rate of the cutting tool in mm/min.

With the manual feed of the cutting tool to the workpiece:

$$L = l + l_{en} + l_{ov},$$

where  $l$  is the length of the surface to be machined;  $l_{en}$  is the distance of cutting tool engagement with the workpiece;  $l_{ov}$  is the tool over-travel distance.

For the automatic machining cycle:

$$L = l + l_{en} + l_{ov} + l_{ap},$$

where  $l_{ap}$  is the distance of the tool approach to the workpiece in order to avoid collision in the beginning of machining.

The length  $l$  is found with the help of the drawing, the distances of engagement and overtravel are commonly taken equal to 1 mm. The value of the length of engagement is found geometrically. For longitudinal turning (Fig. 1.6, a)  $l_{en} = t \cdot \operatorname{tg} \varphi$ , where  $t$  is the depth of cut;  $\varphi$  is the cutting edge angle. For drilling with standard twist drills (Fig. 1.6, b)  $l_{en} = 0.3 \cdot d_c$ , where  $d_c$  is the diameter of the drill. For slot milling with a slotting milling cutter (Fig. 1.6, c)  $l_{en} = \sqrt{t(d_m - t)}$ , where  $d_m$  is the milling cutter diameter.




Fig. 1.6 Diagrams for calculation of the estimated cutting distances during turning (a), drilling (b) and slot milling (c)

*Auxiliary time* is the part of the OCPP required to perform actions needed to ensure changes and the subsequent definition of the state of subjects of labour. Auxiliary time is spent on loading, clamping and unloading of the workpiece or the component of the unit being assembled, operating the machinery, feeding the cutting tool to the workpiece and its withdrawal, measurement of the workpiece, etc. Auxiliary time can be defined as the amount of time for all

the auxiliary steps of the operation. The time needed for the execution of the  $i^{\text{th}}$  auxiliary step  $t_{ai}$ , which is a set of  $m$  actions is calculated as:

$$t_{ai} = \sum_{j=1}^{j=m} t_{aj},$$

where  $t_{ai}$  is the time needed for the  $j^{\text{th}}$  action. The time needed for each action is specified according to the auxiliary time standards, which take into account specific conditions of the operation.

The sum of machining time and auxiliary time is called *operation time*  $t_{op}$ . It should be noted that only the portion of the auxiliary time that is not overlapped by the machining time is included into the  $t_{op}$ . For example, during the drilling operation shown in Fig. 1.4, loading, clamping and unloading of workpieces is performed during the machining in positions *II* and *III*, so the time spent on these activities should not be included into the operation time.

*Workplace maintenance time* is a part of OCPP spent by a worker to service the manufacturing equipment and maintain it and the workplace in working condition. It is commonly accepted to distinguish between equipment maintenance time and workplace preparation time, i.e. consider that:

$$t_w = t_e + t_{wp}.$$

*Equipment maintenance time (EMT)* is spent on changing blunt cutting tools, adjusting machinery, chip cleaning and swarf removal from the machining area. The EMT is taken in percents (up to 6%) of the operation time or machining time or taken according to standards depending on the type of work performed.

*Workplace preparation time (WPT)* includes the time required for cleaning and preparing the workplace for work, lubricating the machine at the end of the shift and other similar actions during the shift. This time is taken as a percentage of the operation time (0.6 ... 8%).

*Rest time* is spent on the personal needs of a worker and on breaks during tedious work. This time is also taken as a percentage of operation time (about 2.5%).

In practical calculations, OCPP is calculated by the simplified equation:

$$t_{oc} = t_{op} \left( 1 + \frac{\alpha + \beta + \gamma}{100} \right),$$

where  $\alpha$ ,  $\beta$ ,  $\gamma$  – the EMT, WPT and rest time, respectively, in percentage of the operation time. Values for  $\alpha$ ,  $\beta$ ,  $\gamma$  are taken according to the standard times.

For the automatic equipment the OCPP is determined by the following equation:

$$t_{oc} = t_{op} \left( 1 + \frac{\alpha}{100} \right).$$

When parts are manufactured in batches, the *set-up time*  $t_s$  is calculated. Setup time is defined as a period of time, spent on the preparation of the performer or performers and technological means for manufacturing operation and bringing these means in order after the end of the shift and (or) operation performed for the batch of subjects of labour. Set-up time is spent by a worker to get acquainted with drawings and technical documentation, to prepare and set-up the equipment, tools and fixtures, to remove and deliver cutting tools and fixtures to the store room after manufacturing a batch of parts.

The time spent to manufacture a batch of parts on the operation is:

$$t_r = t_s + t_{oc}n,$$

$n$  is the number of parts in the batch.

Allocation of hours required to perform certain operations and manufacturing process as a whole is one of the most important tasks of the *manufacturing resource planning*, which implies defining technically sound standards of resources consumption (work time, materials, tools, etc.).

*Standard time* is a regulated time for performing amount of work in certain production conditions by one or several workers of appropriate qualification.

It is common to distinguish between standard times for operation cycle per part, operation time, machining time, auxiliary time and set-up time.

If the products are manufactured continuously, then the standard time of the OCPP  $t_{oc}$  is used as the standard time  $H_t$  for an operation, i.e.:

$$H_t = t_{oc}.$$

If the products are manufactured in batches, then the sum of the OCPP  $t_{oc}$  and portion of the setup time  $t_s$  per one part of a batch is used as the standard time  $H_t$  for the operation, i.e.:

$$H_t = t_{oc} + \frac{t_s}{n}.$$

The reciprocal of the standard time is called the standard production rate.

*Standard production rate* is the rated amount of work that must be performed per unit of time in certain organizational and technical conditions, by one or more workers of appropriate qualification. Production rate can be expressed, for example, in a number of workpieces to be machined per unit of time.

To determine standard time the following three methods are used:

- method of calculations according to the technical standard times;
- method of calculation based on observation of working time;
- method of comparison and calculations based on extended standard time.

Standard time is set based on the analysis of the composition of actions of the worker and production equipment at its most advantageous use.

In the first method a standard time for an operation is calculated based on elements of work with the use of standards which specify the estimated time needed to perform these elements of work. In the second method the standard time is set based on the time study of the working process, which is observed directly in the production environment. Commonly, two basic methods of time study by observation are distinguished: the *work sampling* and *workday time study*. During the work-sampling the attention is focused on measuring the time spent on manual and machine-manual elements of the operation (for example, time spent on mounting and clamping a workpiece) to basic times for these elements, as well as to develop on this basis, the relevant standard times. Workday time study involves measurement of working time during a shift or several shifts. Its main purpose is to determine losses of working time, to set standard time for workplace maintenance and breaks. In the third method standard time is determined approximately by the extended standard times, which are developed on the basis of comparison and calculation of typical operations.

## 1.5 Methods of Production

Different goods of mechanical engineering manufacture are produced in different quantities depending on the requirements. Some goods are produced in a single copy; the others are produced in hundreds of thousands.

Three methods of manufacturing can be distinguished, depending on the variety and volume of production. These methods are job production, batch production and mass production. Batch production is subdivided into small-batch production, medium-batch production and large-batch production.

Method of production is defined according to *production factor*  $k_{pf}$  that is the ratio of number of all different operations done or to be done during a month to the number of working places. In other words, this factor shows the average amount of operations done or to be done for the one working place during a month. Production factor is: 1 for mass production; from 1 to 10 for large-batch production; from 10 to 20 for medium-batch production; from 20 to 40 for small-batch production; 40 and more for job production.

*Job production* is characterized by a small volume of outputting similar products. Their remanufacturing and repairing are, as a rule, not planned. Job products are machines of restricted application (prototype machines, large hydro-turbines, unique machine tools, roll mills etc.).

The characteristic feature of job production is performing (at working places) the great number of various operations that may never be repeated. Job production should be very flexible in this connection. General-purpose equipment and standard production fixtures are used in job production. Equipment in workshops is arranged according to its type (a turning machines sector, a milling machines sector, etc.). Manufacturing processes are not usually developed in detail. Qualification of the most workers in job production is high.

*Batch production* is characterized by manufacturing or repairing products in periodically repeated batch lots. Products produced in batches are steady state machine types (metal cutting machine tools, wood-working machine tools, pumps, compressors, aviation engines, etc.) manufactured in significant quantities. This method of production is the most widespread (75-80 per cent of all the products of mechanical engineering are batch products).

The characteristic feature of batch production is relatively small amount of periodically repeated operations (at working places). Both special fixtures and tools and universal fixtures and tools are used in batch production. Equipment in the workshops is arranged according to the manufacturing process or according to its type (small-batch production). Manufacturing processes in batch production are developed in details. Qualification of the most workers is in general lower than in job production but it is still high, for example, for operating the CNC machines.

*Mass production* is characterized by a large volume of outputting products, manufactured or repaired continuously for a long period of time, during which one operation is done at the majority of working places. Mass products are products for the wide range of customers (automobiles, tractors, low-power electric motors, rolling bearings, etc.).

Special high-performance equipment and production accessories are used in mass production. As a rule, equipment in workshops is arranged strongly according to the manufacturing process. Manufacturing processes in mass production are developed in considerable details. Qualification of the most workers is in general low but highly-qualified service engineers are required.

Subdividing the production into the methods is, in a way, relative and is done according to the predominate production. For example, production of bearings in a ball bearing plant is mass. Job production does take place in a repairing shop of the factory.

Two methods of operation are applied in mechanical engineering: *flow production* and *non-flow production*. Flow production is characterized by arranging the equipment according to the sequence of operations in the manufacturing process and definite time intervals of products output. The time interval,

during which products or workpieces of certain names, standard sizes and modifications are periodically issued is called *Takt time*

$$t_d = F_a / N,$$

where  $F_a$  – actual available hours of equipment operation in the scheduling period (a year, a month, a day, a shift, an hour);  $N$  – the volume of production for the same period.

Nominal annual available hours of equipment operation is 2070 hours for one-shift work, 4140 hours for two-shift work and 6210 hours for three-shift work. Actual annual available hours of equipment operation (with regard to loss of time for equipment repair) for one-, two- and three-shift work is 2030, 4015 and 5965 hours, respectively.

In flow production, the work is performed on the production line. In general, the condition for organizing the flow is the multiplicity of time for each manufacturing operation to the Takt time:

$$\frac{t_{oc_i}}{t_d} = k (k = 1, 2, 3 \dots),$$

where  $t_{oc_i}$  – operation cycle per part of  $i^{\text{th}}$  manufacturing operation.

Bringing the times of operations to the required condition is called *production flow synchronisation*. It is achieved by the corresponding sequencing of manufacturing operations and sometimes by using the so-called doubling machine tools, i.e., for example, using not one but two machines for some operations. One product rolls off a flow line for the time equal to Takt time.

The amount of products or workpieces of certain types, sizes and modifications manufactured per time unit is called *production rate*. Ensuring the given production rate is the most important task in planning of manufacturing processes in mass and large-batch productions.

It is often impossible to organize flow production for the manufactured products in batch production due to low use of equipment for small volumes of output. In this case the variant of a flow method of production, called *flexible flow-production*, is used.

In flexible flow-production, each machine on the production line performs a set of operations. During a definite period of time (usually several shifts), machining of workpieces of the same size is performed on the line. Then the line is readjusted for machining workpieces of the other size, etc.

Flow production can:

- reduce production cycle considerably (in dozen times);



- reduce inter-operational buffers and work-in-process;
- apply high-performance equipment and reduce labour intensity of production;
- simplify production control.

In case of small volume of production, non-flow production is used. It is used in batch and job productions. In non-flow production operation time is not synchronized. Buffers of workpieces (assembly units) that are necessary for workplace capacity are created at workplaces. In non-flow production, the maximal technological action upon the subject of labour is tended to be done at every working place, the amount of operations in manufacturing process is aimed to be reduced, that is to design the manufacturing operations on the basis of concentration of processing steps.

## 1.6 Productivity

Productivity  $Q$  is the volume of production  $W$  issued per time unit  $t$ :

$$Q = W / t.$$

There are machine tool productivity, labour productivity, manufacturing process productivity, employee productivity and social labour productivity.

*Machine tool productivity* is calculated by the volume of material removed from the workpiece or by the area of the machined surface per unit of time. Machine tool productivity depends on its power, quality of the tool and machining parameters.

*Employee productivity* is measured by the amount of products manufactured by the employee during the unit of working time. For example, productivity of a machine tool operator is defined by the amount of parts manufactured for an hour or for a shift. Employee productivity depends on the productivity of equipment, labour intensity and work organisation.

*Automatic machine productivity* that fulfills functions of an ordinary machine tool is measured in the same units as the employee productivity.

*Manufacturing process productivity* is measured in production units or in rubles per time unit. Manufacturing process productivity depends not only on the productivity of the equipment and employee productivity but also on the level of manufacturing process organization, planning and management.

*Employee productivity* characterizes operational efficiency of all the corporate team. It is measured by the amount of production in rubles manufactured for the time unit per one employee.

*Social labour productivity* is measured by comparing the amount of production manufactured for some time period with labour costs. In this case the costs of preceding labour used for creating equipment, buildings, operating costs of materialized labour (basic and additional materials, electric energy, tools, etc.) and current costs of direct labour are taken into consideration.

Manufactured production is measured either in natural values (pieces, mass or volume units) or in rubles. Total labour costs are either in abstract labour units (employee-hour, employee-day) or in rubles.

## 1.7 Prime Cost of a Product

Manufacturing a product requires expenses of live and materialized labour. Expenses for materials, jigs, fixtures and tools and salary connected with making the product and expressed financially are called shop costs that will be further called just (prime) costs.

There are machine prime cost, prime costs of machine assembly units and components. It is possible to evaluate the prime costs for separate operations of the processes of parts manufacturing and machines assembling.

Prime costs are defined by formula

$$C = \sum_{i=1}^p M + \sum_{i=1}^m \left[ I + F + T \left( 1 + \frac{a_1 + a_2}{100} \right) S \right],$$

where  $M$  – expenses for materials for a unit of product without prime costs of waste, rubles;  $E$  – amortization expenses, equipment maintenance for a unit of product, rubles;  $F$  – amortization expenses, maintenance of fixtures for a unit of product, rubles;  $T$  – amortization expenses, maintenance of tools for a unit of product, rubles;  $a_1$  – charging for salary expenses for social needs, %;  $a_2$  – burden costs charged for salary expenses, %;  $p$  – the number of different material grades for a unit of product;  $m$  – the number of operations for a unit of product while manufacturing;  $S$  – salary expenses of the direct labours for a unit of product.

There are planned and actual prime costs.

Planned prime cost is calculated to evaluate possible expenses for manufacturing a machine, a separate component or for performing operations of the manufacturing processes. Planned cost is necessary to choose the most cost-effective variant of manufacturing process or its separate operation.

Actual prime cost reflects the expenses that took place in production processes and manufacturing processes.

Comparison of planned and actual prime costs helps to conclude about the conformance of the actual manufacturing process to the planned one and it helps to improve the present technology.

Thus, prime cost of a unit of production is the primary indicator of economic efficacy of production processes and manufacturing processes.

## Review Questions

1. Name types of products in mechanical engineering.
2. What is a life cycle of a product?
3. What parameters characterize quality of products?
4. What is manufacturability of a product design?
5. What parameters characterize accuracy of a part and of a machine?
6. How is continuous increase of machines accuracy explained?
7. What is the difference between manufacturing process and production process?
8. What does the process planning include?
9. What is an operation?
10. What is a processing step?
11. What are manufacturing means?
12. What is operation cycle per part?
13. What part of the operation cycle per part is called machining time?
14. What part of the operation cycle per part is called auxiliary time?
15. What is set-up time?
16. What is work sampling and workday timestudy?
17. Name the main methods of production and give their brief characteristics.
18. What is Takt time of products?
19. What is synchronization of operations?
20. What is the difference between flow and non-flow production?
21. What parameters are used to evaluate productivity?
22. What costs are included in the shop cost?

## 2. Dimensional Chains and Principles of Part Locating

The task of ensuring the required accuracy of products manufacturing, as already mentioned, is one of the most important in mechanical engineering. Fundamentals of part locating and dimensional chains are the basis for solution of this task.

### 2.1 Fundamentals of Part Locating

#### 2.1.1 General Concepts of Datums and Locating

A certain relative position of parts and assembly units should be provided for normal operation of any machine. During machining, workpieces must be located on the machine table or in a fixture with the required level accuracy. The same task arises during the measurements, when the workpiece or product and a measuring instrument (attachment, device) must also be set relative to each other with the required accuracy.

The process of workpiece or product mounting can be divided into locating and clamping. *Locating* is the process of giving the workpiece or product the desired position relative to the selected coordinate system. *Clamping* is the application of forces and couples of forces to the workpiece or the product to ensure steady position, reached by locating.


Surface or set of surfaces, an axis or a point that belongs to the workpiece or the product and is used for locating is called the *datum*.

Workpieces and products are considered as absolutely rigid bodies during the process of locating.

The locating rules are based on the known concept of theoretical mechanics that state the position of a free rigid body has six degrees of freedom in the selected coordinate system. It can be moved along the three axes and rotated about these axes. Therefore, to give the body the required position it is necessary to constrain these degrees of freedom. For doing this, one need to constrain (fix) six independent coordinates of the body. Moreover, each coordinate serves as a *bidirectional restraint* that constrains freedom of movement along this coordinate.

Let us first consider locating of a prismatic workpiece in a system of coordinates  $XYZ$  (Fig. 2.1, a). To locate the workpiece the following coordinates must be set:  $1-1'$ ,  $2-2'$ ,  $3-3'$ ,  $4-4'$ ,  $5-5'$  and  $6-6'$ . These coordinates constrain all six degrees of freedom:

- coordinates  $1-1'$ ,  $2-2'$  and  $3-3'$  – movement along the axis  $Z$  and rotation about the axes  $X$  and  $Y$ ;
- coordinates  $4-4'$  and  $5-5'$  – movement along the axis  $Y$  and rotation about the axis  $Z$ ;
- coordinate  $6-6'$  – movement along the axis  $X$ .



*Fig. 2.1. Locating of a prismatic workpiece:  
 a – in a coordinate system  $XYZ$ , b – by aligning workpiece locating datums with locating elements of the fixture*

The mounting of a workpiece in the fixture is carried out by aligning workpiece locating datums with locating elements of the fixture. As a result, workpiece coordinates are turned into six locating points that are on the workpiece datums (Figure 2.1, *b*).

Similarly, the relative position of the attached component to the other component (the basic component) is defined through a combination of their datums.

Thus, we get the *six-point locating principle*, which implies that to locate the workpiece relative to the fixture (or attached component relative to the other one) it is necessary and sufficient to have six locating points which constrain by one degree of freedom of the workpiece (the component being attached).

These locating points are usually located on three datums, which are called a *set of datums*.

To indicate the locating point there is a special symbol (Fig. 2.2). Arrangement of the locating points on the datums of a workpiece or a product is called locating scheme.




Fig. 2.2 Designation of the locating point:  
a – on the front and side view, b - on the top view

All locating points on the locating scheme are numbered by sequence numbers, starting from the datum that incorporates the greatest number of locating points. Moreover, the number of projections of the workpiece or the product should be sufficient for an unambiguous representation of the locating points position. When locating points are superimposed on a projection, only one point is drawn with denoted numbers of these points.

The scheme of locating a prismatic workpiece for the above example (see Fig. 2.1) is shown in Fig. 2.3.




Fig. 2.3 Scheme of a prismatic workpiece locating

Now consider locating of a shaft and a disc in the Cartesian coordinate system. In these cases, along with the other coordinates, the coordinates of points located on the axis of the cylindrical surface of the workpiece are most often specified (Fig. 2.4).




Fig. 2.4 Locating of a shaft (a) and disc (b) in a XYZ coordinate system

Coordinates  $1-1'$ ,  $2-2'$ ,  $3-3'$  and  $4-4'$  (Fig. 2.4, a) constrain movements of the shaft along axes  $Y$  and  $Z$  and axes and rotation about the same axes, the coordinate  $5-5'$  constrains movement along the axis  $X$  and coordinate  $6-6'$  constrain rotation about this axis.

Because of the small length of the cylindrical surface of the disc it is possible to specify coordinates of only two points located on its axis (Fig. 2.4, b), but at the end of the disc the coordinates of three points can be specified. Coordinates  $1-1'$ ,  $2-2'$ ,  $3-3'$  constrain movement of the disc along the  $X$  axis and rotation about the axes  $Y$  and  $Z$  and coordinates  $4-4'$  and  $5-5'$  constrain movement along the axes  $Y$  and  $Z$  respectively and coordinate  $6-6'$  constrains rotation about the axis  $X$ .

Thus, all six degrees of freedom are constrained for the shaft and the disc.

Locating schemes for the shaft and the disc are shown in Fig. 2.5, a and 2.5, c, and mounting of these parts in a self-centering chuck are shown in Fig. 2.5, b and 2.5, c.






Fig. 2.5. Locating schemes and the corresponding mounting of a shaft (a, b) and a disc (c, d)

It should be emphasized that the locating points 1, 2, 3 and 4 on the locating scheme of the shaft (Figure 2.5, a) and the locating points 4, 5 on the locating scheme of the disc (Fig. 2.5, c) are imaginary.

### 2.1.2 Classification of Datums

Datums are distinguished according to application, number of constrained degrees of freedom and the nature.

According to application, all datums are divided into functional datums, manufacturing datums and measurement datums.

*Functional datum* is the datum used to determine the position of the part or assembly unit in the product. Functional datums, in turn, are divided into primary and auxiliary functional datums. The *primary datum* is the datum that belongs to the given part or assembly unit and is used to determine their position in the product. The *auxiliary datum* is the datum that belongs to the given part or assembly unit and is used to determine the position of other components that are being attached to the given one. Fig. 2.6 shows an example of sets of primary and auxiliary datums of a part (housing). It should be noted that any part may have only one set of primary datums and as many sets of auxiliary datums, as many parts or assembling units is attached to it.




Fig. 2.6 Example of sets of primary and auxiliary datums of a housing  
(I, II, III – primary datums; IV, V, VI – auxiliary datums)

*Manufacturing datum* is the datum used to determine the position of the workpiece or the product during manufacturing or repairing. Some examples of sets of manufacturing datums have been discussed above.

*Measurement datum* is the datum used to determine the relative position of the workpiece or the product and measuring instruments. An example of measurement datum is given in Fig. 2.7.




Fig. 2.7 Representation of measurement datums of a part  
(A – measurement datum)


Depending on the number of the constrained degrees of freedom, the datums are divided into the plane, guide, point, double -guide and a double-point datums.

*Plane datum* constrains three degrees of freedom of the workpiece or the product – movement along one coordinate axis and rotation about the other two axes. In the examples given above, the plane datum is the bottom surface of the prismatic workpiece (Figure 2.3) and face of the disc (Fig. 2.5, b). The plane datum should have the maximum possible area so that the locating points can be located as far as possible from each other, ensuring the stability of the workpiece or the product.

*Guide datum* constrains two degrees of freedom of the workpiece or the product – movement along one coordinate axis and the rotation about the other axis. Guide datum on Fig. 2.3 is a plane of a prismatic workpiece, on which locating points 4 and 5 are positioned. The guide datum should be the most possible extended so that the locating points are spread to the greatest distance,

ensuring minimum deflection of the workpiece or the product in the corresponding coordinate plane.

*Point datum* constrains one degree of freedom of the workpiece or the product – movement along one coordinate axis or rotation about one coordinate axis. In the examples given above, the point datum is the plane of the prismatic workpiece (see Fig. 2.3), on which the locating point 6 is positioned, the disc face (see Fig. 2.5, a), on which the locating point 5 is placed, and the side walls of the keyways of the shaft and the disc (see Fig. 2.5, a and c), on which the locating points 6 are located. Surface of any dimensions may be used as a point datum.



*Fig. 2.8 Diagram of a double guide datum composed of cylindrical surfaces  
7 – shaft blanket; 8 – regulating wheel; 9 – supporting knife; 10 – grinding wheel;  
11 – workpiece stop*

*Double-guide datum* constrains four degrees of freedom of the workpiece or the product - movement along two axes and rotation about the same axis. This datum must be of the maximum possible length to provide the least deflection of the workpiece or the product. In Fig. 2.5, a the double-guide datum is the axis of the cylindrical surface of the shaft.

Commonly, the double-guide datum is formed as a combination of either two cylindrical or conical surfaces or as a combination of cylindrical and conical

cal surfaces. Here, each of said surfaces has a small length. The role of double-guide datum can be performed, in the first case, by the shaft necks<sup>1</sup> (Figure 2.8), which are used to mount the shaft on the supporting knife and the regulating wheel in centerless grinding; in the second case by the center holes, with the help of which the shaft is installed in the centers of the cylindrical grinders or lathes (Figure 2.9); in the third case by the cylindrical surface and the center hole of the shaft, with the help of which the shaft is set in the three-jaw self-centering chuck and tailstock center of the lathe respectively (Figure 2.10).




Fig. 2.9 Double-guide datum created by center holes in a workpiece




Fig. 2.10 Double-guide datum created by a cylindrical surface and a center hole

*Double-point datum* constrains two degrees of freedom of the workpiece or the product - movement along two axes. An example of a double-point datum is the axis of the cylindrical surface of the disc (see Fig. 2.5, c).

The following sets of datums are called typical: the first set includes plane, guide and point datums, the second set includes double-guide and two point datums, the third set includes plane, double-point and point datums.

By nature, all datums are divided into real and virtual.

*Real datum* is the datum of the workpiece or the product in the form of a real surface, scribed line or point of intersection of the scribed lines.

*Virtual datum* is the datum of the workpiece or the product in the form of an imaginary plane, axis or point.

In the examples mentioned above, the real and virtual datums are as follows:


- for the prismatic workpiece (Figure 2.3), all three datums (the plane, guide and point) are real;
- for the shaft (Fig. 2.5, a), the double-guide datum (the axis of the cylindrical surface) is the virtual one, the point datums are real ones;
- for the disc (Fig. 2.5, c), the plane and point datums are real, double-point datum (the axis of the cylindrical surface of the disc) is virtual;

<sup>1</sup>In this case, the surface that is machined is a manufacturing datum

- for the shaft (Fig. 2.8), the double-guide datum and a point datum (face) are real, another point datum is virtual;
- for the shaft (Fig. 2.9), the double-guide datum (common axis of the center holes) and two point datums (one of which is the vertex of the front center hole cone) are virtual;
- for the shaft (Fig. 2.10), the double-guide datum (common axis of the part of the cylindrical surface and the center hole) and one point datum are virtual, the other point datum (face) is real.

It should be noted that the locating point  $\phi$ , positioned on the virtual point datums (Fig. 2.8 - 2.10), designates the fact that the shaft, at each moment of time, takes specific angular position in the machine coordinate system, i.e. relative to the supporting knife and regulating wheel of the centerless grinding machine (Fig. 2.8), or relative to the centers of the cylindrical grinding machine (Figure 2.9), or relative to the three-jaw chuck of the lathe (Figure 2.10).

### According to application



*Fig. 2.11 Classification of datums*

Fig. 2.11 shows a diagram of the classification of datums. According to this diagram, the full name of the datum should include all three classification parameters. For example, the position of the shaft (Figure 2.8) is determined by the following datums: manufacturing double-guide real datum, manufacturing point real datum, manufacturing point real datum. Names of the datums can be simplified, denoting only those classification parameters that are of interest at the point of time: double-guide virtual datum, plane real datum, guide datum, etc.

## 2.2 Fundamentals of Dimensional Chain Theory

### 2.2.1 Basic Concepts and Definitions

*Dimensional chain* is a sequence of dimensions, directly involved in the task being solved, and forming a closed circuit.

For example, a set of dimensions  $A_1$ ,  $A_2$ , and  $A_\Delta$  (Figure 2.12, *a*) form a dimensional chain that determines size of a gap  $A_\Delta$ .

The dimensional chains are usually represented as separate diagrams (Figure 2.12, *b, d*).

Dimensions that form the dimensional chain are called *component dimensions*.

Component dimensions can be either linear (Fig. 2.12, *a*) or angular (Fig. 2.12, *c*).

Linear component dimensions are usually denoted by capital letters of the alphabet (A, B, ...) and angular component dimensions are denoted by lower case letters of the Greek alphabet ( $\beta$ ,  $\gamma$ , ...) with the exception of the letters  $\alpha$ ,  $\delta$ ,  $\zeta$ ,  $\lambda$ ,  $\omega$ . In some cases, other variables can be used.

In any dimensional chain there is one dimension that is called resulting, and the others dimensions are component dimensions.

*Resulting dimension* of a dimensional chain is initial in the task statement and is a result of the task solution.

For example, it is obvious that the values of the dimensions  $A_1$  and  $A_2$  must be determined depending on the desired clearance value  $A_\Delta$  (Figure 2.12, *a*). Therefore, a dimension  $A_\Delta$  in the chain is considered as a resulting. It is also obvious that this component dimension would be obtained last during the assembly of the mechanism. The same can be said about the component dimension  $\beta_\Delta$ , considering the dimensional chain that is shown in Fig. 2.12, *c*.




Fig. 2.12 Assembly dimensional chain

The resulting dimension is denoted by the index  $\Delta$ .

The component dimensions of a dimensional chain are divided into the increasing and decreasing dimensions.

*Increasing dimension* is the dimension which increase will result in an increase of the resulting dimension value.

*Decreasing dimension* is the dimension which increase will result in a decrease of the resulting dimension value.

In the dimensional chain shown in Fig. 2.12, *a*, the dimension  $A_1$  is increasing, and the dimension  $A_2$  is decreasing.

Increasing dimensions are indicated by an arrow above the letter directed to the right ( $\overrightarrow{A_1}$ ), and decreasing dimensions are indicated by an arrow pointing to the left ( $\overleftarrow{A_2}$ ).

The task of identifying increasing and decreasing dimension of short dimensional chains is quite simple. With the increasing number of component dimensions in the dimensional chain, this task becomes more complicated, and to facilitate its solution it is appropriate to use the following method. The resulting dimension is conditionally assigned the index of a decreasing dimension, i.e. the arrow over its letter is directed to the left (Fig. 2.13). Then, the dimensional contour is looked through in this direction, and the arrows are placed on the tops of the component dimensions. If the arrow is pointed to the right then the dimension is increasing, and if the arrow is pointed to the left then the dimension is decreasing.




Fig. 2.13 Diagram of a dimensional chain. The line with the arrows shows a tracking sequence to identify increasing and decreasing dimensions

Depending on the application all dimensional chains are divided into functional, manufacturing and measurement dimensional chains. The first one is used during the stage of engineering design of a product, the second ones are used on the stage of the product manufacturing, and the third ones are used during measurement of the parts.

Functional dimensional chains are divided into assembly dimensional chains and component dimensional chains. Examples of assembly dimensional chains are shown in Fig. 2.12. An example of component dimensional chain is shown in Fig. 2.14. Here  $A_1$  and  $A_2$  are component dimensions (values of these dimensions are indicated on the drawing of a part),  $A_\Delta$  is the resulting dimension (its value is not indicated on the drawing of a part).




Fig. 2.14 Component dimensional chain

Manufacturing dimensional chains are solved for the processes of assembling machines and manufacturing processes (production of parts).

Manufacturing dimensional chains are divided into two types. In the manufacturing dimensional chains of the first type, the component dimensions



$A_i$  are the dimensions of the machine tool, fixture and cutting tool, and resulting dimension is the size of the machined workpiece (Fig. 2.15, *a*). In the manufacturing dimensional chains of the second type, the component dimensions are the manufacturing dimensions of the workpiece that are obtained from the different operations. The resulting dimensions in these chains are the functional dimensions (taken from the drawing) and dimensions of machining allowances. Fig. 2.15, *b* shows a schematic diagram of grinding of the face of the workpiece performed on the surface grinder and manufacturing dimensional chains of the second type. The functional dimension  $K$  (size of the chamfer) is the resulting dimension in the dimensional chain with the component dimensions  $A_1$ ,  $A_2$  and  $A_3$ , and the allowance  $Z$  is the resulting dimension in the dimensional chain with component dimensions  $A_1$  and  $A_3$ . (The manufacturing dimensions  $A_1$  and  $A_3$  are obtained from the preceding turning operation, the manufacturing dimension  $A_3$  is obtained by face grinding.)




Fig. 2.15 Manufacturing dimensional chains that are obtained during machining:  
*a* - the first type, *b* - the second type

The component dimensions of dimensional chains can be arranged in one or more parallel or non-parallel planes. In the first case, the dimensional chain is called *planar dimensional chain*, in the second case – *spatial dimensional chain*. The component dimensions in planar chains can either be parallel or not parallel to each other. Fig. 2.16 shows planar dimensional chain, in which the component dimension  $A_3$  is at an angle  $\alpha$  relative to the direction of the resulting dimension. Such a dimension is included in the dimensional chain as its projection ( $A'_3$ ) on this direction. Moreover, the angle  $\alpha$  is considered as constant and  $A'_3 = A_3 \cos \alpha$ . Assume that the dimension  $A_3 = 100^{+0.6}_{-0.2}$  and the angle  $\alpha = 30^\circ$ . The nominal value of this dimension is:

$$A'_3 = A_3 \cos \alpha = A_3 \cos 30^\circ = 100 \cdot 0.866 = 86.6 \text{ (mm)}.$$

The limit deviations of the dimension  $A'_3$  are:

$$\Delta_u A'_3 = \Delta_u A_3 \cos \alpha = \Delta_u A_3 \cos 30^\circ = 0.6 \cdot 0.866 = 0.52 \text{ (mm)};$$

$$\Delta_l A'_3 = \Delta_l A_3 \cos \alpha = \Delta_l A_3 \cos 30^\circ = -0.2 \cdot 0.866 = -0.17 \text{ (mm)}.$$

Consequently,  $A'_3 = 86.6^{+0.52}_{-0.17}$  mm.




Fig. 2.16 Planar dimensional chain with non-parallel dimensions

Thus, any planar dimensional chain with non-parallel dimensions can be reduced to a planar dimensional chain with parallel dimensions.




Fig. 2.17 Three types of relationships between dimensional chains:  
a – parallel; b – sequential; c – parallel-sequential

Individual dimensional chains can be interconnected. By *parallel-linked chains* are mentioned the dimensional chains that have one or more common component dimensions. *Sequentially linked chains* are the dimensional chains, in which each the next dimension has a common datum with the previous dimension. *Parallel-sequentially linked chains* have both parallel and sequential connections. Examples of dimensional chains with different types of connections are shown in Fig. 2.17. It can be seen (Fig. 2.17, *a*) that dimensional chains A ( $A_1, A_2, A_3, A_\Delta$ ) and B ( $B_1, B_2, B_3, B_\Delta$ ), have two common component dimensions -  $A_3=B_2$  and  $A_2=B_3$ . Dimensional chains A and C (Figure 2.17, *b*) have a common datum. Dimensional chains A, B and C, shown in Fig. 2.17, *b*, have both parallel and sequential connections.

### 2.2.2 Basic Equations

Let us find the relationship between the basic parameters of the resulting dimension and component dimensions of the planar dimensional chain with parallel dimensions. For doing this, first examine Fig. 2.12, *a*.

It is clear that the nominal value of the resulting dimension  $A_\Delta$  will be:

$$A_\Delta = \overrightarrow{A_1} - \overleftarrow{A_2}.$$

In general, for a dimensional chain with  $n$  number of increasing dimensions and  $p$  number of decreasing dimensions the following can be written:

$$A_\Delta = \sum_{i=1}^n \overrightarrow{A_i} - \sum_{i=1}^p \overleftarrow{A_i}. \quad (2.1)$$

This equation is known as the dimensional chain equation or an equation of nominal sizes.

By using the concept of transmission ratio  $\xi_i$ , which is equal to +1 for increasing dimensions and -1 for decreasing dimensions, the dimensional chain equation can be written in a more compact form:

$$A_\Delta = \sum_{i=1}^{n+p} \xi_i A_i. \quad (2.2)$$

It is obvious (refer to Fig. 2.12, *a*) that the maximum and minimum limits of size of the resulting dimension  $A_\Delta$  would be expressed by the use of the limits of size of the component dimensions  $\overrightarrow{A_1}$  and  $\overleftarrow{A_2}$  as follows:

$$\begin{aligned} A_{\Delta \max} &= \overrightarrow{A_{1 \max}} - \overleftarrow{A_{2 \min}}; \\ A_{\Delta \min} &= \overrightarrow{A_{1 \min}} - \overleftarrow{A_{2 \max}}. \end{aligned}$$

In the general case:

$$A_{\Delta \max} = \sum_{i=1}^n \overrightarrow{A_{i \max}} - \sum_{i=1}^p \overleftarrow{A_{i \min}}, \quad (2.3)$$

$$A_{\Delta \min} = \sum_{i=1}^n \overrightarrow{A}_{i \min} - \sum_{i=1}^p \overleftarrow{A}_{i \max} . \quad (2.4)$$

To establish relationship between tolerance of the resulting dimension and tolerances of the component dimensions of a dimensional chain, let's subtract term by term equation (2.4) from equation (2.3). In this case, we can found:

$$TA_{\Delta} = \sum_{i=1}^n T\overrightarrow{A}_i + \sum_{i=1}^p T\overleftarrow{A}_i$$

or finally

$$TA_{\Delta} = \sum_{i=1}^{n+p} TA_i , \quad (2.5)$$

*i.e., tolerance of the resulting dimension is equal to the sum of tolerances of the component dimensions.*

Let us find the relationship between limit deviations of the resulting dimension and limit deviations of the component dimensions of a dimensional chain. It follows from the scheme, shown in Fig. 2.18 that the maximum and minimum limits of size of the component dimensions and resulting dimension can be written as:

$$A_{i \max} = A_i + \Delta_u A_i ; \quad (2.6)$$

$$A_{i \min} = A_i + \Delta_l A_i ; \quad (2.7)$$

$$A_{\Delta \max} = A_{\Delta} + \Delta_u A_{\Delta} ; \quad (2.8)$$

$$A_{\Delta \min} = A_{\Delta} + \Delta_l A_{\Delta} ; \quad (2.9)$$

In the equations (2.6-2.9),  $\Delta_u A_i$ ,  $\Delta_u A_{\Delta}$  - are the upper deviations of the component dimensions and the resulting dimension respectively;  $\Delta_l A_i$ ,  $\Delta_l A_{\Delta}$  - are the lower deviations for these dimensions. Inserting these expressions into Equations (2.3) and (2.4), the following can be found:

$$A_{\Delta} + \Delta_u A_{\Delta} = \sum_{i=1}^n (\overrightarrow{A}_i + \Delta_u \overrightarrow{A}_i) - \sum_{i=1}^p (\overleftarrow{A}_i + \Delta_l \overleftarrow{A}_i) ;$$

$$A_{\Delta} + \Delta_l A_{\Delta} = \sum_{i=1}^n (\overrightarrow{A}_i + \Delta_l \overrightarrow{A}_i) - \sum_{i=1}^p (\overleftarrow{A}_i + \Delta_u \overleftarrow{A}_i) .$$




Fig. 2.18 Diagram of dimensions, tolerance and deviations

Subtracting Equation (2.1) from these equations term by term, we can formulate the following:

$$\Delta_u A_\Delta = \sum_{i=1}^n \Delta_u \bar{A}_i - \sum_{i=1}^p \Delta_l \bar{A}_i ; \quad (2.10)$$

$$\Delta_l A_\Delta = \sum_{i=1}^n \Delta_l \bar{A}_i - \sum_{i=1}^p \Delta_u \bar{A}_i . \quad (2.11)$$

Thus, the upper deviation of the resulting dimension is equal to the difference between sums of upper deviations of increasing dimensions and lower deviations of decreasing dimensions, and the lower deviation of the resulting dimension is equal to the difference between sums of the lower deviations of increasing dimensions and upper deviations of decreasing dimensions.

Let's establish relationship between the coordinate of the center-line of the resulting dimension ( $\Delta_0 A_\Delta$ ) tolerance zone and the coordinates of the center-lines of the tolerance zones of the component dimensions ( $\Delta_0 A_i$ ). To define the relationship, according to the diagram shown in Fig. 2.18, it is needed to express limit deviations of the resulting dimension and component dimensions by means of the tolerance and coordinate of the center-line of the tolerance zone:

$$\Delta_u A_\Delta = \Delta_0 A_\Delta + \frac{TA_\Delta}{2} ; \quad (2.12)$$

$$\Delta_l A_\Delta = \Delta_0 A_\Delta - \frac{TA_\Delta}{2} . \quad (2.13)$$

$$\Delta_u A_i = \Delta_0 A_i + \frac{TA_i}{2} ; \quad (2.14)$$

$$\Delta_l A_i = \Delta_0 A_i - \frac{TA_i}{2} . \quad (2.15)$$

By inserting these expressions into Equations (2.10) and (2.11), the following equations can be obtained:

$$\begin{aligned}\Delta_0 A_\Delta + \frac{T A_\Delta}{2} &= \sum_{i=1}^n \left( \Delta_0 \bar{A}_i + \frac{T \bar{A}_i}{2} \right) - \sum_{i=1}^p \left( \Delta_0 \bar{A}_i - \frac{T \bar{A}_i}{2} \right) \\ \Delta_0 A_\Delta - \frac{T A_\Delta}{2} &= \sum_{i=1}^n \left( \Delta_0 \bar{A}_i - \frac{T \bar{A}_i}{2} \right) - \sum_{i=1}^p \left( \Delta_0 \bar{A}_i + \frac{T \bar{A}_i}{2} \right)\end{aligned}$$

By adding these equations, term by term, and dividing the left and right sides of the resultant equation by 2, the following relationship is obtained:

$$\Delta_0 A_\Delta = \sum_{i=1}^n \Delta_0 \bar{A}_i - \sum_{i=1}^p \Delta_0 \bar{A}_i, \quad (2.16)$$

that is, *the coordinate of center-line of tolerance zone of the resulting dimension is equal to the difference between sums of coordinates of center-lines of tolerance zones of the increasing component dimensions and decreasing component dimensions.*

With transmission ratios, Equation (2.16) takes the following form:

$$\Delta_0 A_\Delta = \sum_{i=1}^{n+p} \xi_i \Delta_0 A_i. \quad (2.17)$$

Let's express average value of the resulting dimension ( $A_{\Delta av}$ ) by means of average values of the component dimensions ( $A_{iav}$ ). For this purpose, it is needed to add term by term Equation (2.16) and Equation (2.1). The result is as follows:

$$\Delta_0 A_\Delta + A_\Delta = \sum_{i=1}^n (\Delta_0 \bar{A}_i + \bar{A}_i) - \sum_{i=1}^p (\Delta_0 \bar{A}_i + \bar{A}_i).$$

Taking into account that (refer to Fig. 2.18):

$$\begin{aligned}\Delta_0 A_\Delta + A_\Delta &= A_{\Delta av}; \\ \Delta_0 A_i + A_i &= A_{iav},\end{aligned}$$

the resulting equation would be:

$$A_{\Delta av} = \sum_{i=1}^n \bar{A}_{iav} - \sum_{i=1}^p \bar{A}_{iav} \quad (2.18)$$

that is, *the average value of the resulting dimension is equal to the difference between sums of the average values of the increasing and decreasing dimensions.*

With transmission ratios, Equation (2.18) can be written as:

$$A_{\Delta av} = \sum_{i=1}^{n+p} \xi_i A_{iav}. \quad (2.19)$$

Relationships (2.3)-(2.5) and (2.10)-(2.11) were obtained under the assumption that the combination of maximum increasing dimensions and mini-

imum decreasing dimensions and vice versa are possible in a dimensional chain. The method of calculating dimensions of dimensional chains, based on the use of these relationships, is called the *maximum-minimum method*. It provides a complete interchangeability, eliminating reject.

Meanwhile, the probability of such a combination of the component dimensions in a particular product is quite small. This circumstance, as well as the laws of the size distribution of these dimensions, is taken into account in the *statistical method* of dimensional chains calculations, which differs from the maximum-minimum method in the way of calculation of resulting dimension tolerance.

Assuming that the size distribution of the component dimensions correspond to the normal law, and the borders of the range of dispersion  $\omega_i = 6\sigma_{A_i}$  coincide with the limits of their tolerance zones, the following equation can be written:

$$TA_i = 6\sigma_{A_i}$$

or

$$\sigma_{A_i} = \frac{1}{6}TA_i. \quad (2.20)$$

Since the average value of the resulting dimension is the algebraic sum of the average values of the component dimensions, in accordance with the well-known theorem in probability theory about the variance of the sum of independent random variables (component dimensions), we have:

$$\sigma_{A_\Delta}^2 = \sum_{i=1}^{n+p} \sigma_{A_i}^2$$

Using relationship (2.20), we can write:

$$(TA_\Delta)^2 = \sum_{i=1}^{n+p} (TA_i)^2$$

or

$$TA_\Delta = \sqrt{\sum_{i=1}^{n+p} (TA_i)^2}. \quad (2.21)$$

Note that for Equation (2.21) 0.27% of the products will probably have value of the resulting dimension beyond the tolerance.

In the general case, including cases when size distribution of component dimensions units differs from the normal, tolerance of the resulting dimension of a planar dimensional chain with parallel dimensions is defined by the formula:

$$TA_\Delta = t_\Delta \sqrt{\sum_{i=1}^{n+p} \lambda_i^2 (TA_i)^2}, \quad (2.22)$$

where  $t_{\Delta}$  is the risk ratio;  $\lambda_i$  is the relative standard deviation (dimensionless ratio).

This deviation is found from the relation:

$$\lambda_i = \frac{2\sigma_{A_i}}{\omega_i}$$

or

$$\lambda_i = \frac{2\sigma_{A_i}}{TA_i}$$

Risk ratio  $t_{\Delta}$  determines the probability that the size of the resulting dimension is within the limits of its tolerance zone. This factor is selected from the tables of Error function  $\Phi(t)$  values, depending on the given risk  $P$ .

For the normal distribution of the resulting dimension sizes and equal probability of its overrunning both limits of the tolerance zone the percentage value  $P$ , is related to the value of  $\Phi(t)$  with the following equation:

$$P = 100[1 - 2\Phi(t)]. \quad (2.23)$$

Series of the  $t_{\Delta}$  values is given in Table 2.1.

Table 2.1

1. Risk $P$ , %	32	23	16	9	4.6	2.1	0.94	0.51	0.27	0.1
2. Ratio $t_{\Delta}$	1	1.2	1.4	1.7	2	2.3	2.6	2.8	3	3.3

Coefficient  $\lambda_i^2$  values are as follows:

- for the normal law (Gaussian) of distribution of sizes of component dimensions  $\lambda_i^2 = 1/9$ ;
- for the Simpson distribution (triangular distribution)  $\lambda_i^2 = 1/6$ ;
- for the law of equal probability  $\lambda_i^2 = 1/3$ .

Normal size distribution often take place in large-batch and mass production of products, the Simpson distribution occurs in batch production, the distribution according to the law of equal probability occurs in single-job production.

Assuming that the distribution of component dimensions is normal, and the risk  $P=0.27\%$ , then the  $\lambda_i^2 = 1/9$ , coefficient  $t_{\Delta} = 3$  (see Table 2.1) and Equation (2.22) is converted into Equation (2.21).



The tasks of the tolerance analysis can be of two types: direct task (product design stage) and inverse task (product control stage).

The *direct task* consists in calculation of tolerances and limits of size for component dimensions, with the given basic sizes of the component dimensions and the limit deviations and tolerance of the resulting dimension.

The *inverse task* consists in calculation of basic size and limit deviations for the resulting dimension, with the given basic sizes and limit deviations of the component dimensions.

### 2.2.3 Methods of Ensuring Accuracy of Resulting Dimensions

The task of ensuring required accuracy of resulting dimensions can be economically solved by one of the following five methods: complete interchangeability, incomplete interchangeability, group interchangeability, fitting or adjustment.

Let's consider solution of the task by different methods for the dimensional chain shown in Fig. 2.19.




Fig. 2.19 Dimensional chain of a mechanical unit

#### 2.2.3.1 Complete Interchangeability Method

With the method of complete interchangeability, the required accuracy of the resulting dimension of a dimensional chain is achieved in all cases of its

implementation by incorporating component dimensions without selection, sorting or changing their values.

The widespread use of the complete interchangeability method is due to the following advantages:

- easy to achieve the required accuracy of the resulting dimension (for example, the application of this method in assembly brings the latter simply into the process of connecting the parts);
- possibility of broad co-operation between workshops and factories in the manufacture of individual parts and assembly units;
- possibility to perform assembly operations by semi-skilled workers;
- ease of engineering planning of the assembly processes.

Tolerance and limit deviations of component dimensions of a dimensional chain are calculated using the maximum-minimum method.

The calculation is as follows.

1. The tolerance of the resulting dimension is allocated between tolerances of the component dimensions. This task is a multiple-choice, since it has only one equation (2.5).

For approximate estimation of tolerances of the component dimensions the method of equal tolerances (equal effects) is the most commonly used. In accordance with the method, the tolerance of each component dimension is taken one and the same. This tolerance [average tolerance  $(TA_i)_{av}$ ] is found by dividing the tolerance of the resulting dimension by the number of component dimensions, i.e.

$$(TA_i)_{av} = \frac{TA_{\Delta}}{n + p}.$$

Afterwards, the found by this method tolerances of the component dimensions are corrected depending on the complexity of achieving the required accuracy of each component dimension. As a result, it is attempted to reduce the manufacturing costs of the product.

For the given example (Figure 2.19)

$$(TA_i)_{av} = \frac{0.2}{3} \cong 0.067 \text{ (mm)}.$$

The most difficult task is to ensure accuracy of the dimension  $A_2$  - the distance between the inner walls of the housing, thus the tolerance of this dimension should be taken a much larger than the tolerances of the dimension  $A_1$  and  $A_3$ . Keeping this in mind, let's set as follows:  $TA_1=0.03$  mm;  $TA_2=0.15$  mm;  $TA_3=0.02$  mm.

2. All component dimensions, except one, are assigned limit deviations. Usually for holes (inner elements) the deviations are assigned as  $H$ , and

for shaft (outer elements) - as  $h$ , for the rest of the dimensions – deviations are bilateral.

Accepted tolerances are as follows:  $A_1 = 45_{-0.03}$  mm;  $A_2 = 50^{+0.15}$  mm.

3. To determine limit deviations of the "remaining" dimension, first with the help of Equation (2.16) the coordinate of the centerline of the tolerance zone of this dimension is found. Then, using Equations (2.14) and (2.15) the deviation are calculated.

For this example, the "remaining" dimension is  $A_3$ . The coordinate of the centerline of this dimension tolerance is found as

$$\begin{aligned}\Delta_0 A_\Delta &= \Delta_0 \bar{A}_2 - \Delta_0 \bar{A}_1 - \Delta_0 \bar{A}_3; \\ 0.1 &= 0.075 - (-0.015) - \Delta_0 A_3.\end{aligned}$$

Hence

$$\Delta_0 A_3 = -0.01 \text{ (mm)}.$$

The limit deviations of the dimension  $A_3$  will be:

$$\begin{aligned}\Delta_u A_3 &= \Delta_0 A_3 + \frac{TA_3}{2} = -0.01 + \frac{0.02}{2} = 0 \text{ (mm)}; \\ \Delta_l A_3 &= \Delta_0 A_3 - \frac{TA_3}{2} = -0.01 - \frac{0.02}{2} = -0.02 \text{ (mm)}.\end{aligned}$$

Thus, we obtain  $A_3 = 5_{-0.02}$  (mm).

The correctness of the direct task solution is checked by solving inverse task.

1. With the help of Equation (2.1), we find the basic size of the resulting dimension

$$A_\Delta = \bar{A}_2 - \bar{A}_1 - \bar{A}_3 = 50 - 45 - 5 = 0 \text{ (mm)}.$$

2. With the help of Equations (2.10) and (2.11), we define its limit deviations

$$\begin{aligned}\Delta_u A_\Delta &= \Delta_u A_2 - \Delta_l A_1 - \Delta_l A_3 = 0.15 - (-0.03) - (-0.02) = 0.2 \text{ (mm)}; \\ \Delta_l A_\Delta &= \Delta_l A_2 - \Delta_u A_1 - \Delta_u A_3 = 0 - 0 - 0 = 0 \text{ (mm)}.\end{aligned}$$

Thus, we obtain  $A_\Delta = 0^{+0.2}$  mm, i.e., the direct task is solved correctly.

The method of complete interchangeability, which takes into account the possibility of the most unfavorable combination of limit deviations of the component dimensions, often results in a very tight (uneconomic) tolerances of these dimensions. It is assumed that the economically feasible area of application of the complete interchangeability method are the dimensional chains with a small number of dimensions (usually  $n + p \leq 4$ ) and a relatively wide tolerance of the resulting dimension.

### 2.2.3.2 Incomplete Interchangeability Method

The method consists in the fact that the required level of dimensional accuracy of the resulting dimension is achieved with a certain pre-determined risk by incorporating the component dimensions without selection, sorting or changing their values. The intentional risk of the resulting dimension exceeding the tolerance zone limits is usually small. However, this risk makes it possible (as will be shown below) to significantly expand the tolerances of the component dimensions compared with the tolerances allocated by the method of complete interchangeability, and thus, greatly reduce the cost of manufacturing of parts and products in general.

In the method of incomplete interchangeability the tolerances of the component dimensions are calculated using Equation (2.22), derived on the basis of the probability theory.

Solution of the direct task by the described method is carried out in the following way.

1. Value of the risk ratio  $t_{\Delta}$  and relative standard deviation  $\lambda_i$  are set. For this example (Fig. 2.19), let's assume that the risk  $P=1\%$ , for which  $t_{\Delta} = 2.57$  (see Table 2.1). Assuming that the distribution of the component dimensions values corresponds to the Gaussian law, we take  $\lambda_i^2 = 1/9$ .

For approximate estimation of the component dimensions tolerances the average tolerance  $(TA_i)_{av}$  is determined by the equation

$$(TA_i)_{av} = \frac{TA_{\Delta}}{t_{\Delta} \sqrt{\lambda_i^2 (n+p)}},$$

that follows from Equation (2.22). For this example we obtain

$$(TA_i)_{av} = \frac{0.2}{2.57 \sqrt{\frac{1}{9} \cdot 3}} = 0.135 \text{ (mm)}.$$

2. Using Equation (2.22), the following preliminary tolerances for component dimensions are set:  $TA_1=0.1$  mm,  $TA_2=0.2$  mm;  $TA_3=0.06$  mm.

Correctness of the tolerances selection is checked using Equation (2.22):

$$TA_{\Delta} = t_{\Delta} \sqrt{\sum_{i=1}^{n+p} \lambda_i^2 (TA_i)^2} = 2.57 \sqrt{1/9 [(0.1)^2 + (0.2)^2 + (0.06)^2]} = 0.2 \text{ (mm)}.$$

Further, solution of the direct task coincides with solution by the maximum-minimum method.

3. All component dimensions, except one, are assigned limit deviations. Accepted tolerances are as follows:

$$A_1 = 45_{-0.1} \text{ mm}; A_2 = 50^{+0.2} \text{ mm}.$$

4. Then coordinate of centerline of the A3 dimension tolerance zone is found

$$\begin{aligned}\Delta_0 A_\Delta &= \Delta_0 \bar{A}_2 - \Delta_0 \bar{A}_1 - \Delta_0 \bar{A}_3; \\ 0.1 &= 0.1 - (-0.05) - \Delta_0 A_3.\end{aligned}$$

Hence

$$\Delta_0 A_3 = -0.01 \text{ (mm)}.$$

The limit deviations of the dimension A3 will be:

$$\begin{aligned}\Delta_u A_3 &= \Delta_0 A_3 + \frac{TA_3}{2} = 0.05 + \frac{0.06}{2} = 0.08 \text{ (mm);} \\ \Delta_l A_3 &= \Delta_0 A_3 - \frac{TA_3}{2} = 0.05 - \frac{0.06}{2} = 0.02 \text{ (mm)}.\end{aligned}$$

Thus, we obtain  $A_3 = 5^{+0.08}_{+0.02}$  (mm).

The correctness of the direct task solution is checked by solving inverse task.

1. With the help of Equation (2.1), we find the basic size of the resulting dimension

$$A_\Delta = \bar{A}_2 - \bar{A}_1 - \bar{A}_3 = 50 - 45 - 5 = 0 \text{ (mm)}.$$

2. Then coordinate of centerline of the resulting dimension tolerance zone is found

$$\Delta_0 A_\Delta = \Delta_0 \bar{A}_2 - \Delta_0 \bar{A}_1 - \Delta_0 \bar{A}_3 = 0.1 - (-0.05) - (-0.05) = 0.1 \text{ (mm)}.$$

3. Then the limit deviations of the resulting dimension are found

$$\begin{aligned}\Delta_u A_\Delta &= \Delta_0 A_\Delta + \frac{TA_\Delta}{2} = 0.1 + \frac{0.2}{2} = 0.2 \text{ (mm);} \\ \Delta_l A_\Delta &= \Delta_0 A_\Delta - \frac{TA_\Delta}{2} = 0.1 - \frac{0.2}{2} = 0 \text{ (mm)}.\end{aligned}$$

Thus, we obtain  $A_\Delta = 0^{+0.2}$  mm, i.e., the direct task is solved correctly.

Table 2.2

Method	Component dimensions		
	A <sub>1</sub>	A <sub>2</sub>	A <sub>3</sub>
Complete interchangeability	45 <sub>-0.03</sub>	50 <sup>+0.15</sup>	5 <sub>-0.02</sub>
Incomplete interchangeability	45 <sub>-0.1</sub>	50 <sup>+0.2</sup>	5 <sup>+0.08</sup> <sub>+0.02</sub>

Table 2.2 compares the results of calculations of the tolerances and limit deviations of the component dimensions of the given dimensional chain (Figure 2.19), performed by complete and incomplete interchangeability. It can be

seen that the method of incomplete interchangeability compared with the method of complete interchangeability allows, for even short dimensional chains, the tolerances of the component dimensions to be significantly increased. The economic effect of application of the incomplete interchangeability method instead of the method of complete interchangeability increases with the decreasing tolerance of the resulting dimension and the increasing number of dimensions in the dimensional chain.

### 2.2.3.3 Method of Group Interchangeability

In the method of group interchangeability, the required accuracy of the resulting dimension is achieved by incorporating into dimensional chain the component dimensions that belong to the corresponding groups, to which these component dimensions are sorted beforehand.

The method of group interchangeability (sometimes referred to as the selective assembly) is usually used in case of tight tolerance of a resulting dimension, which is difficult or even impossible to ensure by the method of incomplete interchangeability. With the use of the group interchangeability method the specified tolerance of the resulting dimension  $TA_{\Delta}$  is increased in  $N$  times ( $N$  is an integer). The increased tolerance  $T'A_{\Delta} = TA_{\Delta} \cdot N$ , which is often called the manufacturing tolerance, is used to calculate the tolerances of the component dimensions. The parts manufactured with such relatively wide tolerances are sorted by size in  $N$  groups and each is assigned a number. Then products are assembled of the parts that belong to the same group, which provides the required tolerance value of the resulting dimension  $TA_{\Delta}$ .

Thus, when assembling products of the parts belonging to the same group, the resulting dimension tolerance  $TA_{\Delta}$  is ensured by the method of complete interchangeability.

In assessing the economic efficiency of this method it is necessary to take into account the additional costs associated with the precise measurement of the parts and sorting them into groups, their labeling and storage. Logistical difficulties and costs increase with the increasing number of dimensions in the dimensional chain and number of groups of parts. This explains the fact that the method is used for the dimensional chains with the number of dimensions less than four, and the number of part groups are striving to make as small as possible.

To apply the method of group interchangeability it is necessary to satisfy the following conditions.

1. Deviation of form and location of the parts shall not exceed the tolerance of their size in the group. Obviously, if this condition is not met, the application of the method of group interchangeability is impossible.

2. When allocating the increased tolerance of the resulting dimension  $T'A_{\Delta}$  between the component dimensions it is necessary that the sum of the increasing dimensions tolerances is equal to the sum of the decreasing dimensions tolerances, i.e.

$$\sum_{i=1}^n T'\bar{A}_i = \sum_{i=1}^p T'\bar{A}_i .$$

If this equality is not satisfied, the average value of the resulting dimension of the product assembled from parts of the different corresponding groups will be different.

Let us show this by the example of the three-dimension dimensional chain, to which any multi-dimension chain can be reduced.

Fig. 2.20 shows dimensional chain A, which defines the gap between the shaft and the bore in the bushing. The equation of this dimensional chain

$$A_{\Delta} = \bar{A}_1 - \bar{A}_2 .$$

The resulting dimension tolerance  $TA_{\Delta}$  is increased  $N$  times.




Fig. 2.20 Ensuring accuracy of the resulting dimension by the method of group interchangeability

In accordance with the enlarged tolerance of the resulting dimension, the manufacturing tolerances  $T'A_1$  and  $T'A_2$  are established, and  $T'A_1 = T'A_2$ .

Each of the tolerance zones  $T'A_1$  and  $T'A_2$  is divided into  $N$  intervals, i.e.  $N$  group of parts is formed.

Thus

$$\begin{aligned}T^I A_1 &= T^{II} A_1 = \dots = T^N A_1; \\T^I A_2 &= T^{II} A_2 = \dots = T^N A_2; \\T^I A_1 + T^I A_2 &= T^{II} A_1 + T^{II} A_2 = \dots = T^N A_1 + T^N A_2 = TA_{\Delta}.\end{aligned}$$

Thus, the coupling of parts taken from the corresponding groups ensures tolerance  $TA_{\Delta}$  exactly in the same way as in the method of complete interchangeability.

Coordinates of the centerlines of the resulting dimension tolerance:

for the first intervals of  $T^I A_1$  and  $T^I A_2$

$$\Delta_0^I A_{\Delta} = \Delta_0^I A_1 - \Delta_0^I A_2;$$

for the second intervals of  $T^{II} A_1$  and  $T^{II} A_2$

$$\Delta_0^{II} A_{\Delta} = (\Delta_0^I A_1 + T^I A_1) - (\Delta_0^I A_2 + T^I A_2).$$

Since  $T^I A_1 = T^I A_2$ , then

$$\Delta_0^{II} A_{\Delta} = \Delta_0^I A_1 - \Delta_0^I A_2.$$

Thus, with  $T^I A_1 = T^I A_2$  the coordinates of centerlines of tolerances of the resulting dimension and its average sizes in different groups of parts will be identical.

That will not happen, if  $T^I A_1 \neq T^I A_2$  and the equation  $T^I A_1 + T^I A_2 = T^I A_{\Delta}$  is satisfied.

Thus, for the second intervals,  $T^{II} A_1$  and  $T^{II} A_2$

$$\Delta_0^{II} A_{\Delta} = (\Delta_0^I A_1 + T^I A_1) - (\Delta_0^I A_2 + T^I A_2).$$

However, since  $T^I A_1 \neq T^I A_2$ , then

$$\Delta_0^{II} A_{\Delta} \neq \Delta_0^I A_{\Delta}$$

i.e. the coordinates of the centerlines of tolerances of the resulting dimension and its average sizes in different groups of parts will not be identical.

3. An important requirement, which largely determines the efficiency of the method of group interchangeability, is the requirement for identity of size distributions within the tolerance zones. Only under this condition the assembly of the products will be ensured (Fig. 2.21, *a*), there will be no excess of parts of one kind and the lack of parts of the other kind in the group, i.e. the situation shown in Fig. 2.21, *b*. It is difficult to completely avoid it. Therefore, when using the group interchangeability method, there almost always is work-in-process.

The method of group interchangeability should be used in large-batch and mass production of the couplings of high accuracy. In manufacture of roller



bearings and assembly of threaded joints with interference fit, this method is the only economical way to ensure accuracy.




Fig. 2.21 The influence of the nature of distributions of sizes on the assemblability of products (arrows connect the corresponding groups of parts)

Let's consider application of the method of group interchangeability to ensure accuracy of the resulting dimension in the example shown in Fig. 2.19.

Recall that the resulting dimension in this example is  $A_{\Delta} = 0^{+0.2}$ . The basic sizes of the component dimensions are:  $A_1=45$  mm;  $A_2=50$  mm;  $A_3=5$  mm. Equation of the dimensional chain is

$$A_{\Delta} = \bar{A}_2 - \bar{A}_1 - \bar{A}_3.$$

Let us assume that it is economically feasible to enlarge the resulting dimension tolerance  $A_{\Delta}$  in three times, i.e. the number of groups of parts  $N=3$ . The increased tolerance of the resulting dimension is

$$T'A_{\Delta} = TA_{\Delta} \cdot N = 0.2 \cdot 3 = 0.6 \text{ (mm)}.$$

The sum of the increased tolerances of the increasing dimensions must be equal to the sum of the increased tolerances of the decreasing dimensions, i.e.

$$T'A_2 = T'A_1 + T'A_3 = \frac{1}{2} T'A_{\Delta}.$$

Hence

$$T'A_2 = \frac{1}{2} T'A_{\Delta} = \frac{0.6}{2} = 0.3 \text{ (mm)};$$

$$T'A_1 + T'A_3 = \frac{1}{2} T'A_{\Delta} = 0.3 \text{ (mm)}.$$

Considering the complexity of manufacturing, accept

$$T'A_1 = 0.24 \text{ mm and } T'A_3 = 0.06 \text{ mm}.$$

Accordingly, the group tolerances are:

$$TA_1 = \frac{T'A_1}{N} = \frac{0.24}{3} = 0.08 \text{ (mm)};$$

$$TA_2 = \frac{T'A_2}{N} = \frac{0.3}{3} = 0.1 \text{ (mm)};$$

$$TA_3 = \frac{T'A_3}{N} = \frac{0.06}{3} = 0.02 \text{ (mm)}.$$

For the  $i^{th}$  group of parts (see Table 2.3.) the following coordinates of centerlines of tolerance zones are set

$$\Delta_0 A_1 = -0.04 \text{ mm}; \Delta_0 A_2 = -0.05 \text{ mm}.$$

The coordinate of the centerline of the dimension  $A_3$  tolerance is found from the equation

$$\begin{aligned} \Delta_0 A_\Delta &= \Delta_0 \bar{A}_2 - \Delta_0 \bar{A}_1 - \Delta_0 \bar{A}_3; \\ 0.1 &= 0.05 - (-0.04) - \Delta_0 A_3. \end{aligned}$$

Hence

$$\Delta_0 A_3 = -0.1 + 0.05 + 0.04 = -0.01 \text{ (mm)}.$$

The coordinates of the tolerance centerlines of the dimensions of each following group (Table 2.3) are obtained by increasing the coordinate of the previous group by the value of the group tolerance, i.e. for the dimension  $A_1$  – by 0.08 mm; for the dimension  $A_2$  – by 0.1 mm; for the dimension  $A_3$  - by 0.02 mm.

Table 2.3

*Tolerances and coordinates of tolerance centerlines of the component dimensions*

Group	$TA_1$	$\Delta_0 A_1$	$TA_2$	$\Delta_0 A_2$	$TA_3$	$\Delta_0 A_3$	$TA_\Delta$	$\Delta_0 A_\Delta$
<i>I</i>	0.08	-0.04	0.1	+0.05	0.02	-0.01	0.2	0.1
<i>II</i>	0.08	+0.04	0.1	+0.15	0.02	+0.01	0.2	0.1
<i>III</i>	0.08	+0.12	0.1	+0.25	0.02	+0.03	0.2	0.1

The last two columns of the table show that the assembly of parts of the corresponding groups will ensure the required size of the resulting dimension.

The basic sizes and limit deviations of the component dimensions in groups of parts are given in Table 2.4.

Table 2.4

*Basic sizes and limit deviations of the component dimensions*

Group	$A_1$	$A_2$	$A_3$
<i>I</i>	$45_{-0.08}$	$50^{+0.1}$	$5_{-0.02}$
<i>II</i>	$45^{+0.08}$	$50^{+0.2}_{+0.1}$	$5^{+0.02}$
<i>III</i>	$45^{+0.16}_{+0.08}$	$50^{+0.3}_{+0.2}$	$5^{+0.04}_{+0.02}$

### 2.2.3.4 Fitting Method

The fitting method implies that the required accuracy of the resulting dimension is ensured by varying the size of the so-called adjusting member (one of the component dimensions) by removing a certain thickness layer of material from it. The compensating dimension, often referred to simply as the compensator, is designated on the dimensional chain diagram as a framed dimension, for example  $\boxed{A_1}$ .

The fitting method ensures the accuracy of the resulting dimension by allocating economically feasible, under the specified manufacturing conditions, tolerances to the component dimensions, and defining coordinates of the tolerance zones centerlines:

$$T'A_1, T'A_2, \dots, T'A_{n+p};$$

$$\Delta'_0 A_1, \Delta'_0 A_2, \dots, \Delta'_0 A_{n+p}.$$

The resulting dimension tolerance  $T'A_\Delta$  may exceed the required tolerance  $TA_\Delta$ , i.e.

$$T'A_\Delta = \sum_{i=1}^{n+p} T'A_i > TA_\Delta.$$

The difference between these tolerances is called the maximum calculated compensation

$$\delta_c = T'A_\Delta - TA_\Delta.$$

This calculated compensation must be eliminated from the dimensional chain by removing the allowance from the adjusting member.

Let's show sequence and contents of fitting works on the example (Fig. 2.19), assuming that the spacer ring of thickness  $\boxed{A_3}$  is taken as the adjusting member. Firstly, preassembly of the product is performed (without mounting the spacer ring) and the distance between the face of the gear and the wall of the housing is measured. The size of the compensating dimension  $\boxed{A_3}$  is usually defined as the difference between this distance and the desired average gap  $A_\Delta$ . Next, the product is disassembled. Then, by removing allowance from the spacer ring, the required size of the spacer ring is achieved and the product is finally assembly.

The main advantage of the fitting method is the possibility to achieve high accuracy of the resulting dimension at a relatively low accuracy of parts.

The disadvantages of the method are the need for highly skilled workers and a significant variation of time spent to variation of allowances to be removed. The latter hinders the use of flow production methods.


Job production and small-scale production are considered as the economically feasible areas of application of the fitting method.

### 2.2.3.5 Adjustment Method

Method of adjustment implies that the required accuracy of the resulting dimension is achieved by changing the size of the compensating dimension without removing material from the compensator.

In principle, the method of adjustment is similar to the fitting method. The difference between them is how to change the size of the compensator. In the method of adjustment, this change can be accomplished in two ways: by changing the position of the compensating dimension or by inserting a special part of the desired size, into the product assembly. In the first case the compensator is called a movable compensator and in the second case – a stationary one.

An example of a movable compensator is a sleeve in the mechanism (Figure 2.22). By moving the sleeve in the axial direction the gap  $A_{\Delta}$  between its face and the face of the gear can be adjusted. After the required gap is achieved, the sleeve position is fixed relative to the housing by a locking screw.



*Fig. 2.22 Ensuring accuracy of the gap  $A_{\Delta}$  in the adjustment method with the help of the movable compensator*

As a stationary compensator the spacer rings, washers and other parts of simple construction are used. The groups of stationary compensators of different sizes should be manufactured beforehand.

The adjustment method advantages are as follows.

1. It is possible to achieve any degree of accuracy the resulting dimension with broad tolerances of the component dimensions.
2. Time spent on adjustment work is relatively small.
3. There are no significant difficulties in organizing and planning the assembly work.
4. It is possible to maintain the required grade of accuracy of the resulting dimension in the process of product operation, which has tendency to reduce due to the wear of parts.


In practice, the tasks of ensuring required accuracy of resulting dimensions are often solved for the interconnected dimensional chains. In this case, the solution of the direct task starts for a dimensional chain with the smallest tolerance of the resulting dimension. Then the task is solved for the dimensional chain with the successively wider tolerance, and so on. The methods of ensuring required accuracy for each individual dimensional chain can vary. The inverse task can be performed in any sequence of the dimensional chains.

All above-mentioned methods of ensuring accuracy of resulting dimensions were related to the dimensional chains, the dimensions of which are linear. For the dimensional chains with angular dimensions, given in degrees and having a common vertices of angle (see Fig. 2.12, *c* and 2.12, *d*), the methods of calculation and relationships are the same as for dimensional chains with linear dimensions.

#### **2.2.4 Tolerance Analysis of Manufacturing Processes**


As noted above, the resulting dimensions in manufacturing dimensional chains of the second type, hereinafter simply called manufacturing dimensional chains, are the functional dimensions of the parts and the dimensions of the machining allowances. The component dimensions of these chains are the manufacturing dimensions of the workpiece. These include dimensions of the initial workpiece, dimensions obtained on all machining operations (processing steps), dimensions of heat-hardened layers, i.e. all the dimensions that are specified in the manufacturing documentation, which regulates the process of parts production.

Fig. 2.23 shows a diagram of facing the workpiece on a lathe and a simple manufacturing dimensional chain, the component dimensions of which are the workpiece dimensions  $A_1$  and  $A_2$  obtained on the previous and current operations respectively. Since it is the dimensions  $A_1$  and  $A_2$  that are sure to be obtained on the operation, the allowance  $Z$  is a resulting dimension in the manufacturing dimensional chain (the allowance is obtained as the result of the obtaining these dimensions).



*Fig. 2.23 Facing of a workpiece on a lathe and manufacturing dimensional chain, with the allowance as a resulting dimension*

At the same time, in some cases, the allowance can be included in the dimensional chain as a component dimension, i.e. the manufacturing dimension in a way. Fig. 2.24 shows a diagram of facing a bar on a turret lathe. The bar after machining of the previous workpiece is fed to the right until it contacts the stop, relative to which at a distance equal to the allowance  $Z$  a facing cutter is set. Thus, allowance (manufacturing dimension  $A$ ) will be obtained after the facing of the workpiece.



*Fig. 2.24 Facing of a bar on a turret lathe*

If the functional dimension is a resulting dimension in the manufacturing dimensional chain (see Fig. 2.15, *b*), then we say that it is not directly ensured during the part manufacturing. In most cases this can be avoided, but usually at


the expense of complicating the manufacturing process. Therefore, manufacturing processes are often designed so that some of the functional dimensions, usually those of the lower accuracy, are not ensured directly.

However, there are functional dimensions which can not be physically ensured directly. An example of such a functional dimension is the thickness of the carburized layer that is formed by chemical heat treatment and subsequent grinding.

Note that the diametric functional dimensions, with a few exceptions, are directly ensured during the manufacture.

In addition, it is necessary to distinguish between the allowances and the so-called redundant allowances. Redundant allowance is an "extra" amount of material that must be removed due to simplification of the original shape of the workpiece relative to the net shape of the part. The concept of "redundant allowance" is illustrated in Fig. 2.25, which shows allowances by ordinary hatching and redundant allowance by cross-hatching (workpiece is a round rolled bar). Unlike allowances the redundant allowances are not included into manufacturing dimensional chains and are omitted during the tolerance analysis.

The essence of the tolerance analysis of the designed manufacturing process is in solving the inverse tasks for the manufacturing dimensional chains.



*Fig. 2.25 Explanation of a redundant allowance*

Tolerance analysis helps to assess quality of a manufacturing process and to particularly determine whether the process will ensure functional dimensions that are not directly obtained during the workpiece machining, to find the limits of size for the machining allowances and assess sufficiency of the allowances to ensure the required quality of surface layer of the machined surfaces and (or) the possibility to remove the allowances without overloading the cutting tool.

The initial data for tolerance analysis are the part drawing, the drawing of the workpiece and the manufacturing process.

Procedure of the tolerance analysis for the designed manufacturing process is easier to examine using a specific example. Let's consider manufacturing process of a punch as an example (see Fig. 2.26). Tolerance analysis is performed only in the longitudinal direction; tolerance analysis in the diametrical direction can be performed similarly.




Fig. 2.26 Sketch of a part








Fig. 2.27 Sketch of a workpiece

After examining the initial data, the simplified sketches of a part, a workpiece and machining process are drawn. In sketches of a part and a workpiece, only the longitudinal dimensions are specified (Fig. 2.26 and 2.27). Sketches of machining are performed only for the operations that form longitudinal dimensions (Table 2.5). The changes of sizes during the heat treatment are considered to be negligible. Sketches of machining are supplemented with designation of the manufacturing datums, the machined surfaces (thick lines) and all the manufacturing dimensions in the longitudinal direction.



Table 2.5

Operation	Sketch	Processing steps
<p>1 Turning</p>		<ol style="list-style-type: none"> <li>1. Cut the face ensuring the dimension <math>57_{-0,74}</math>.</li> <li>2. Cut a chamfer.</li> </ol>
<p>2 Turning</p>		<ol style="list-style-type: none"> <li>1. Cut the face, ensuring the dimension <math>55,2_{-0,3}</math>.</li> <li>2. Cut the face, ensuring the dimension <math>30 \pm 0,1</math>.</li> <li>3. Cut the chamfer.</li> </ol>
<p>3 Heat treating</p>		<ol style="list-style-type: none"> <li>1. Harden.</li> <li>2. Temper.</li> </ol>
<p>4 Cylindrical grinding</p>		<ol style="list-style-type: none"> <li>1. Grind the face, severing the allowance <math>0,2 \pm 0,05</math>.</li> </ol>
<p>5 Surface grinding</p>		<ol style="list-style-type: none"> <li>1. Grind the face, ensuring the dimension <math>30 \pm 0,026</math>.</li> </ol>

The operations and processing steps being analyzed are numbered in the sequence of the numbers 1, 2, 3, etc. In addition, the numbers of the operations according to the manufacturing process are denoted.

Manufacturing dimensions are indicated by the letter A with the indices of numbers of the operations and processing steps. For example, the size  $A_{1,2}$  is obtained during the 2<sup>nd</sup> processing step of the 1<sup>st</sup> operation. For the dimensions of the workpiece the first index is 0 (zero), and the second one equal to 1, 2, 3, etc.

Functional dimensions are denoted by the letter K with indices 1, 2, 3, etc.

Allowances are denoted by the letter Z with the same indices as the manufacturing dimensions for which these allowances are removed.

To carry out tolerance analysis the dimensional diagram of the manufacturing process is built. To construct a dimensional diagram the machining allowances are depicted in an arbitrary scale on the sketch of the part as shown in Fig. 2.28. At first, the allowances that are cut on the last operation are shown, then allowances of the second operation and so on.

The following elements should be denoted on the sketch:

- manufacturing dimensions in the order of their obtaining, starting with the dimension of the initial workpiece and ending with the dimensions of the last operation;
- dimensions of the machining allowances (represented by wavy lines);
- functional dimensions.

Thus the dimensional diagram of the manufacturing process is constructed (Figure 2.28). The correctness of the constructed diagram is checked as follows:

- number of manufacturing dimensions should be one less than the number of the machined surfaces;
- number of functional dimensions and allowances should be equal to the number of manufacturing dimensions.

In the given example, the number of surfaces is 10, the number of manufacturing dimensions is 9, the number of functional dimensions is 4 and the number of allowances is 5. Therefore, the dimensional diagram is constructed correctly.

It should be borne in mind that if the allowance value is ensured during the processing step, then the allowance is a manufacturing dimension as well. In this example, the allowance  $Z_{4,1}$  is the manufacturing dimension  $A_{4,1}$ . This allowance must be considered as both an allowance and a manufacturing dimension.




Fig. 2.28 Dimensional diagram of the process

The manufacturing dimensional chains are defined according to the dimensional diagram of the process. For example, the allowance  $Z_{1.1}$  is the resulting dimension in the dimensional chain that incorporates component dimensions  $A_{0.1}$  and  $A_{1.1}$ , and the functional dimension  $K_4$  is the resulting dimension in the dimensional chain with dimensions  $A_{2.3}$  and  $A_{4.1}$ .

However, it is difficult to identify manufacturing dimensional chains with a large number of component dimensions. To facilitate this task it is reasonable, especially in the absence of experience, to construct a graph of the manufacturing dimensional chains.

To do this, all surfaces in the dimensional diagram (Fig. 2.28) are numbered strictly in the order of their position (from left to right or right to left).

Firstly, a graph-tree of manufacturing dimensions is constructed (Fig. 2.29). The machined surfaces on the graph-tree are depicted by circles (vertices of a graph), and manufacturing dimensions are depicted by straight lines (ribs) that connect the corresponding vertices. Construction of the graph-tree starts from the vertex-root. As a vertex-root the datum surface of the first operation or surface from which the first manufacturing dimension is given should be taken.




Fig. 2.29 Graph-tree of the manufacturing dimensions

In the given example, the surface 10 is taken as the vertex-root (see Fig. 2.28 and 2.29.) From the vertex-root 10 the lines  $A_{0,1}$ ,  $A_{0,2}$  and  $A_{1,1}$  are constructed, at the ends of which the vertices 1, 7 and 2 are located, respectively. From the vertex 2 the lines  $A_{1,2}$  and  $A_{2,1}$  are constructed, at the ends of which the vertices 3 and 9 are located, respectively, and so on. As a result, the graph-tree should include all the surfaces (the vertices) and manufacturing dimensions (the ribs), that connect these surfaces, of the dimensional diagram. The graph is built correctly provided that there are no gaps and closed circuits (loops).

Then, the graph-tree is supplemented with the functional dimensions in the form of thick arcs that connect the corresponding vertices, and with the allowances in the form of wavy lines. Thus the graph of the manufacturing dimensional chains is constructed (Fig. 2.30).

The manufacturing dimensional chains on the graph are represented as the shortest contours, which consist of allowance or functional dimension and manufacturing dimensions. For example: the allowance  $Z_{2,2}$  is the resulting

dimension of the chain with the component dimensions  $A_{0,2}$ ,  $A_{1,1}$ ,  $A_{2,1}$  and  $A_{2,2}$ ; the functional dimension  $K_1$  is the resulting dimension of the chain with the component dimensions  $A_{5,1}$ ,  $A_{4,1}$ ,  $A_{2,2}$  and  $A_{2,1}$ ; the functional dimension  $K_3$  is of the same size with the manufacturing dimension  $A_{1,2}$ , i.e. is ensured directly.




Fig. 2.3 Graph of the manufacturing dimensional chains

To define the increasing and the decreasing dimensions on the graph (Figure 2.30), proceed as follows. Look through the dimensional contour starting the tracking along the resulting dimension from the vertex with a greater number to the vertex with a smaller number. If, in the direction of tracking, the component dimension connects vertex of a smaller number with the vertex of a higher number, then the dimension is an increasing one, and if the opposite it is a decreasing one. For example, the tracking of the contour with  $Z_{2,2}$ ,  $A_{0,2}$ ,  $A_{1,1}$ ,  $A_{2,1}$ ,  $A_{2,2}$  (Fig. 2.30) should be started from the vertex 7 to the vertex 6. Equation of the dimensional chain will be

$$Z_{2,2} = A_{2,2} - A_{2,1} + A_{1,1} - A_{0,2} = A_{2,2} + A_{1,1} - A_{2,1} - A_{0,2}.$$

The manufacturing dimensional chains and the results of calculation of their resulting dimensions (allowances and functional dimensions) for the given example are shown in Table 2.6. The results of calculations, performed by the maximum-minimum method, indicate the following.

Table 2.6

Inspected dimensions	Dimensional chains diagrams	Dimensional chains equations and calculation of the resulting dimensions values
$K_1 = 55_{-0.74}$		$K_1 = A_{2.1} + A_{5.1} - A_{2.2} - A_{4.1};$ $K_1 = 55.2_{-0.3} + 30 \pm 0.026 - 30 \pm 0.1 - 0.2 \pm 0.05 = 55^{+0.176}_{-0.476}$
$K_2 = 30 \pm 0.026$		$K_2 = A_{5.1} = 30 \pm 0.026$
$K_3 = 1 \pm 0.3$		$K_3 = A_{1.2} = 1 \pm 0.3$
$K_4 = 1 \pm 0.3$		$K_4 = A_{2.3} - A_{4.1};$ $K_4 = 1.2 \pm 0.2 - 0.2 \pm 0.05 = 1 \pm 0.25$
$Z_{1.1}$		$Z_{1.1} = A_{0.1} - A_{1.1};$ $Z_{1.1} = 59^{+1.0}_{-0.5} - 57_{-0.74} = 2^{+1.74}_{-0.5}$
$Z_{2.1}$		$Z_{2.1} = A_{1.1} - A_{2.1};$ $Z_{2.1} = 57_{-0.74} - 55.2_{-0.3} = 1.8^{+0.3}_{-0.74}$

Inspected dimensions	Dimensional chains diagrams	Dimensional chains equations and calculation of the resulting dimensions values
$Z_{2.2}$		$Z_{2.2} = A_{1.1} + A_{2.2} - A_{0.2} - A_{2.1};$ $Z_{2.2} = 57_{-0.74} + 30 \pm 0.1 - 30_{-0.5}^{+1.0} - 55.2_{-0.3} = 1.8_{-1.84}^{+0.9}$
$Z_{5.1}$		$Z_{5.1} = A_{2.2} + A_{4.1} - A_{5.1};$ $Z_{5.1} = 30 \pm 0.1 + 0.2 \pm 0.05 - 30 \pm 0.026 = 0.2 \pm 0.176$

The designed process of a punch manufacturing does not ensure functional dimension  $K_1$ , which is a resulting dimension in the dimensional chain with dimensions  $A_{2.1}$ ,  $A_{5.1}$ ,  $A_{2.2}$  and  $A_{4.1}$ . However, the calculated error of the  $K_1$  (0.652 mm) is less than its tolerance (0.74 mm). Therefore, to ensure the specified by the drawing the limit deviations it only is necessary to adjust the basic sizes of the relevant manufacturing dimensions. Functional dimensions  $K_2$  and  $K_3$  are ensured directly, coinciding with the manufacturing dimensions  $A_{5.1}$  and  $A_{1.2}$ , respectively. Functional dimension  $K_4$ , being the resulting dimension in the dimensional chain with dimensions  $A_{2.3}$  and  $A_{4.1}$ , is obtained in accordance with the requirement of the drawing.

Let us now turn to the analysis of the calculated values of machining allowances. The minimum values of the allowances  $Z_{1.1}$  and  $Z_{2.1}$  are sufficient to ensure the required quality of the surface layers; fluctuation of these allowances is small, providing sufficiently stable machining conditions. The minimum value of the allowance  $Z_{2.2}$  is negative, which could lead to the violated requirements of the surface layer quality (some surfaces on the part will remain unmachined). The minimum value of the allowance  $Z_{5.1}$  is only 0.024 mm, which may not be sufficient to remove the defective layer.

Therefore, the process described above as a whole should be considered unsatisfactory, requiring corresponding adjustments.

## Review Questions

1. What is locating and clamping?
2. What is a datum, a set of datums, a locating point?
3. What is the six-point principle?
4. How are datums classified according to the number of the constrained degrees of freedom?
5. How are datums classified according to the nature?
6. What are the primary and auxiliary datums of a product?
7. What is a dimensional chain?
8. Can you list the types of component dimensions of dimensional chains?
9. How are dimensional chains classified?
10. What are the direct and inverse tasks in calculation of dimensional chains?
11. How is the resulting dimension tolerance allocated between the tolerances of the component dimensions (solution of the direct task)?
12. What is the difference between maximum-minimum method and statistical method of the direct task solving?
13. How are the planar dimensional chains with non-parallel dimensions solved?
14. What are the peculiarities of calculation of parallel-linked dimensional chains?
15. What is the essence of ensuring accuracy of the resulting dimension by the complete interchangeability method?
16. What is the essence of ensuring accuracy of the resulting dimension by the incomplete interchangeability method?
17. What is the essence of ensuring accuracy of the resulting dimension by the group interchangeability method?
18. What is the essence of ensuring accuracy of the resulting dimension by the fitting method?
19. What is the essence of ensuring accuracy of the resulting dimension by the adjustment method?
20. What dimensions are resulting in dimensional chains formed during the manufacture of parts?
21. How is the dimensional diagram of the manufacturing process constructed?
22. What is the essence of the tolerance analysis of the designed manufacturing process?



### **3. Ensuring Material Properties and Accuracy of a Part**

To get the high-quality part it is necessary for the manufacturing process to involve solution of the two most important tasks:

- ensuring the required material properties of a part;
- ensuring the necessary accuracy of sizes, form and location of the part surfaces.

These tasks are interconnected though it is rational to look at each of them separately at first.

#### **3.1 Ensuring Material Properties**

##### **3.1.1 General Ideas on Formation of Material Properties during Manufacturing**

Parts of machines are manufactured from steels, cast irons, non-ferrous metals and alloys, polymers, granite and other materials. Material of a part is chosen by a design engineer basing on the part function. The choice of material is also done due to its technological properties.

Mechanical properties of material are ultimate strength, yield strength, hardness, Young modulus, impact strength, fatigue strength, strain, etc.


Physical properties of material are specific weight, point of melting and crystallization, thermal conductivity, coefficient of thermal expansion, electrical resistance, etc.

Chemical properties of material are characterized first of all by its corrosion resistance.

Technological properties of material are its casting characteristics, deformability and machinability, weldability, etc.

In manufacturing a part, material of the workpiece is exposed to force, heat, chemical and other kinds of influences. As a result, chemical composition, structure, grain size and, hence, the properties of material can change at any stage of the manufacturing process. The formation of the part material properties can be presented by the scheme shown in Fig. 3.1.

The way material properties of workpiece material are formed at the main stages of manufacturing are further considered.



*Fig. 3.1 The scheme of forming material properties of workpiece material while manufacturing*

**Formation of properties of workpiece material.** Rolling, casting, forging and stamping are mostly used to produce workpieces.

Structure and grain size of casting material which influence on the mechanical properties of material are defined by the big number of factors: amount and kind of impurities and alloying elements in the alloy, casting temperature, rate of cooling during crystallization, temperature, thermal conductivity, condition of inner surfaces of a casting mold.

Harmful impurities that affect mechanical and physical material properties of castings are sulfur and phosphorus. Phosphorus reduces plasticity, causes cold brittleness of steel and promotes formation of liquation. Sulfur causes hot tears that appeared during crystallization. The more complicated is the shape of casting and the higher is the resistance of the casting mold to metal shrinkage, the more dangerous is the high concentration of sulfur in steel.

Alloying steel with nickel, chromium, molybdenum and vanadium favors fine-grain structure and improves mechanical properties of castings.

Higher speed of cooling during crystallization leads to finer grain structure. Hence, permanent-mold casting compared to sand casting provides higher mechanical properties for the casting material. At the same time, it is necessary to bear in mind that during fast cooling of surface layers of thin-walled parts of the cast iron castings, chilling can take place. Chilling is a forming of white cast iron where all the carbon is in bound state in the form of cementite. White-cast iron has high hardness (HB 4500...5500 MPA); its machining by cutting tools is ultra-problematic.

Material properties of a casting depend largely on its construction that should provide the possibility of simultaneous or successive solidification of the casting elements. Uniform thickness of casting walls is desirable for simultaneous solidification, while gradual increase of wall thickness in direction of metal solidification is desirable for successive solidification. Uneven cooling of different elements of a casting and resistance of casting mold to metal shrinkage can lead to formation of cracks, shrinkage cavities and residual stresses.

When workpieces are manufactured by cold-forming processes, material of a workpiece work hardens. In this case, along with the improvement of strength properties of material, the reduction of its plasticity properties also takes place. Residual stresses appear due to non-uniformity of plastic deformations in different parts of a workpiece.

When workpieces are manufactured by hot-forming process, the temperature of metal heating is of great importance. Violation of temperature conditions can lead to forming of cracks in a workpiece, defective macro-granular structure (overheated steel) and to irreparable reject in the form of burning (melting and oxidation of metal at the grain boundaries that lead to the total loss of plasticity). Before the hot-forming, workpiece should be uniformly heated throughout. Otherwise, thermal stresses arise in the workpiece, which can lead to the cracks formation. High temperature results in oxidation of metal. Consequently, scale and decarbonized layer with thickness of approximately 1.5...2.0 mm appear on the surface of the steel workpiece. To decrease workpiece oxidation, workpieces are heated in neutral or reducing atmosphere.

In general, material of workpieces manufactured by forming process compared to material of conventionally manufactured castings has finer grain structure and higher mechanical properties. Moreover, when using special casting methods, for example, a method of directional solidification, a very high level of mechanical properties can be ensured.

#### **Forming material properties with heat and chemical-heat treatment.**

The main task of heat treatment is the changing material structure aimed at forming the necessary properties. Since steels are the most wide-spread materials in mechanical engineering, then the different types and methods of heat treatment will be described below as applied to the steel workpieces.

The main types of heat treatment of steel workpieces are annealing, normalizing, hardening and tempering.

*Annealing* of steel workpieces is done to reduce hardness, to raise plasticity, to get uniform fine-grain structure and relieve residual stresses. During annealing, workpieces are heated by 30...50 °C higher than point  $A_{c3}$ , then is held at this temperature till the total completion of structure-phase conversions and then is slowly cooled down. As a result of annealing, the coarse-grained structure that affects mechanical properties of steel is eliminated. In workpieces produced by forging and stamping, annealing eliminates the consequences of difference in deformation conditions of the workpiece separate sections, and the structure of steel becomes uniform.

*Normalising* differs from annealing by the conditions of cooling. After

being heated to temperature 50...70 °C higher than point  $A_{c3}$  the workpiece is cooled down in the air. Normalising provides higher strength than annealing due to higher cooling rate.

*Hardening* of steel workpieces is done to produce structures with high hardness. During (full) hardening, the workpiece is heated higher than point  $A_{c3}$ , is held at this temperature for a definite time period and is then cooled down fast by sinking the workpiece into water or oil with the temperature of 20...25 °C. Essential residual effects and deformations (warping) of workpieces appear during hardening because of uneven heating and cooling and changing of volume during phase transitions. Hardening flaws can appear in the workpieces under certain conditions. To avoid these negative phenomena, hardening is done in two media or a graduated hardening is used. Workpieces made of alloy steels which temperature of the end of martensitic transformation is lower than 20...25 °C are cryogenically treated just after hardening. The temperature of cooling is from -40 °C to -196 °C.

It is impossible to achieve similar rate of cooling for both the surface and the core parts of the workpieces in hardening. The rate of cooling at some distance from the workpiece surface turns to be not enough for hardening that is why steel is able to be hardened only to the definite depth. This ability of steel is called hardenability. It can be improved by increasing carbon content and adding the alloying elements, chromium, for example, in steel.

In many cases, it is rational to harden only the surface layer of the workpiece without hardening its core part. For this only surface layer is heated to the hardening temperature and is cooled fast. Heating can be performed by oxy-fuel heating, high frequency current, low-temperature plasma and laser.

*Tempering* is done after hardening at the temperature lower the point  $A_{c1}$ . During tempering, structural and phase transformations occur in hardened steel and they provide improving its plasticity and reducing residual stresses. Depending on the heating temperature, there are three kinds of tempering: low (120...250 °C), average (350...450 °C) and high (500...650 °C). In low tempering, the exposure is 0,5...2 hours. If the temperature is 100...120 °C the exposure can be up to 10...15 hours. This exposure mode is used when it is necessary to maintain steel hardness obtained after the hardening. The exposure in average and high tempering is usually from 1 to 2 hours for the light-weighted workpieces and for the workpieces with the weight from 200 to 1000 kg it is from 3 to 8 hours.

The complex heat treatment of constructional steels, which is a combination of hardening and high tempering, in Russian engineering is called *enhancement (hardening and high-temperature tempering)*.

For case hardening of steel workpieces and making the workpieces corrosion-resistant, the chemical heat treatment is used. The most widespread types of case hardening are carburising, nitriding and carbonitriding.

*Carburising* is diffusion alloying of surface layer of the low carbon steel with the carbon. Further hardening and low tempering provide high hardness of the surface layer and high plasticity of the workpiece core part, and cause the formation of compressive residual stresses in the surface layer. It allows wear resistance of a part and its fatigue strength to be improved. Hardness of the surface layer after hardening and tempering can be *HRC* 64...66. The thickness of the carburized case ranges from 0.5 to 2.2 mm, though it can reach (for large workpieces) 6 mm.

Carburising is performed in solid or gas carburizer at the temperature of 920...1050 °C. The exposure can last from 2 to 24 hours.

In many cases, not all but only separate workpiece surfaces that must have high hardness are carburized. To save non-hardening surfaces the copper-coating, special plasters, copper plugs for holes and caps for the outer surfaces are used.

*Nitriding* is diffusion alloying of the workpiece surface layer with the nitrogen. Nitriding is usually used for alloy steel workpieces. Finish machining, then hardening and high tempering are done prior to nitriding. Finish machining of workpieces is done after nitriding (fine surface grinding, lapping, etc.). Nitriding is used for improving the wear resistance and fatigue strength of the parts, and also for corrosion resistance. Hardness of the surface layer after nitriding reaches *HRC* 70...72. Thickness of the nitrided case is usually not more than 0.5 mm. Residual stresses of compression appear in the nitrided case.

Nitriding is done in the atmosphere of dissociated ammonia at the temperature of 500...600 °C. Nitriding process is quite slow. So, to get the nitrided case with the thickness of 0.1 and 0.8 mm at the temperature 500...520 °C accordingly 3 and 90 hours will be required.

*Carbonitriding* is simultaneous diffusion alloying of surface layer of the workpieces with carbon and nitrogen. Such a process has definite advantages. Nitrogen that advances carbon diffusion gives the possibility to lower the temperature of carbon saturation to 820...850 °C. Carbonitriding is usually used for alloy steel workpieces. Carbonitrided case properties takes the intermediate position between carburized and nitrided cases. It has good resistance to wear

and corrosion.

Carbonitriding is done in gas and sometimes in liquid medium. Gas carbonitriding is done in the mixture of carbonizing gas (lighting gas, methane) and ammonia. There are two kinds of this process – high-temperature and low-temperature. In the first case, carbonitriding is done at the temperature of 820...850 °C and in the second case, it is done at the temperature of 530...570 °C. After high-temperature carbonitriding it is necessary to carry out hardening and low-temperature tempering of the workpiece. Hardness of the surface layer after this is *HRC* 63...64. Low-temperature carbonitriding is done after hardening and tempering the workpieces. Hardness of the surface layer after this kind of carbonitriding is *HRC* 67...68. The thickness of carbonitrided case is less than 0.8 mm.

**On influence of cutting and other kinds of dimensional machining on the properties of a workpiece material.** Cutting with cutting tools and abrasive tools prevails in making workpieces nowadays. Electrical discharge, electrochemical, ultrasonic, electron beam, laser and other methods of machining find increasingly wider application. Each of machining method has some or other impact on the material properties of the workpiece and the finished part as well. In cutting, the workpiece surface layer undergoes essential plastic deformations and is thus hardened (work hardened). In electrical discharge machining, where metal removal happens thanks to its melting or vapouring, the structure and chemical composition of the surface layer changes. Electrochemical machining, which is based on anodic dissolution of the workpiece metal, causes etching of the material at the grain boundaries and hydrogenation of the surface layer. Each of machining method except the electrochemical one, under the optimal conditions causes the forming of residual stresses in the surface layer.

In precision dimensional machining, the surface layer with the changed properties is usually not thick, its thickness is about 0.005...0.3 mm. However, since it is the surface layer that withstands the heaviest loads during the part operation, the impact of its material properties on the part performance characteristics turns to be very essential and sometimes crucial.

The condition of the part (workpiece) surface layer is commonly characterized by the term “surface layer quality” that means not only the group of properties of its material but also the microgeometry of the machined surface.

Taking the foregoing into consideration, the impact of the surface layer quality on the performance characteristics of parts and their couplings, as well as manufacturing ensuring of the required surface layer quality will be considered in more detail.

### 3.1.2 Surface Layer Quality and its Influence on Part Performance Characteristics

#### 3.1.2.1 Components of Surface Layer Quality

Components of surface layer quality include surface roughness, waviness, work hardening and residual stresses. Auxiliary components include sub-roughness, chemical composition, structure, grain size, density of dislocations etc.

*Roughness 1* of a surface (Fig. 3.2) represents micro-irregularities with height of 0.01...1000  $\mu\text{m}$  and spacing smaller than the sampling length  $l$ , which is used for roughness measurement.




Fig. 3.2 Roughness (1) and waviness (2)

*Waviness 2* of a surface represents micro-irregularities with height of 0.01...1000  $\mu\text{m}$  and spacing larger than the sampling length  $l$  used for roughness measurement.


Work hardening of the metal surface layer is usually assessed by microhardness (Fig. 3.3). For doing this, the height  $h_H$  and degree of work hardening is determined

$$u_H = \frac{H_{\mu_{\max}} - H_{\mu_{\text{ini}}}}{H_{\mu_{\text{ini}}}} \cdot 100\% ,$$

where  $H_{\mu_{\max}}$  is the maximum microhardness of the metal surface layer;  $H_{\mu_{\text{ini}}}$  is the initial microhardness of the metal.

*Residual stresses* (macrostresses) in the surface layer of parts are characterized by sign (tensile stresses are considered as positive values and compressive stresses – as negative ones), absolute value of the maximum residual stresses  $\sigma_{res_{\max}}$  and their depth  $h_\sigma$  (Fig. 3.3).

It should be noted that residual stresses are elastic stresses and cannot be higher than the yield strength of the material.



*Fig. 3.3 Distribution of microhardness ( $H_{\mu}$ ) and longitudinal residual stresses ( $\sigma_{res}$ ) across the shaft section*

It should be emphasized that the residual stresses are always balanced across the section of the part (Fig. 3.3). However, after finishing operations, the stresses in the core of the part that balance residual stresses in relatively thin surface layer are usually small and as a rule are neglected. It also should be borne in mind that there is always a planar residual stress state in surface layer of parts. Thus, residual stresses are analysed in two mutually perpendicular directions aligned with the part axes. For example, axial and hoop residual stresses are formed in machining of bodies of revolution; in surface grinding the residual stresses will be directed along the longitudinal feed and cross feed. The residual stresses that act in direction perpendicular to the machined surface are usually small and, thus are neglected.

### **3.1.2.2 Measurement of Surface Layer Quality Parameters**

Measurement of roughness parameters is performed with tracing machines and optical devices. The majority of these devices is also used for measuring waviness. To measure waviness on the surfaces of revolution and on spheres, roundness testers are used.

To define parameters of surface layer work hardening, micro-hardness testers that measure hardness by pressing tetrahedral diamond pyramid under



the load up to 2 N are used. Microhardness measurements are done on the sloped samples under the angle  $\alpha = 1 \dots 5^\circ$  to the machined surface (Fig. 3.4). The use of the sloped samples “stretches” the surface layer and allows the necessary amount of measurements to be made. For production of sloped samples, it is necessary to use such machining methods that almost eliminate work hardening of the metal. Lapping with diamond pastes with the decreasing grain sizes or electrochemical machining are usually used for this purpose. At some distance from the surface, the sizes of the pyramid prints (and microhardness) stop changing (Fig. 3.4). This distance corresponds to the depth of the work-hardened layer  $h_1$  that relates to the size  $l$ , which is found by the microhardness tester, with the ratio

$$h_1 = l \sin \alpha .$$

To measure residual stresses, two methods are used: mechanical and X-ray. Mechanical method is the most widespread. It consists in the consequent removal of thin stressed metal layers from the machined workpiece surface and measurement of the deformations of the rest part of the workpiece.




Fig. 3.4 Diagram of microhardness measurement (1 – machined surface; 2 – plane of a sloped sample; 3 – work hardened layer)

To understand the mechanical method of residual stresses measurement better, the most simple case of defining these stresses in a plate (Fig. 3.5) which upper surface was machined will be considered. Suppose that the depth of residual stresses  $h_\sigma$  is much smaller than the plate height  $h$ , i.e.  $h_\sigma \ll h$ . The change of the plate height  $h$  when removing the stressed layers will be supposed to be negligible.




Fig. 3.5 Diagram of defining residual stresses in a plate

Suppose that the differentially small layer of metal, with the residual stresses  $\sigma_{res}$ , is removed from the plate  $da$ . Thus, the plate pure bended by the residual stresses with the moment  $dM$  will get deflection equal to

$$df = \frac{l^2}{8EI} dM .$$

The moment  $dM$  will be

$$dM = \sigma_{res} b \cdot da \cdot \frac{h}{2} .$$

By substituting this formula into the previous equation and taking into consideration that  $I = \frac{bh^3}{12}$  it will be

$$\sigma_{res} \frac{4Eh^2}{3l^2} \frac{df}{da}$$

Or, by changing the differentials with the increments it will be

$$\sigma_{res} \frac{4Eh^2}{3l^2} \frac{\Delta f}{\Delta a} .$$

Therefore, to define residual stresses in the plate surface layer, it is necessary to consequently remove metal layers with thickness  $\Delta a$  from the plate and to measure deflections  $\Delta f$  that arise after this removal. Removal of the layers is usually done by the electrochemical method. Plate deflections can be measured by a dial indicator. The rule of defining signs of deflections  $\Delta f$  is shown in Fig. 3.6. If, after the removal of the layer  $\Delta a$ , the plate bends the way shown in Fig. 3.6, *a*, then the deflection  $\Delta f$  is positive and the residual stresses are tensile. Otherwise, (Fig. 3.6, *b*) the deflection is negative and the residual stresses are compressing.




Fig. 3.6 Determining signs of deflections and residual stresses after removing a layer of material  $\Delta a$  : a – tensile stresses in a layer; b – compressive stresses in a layer

At some distance from the machined surface, the removal of the next metal layer will not be followed by the plate deformation. This distance is taken as the depth of residual stresses  $h_{\sigma}$ .

### 3.1.2.3 Influence of Surface Layer Quality on Part Performance Characteristics

**Surface roughness.** Roughness greatly influences various performance characteristics of parts: friction and wear; contact stiffness; corrosion resistance; fatigue strength; strength of pressure couplings; tightness of joints; electrocontact resistance; dustability of surfaces and many other properties of parts. Surface roughness has the essential impact on wear of parts during break-in. During this period (section *I*, Fig. 3.7) the wear intensity is ultimate. It is much smaller and is almost constant in section *II* of the steady-state wear. Catastrophic wear is characterized by the section *III*. Break-in period forms roughness that is defined only by the friction (wear) conditions rather than by the initial one that is obtained during mechanical machining, but. This roughness, also called equilibrium roughness, can be either smaller or larger than the initial one (Fig. 3.8). If the initial roughness is larger than the equilibrium one, then cutting of the micro-irregularities and gradual increasing of roughness to the equilibrium one takes place during the break-in. If the initial roughness is smaller than the equilibrium one, then seizure and tearing of metal particles and gradual increasing of roughness to the equilibrium one happens due to poor lubricant retention on the surfaces. It is evident that the lowest break-in wear and the highest durability of coupling will be provided in case the initial roughness is close to the equilibrium one. It is the roughness that is necessary to obtain during manufacturing.

Contact stiffness, defined by the ability of the surface layers of the contacting parts to resist the deforming forces, mostly depends on the surface roughness. It should be noted that contact displacements (in joints) caused by

deformation of micro-irregularities make up the essential part of the elastic displacements in a machine. For example, contact displacements make up 80...90 per cent of the overall displacements in the carriages of the metal lathes. To improve contact stiffness, it is necessary to reduce amplitude parameters of roughness ( $Ra$ ,  $Rz$ ) and increase bearing length ratio  $t_p$ .




Fig. 3.7 Surface wear of a part related to time

Surface roughness also influences corrosion resistance of parts. The increase of amplitude parameters of roughness leads to increase of the actual part surface area and intensifies corrosion. That is why roughness must be minimal to provide high corrosion resistance of the parts.




Fig. 3.8 Dependence of roughness of a friction surface on time:

1 –  $Rz_{ini}=5.4 \mu m$ ; 2 –  $Rz_{ini}=0.5 \mu m$ ;  
3 – equilibrium roughness

Surface roughness greatly influences fatigue strength. Valleys of the profiles are the stress risers. The coefficient of stress concentration varies from 1.5 to 2.5 for the surfaces machined by cutting. Formation of fatigue cracks that leads to the part damage happens just near the valleys. Stress concentration reduces and the fatigue strength of the parts increases as amplitude parameters of roughness decrease. Thus, surface roughness reduction of the samples made of steel 30XГСА ( $HRC$  35...37) from  $Ra$  0.74 to 0.22  $\mu m$  increases fatigue

strength by about 14 % and service life more than in three times, according to the data of professor A. G. Suslov. It is found that thanks to self-unloading, the stress concentration near the evenly spaced valleys has less influence on fatigue strength than the stress concentration near the random scratches on the surfaces. That is why the scratches (notches) must be eliminated during manufacture.

**Surface waviness.** Waviness influences wear, contact stiffness, contact fatigue strength, smoothness of movements and part vibration. The influence of waviness on movements smoothness and part vibrations is essential. The presence of waviness on the necks of shafts and plain bearings, on the rings and rolling bodies of the rolling bearings, on the guideways and the slide-block decreases accuracy and movement stability, causes vibrations and noise and leads to reduction of durability of products. To improve all the mentioned above performance characteristics of parts and their couplings it is necessary to reduce amplitude parameters of waviness ( $W_a$ ,  $W_z$ ,  $W_{\max}$ ) and increase waviness spacing  $S_{m_w}$ . For example, it was found that reduction of the waviness height  $W_z$  from 2.5 to 1  $\mu\text{m}$  on the bearing races increases durability more than twice.

**Work hardening of surface layer.** Work hardening of a surface layer considerably defines contact stiffness, wear, fatigue strength and corrosion resistance. The increase of work hardening ratio and work-hardened layer depth promotes the increase of contact stiffness and wear resistance (except the cases of abrasive wear) and also increases fatigue strength of the parts that work at normal temperature. Work hardening of parts made of heat-resistant alloys is harmful as it causes diffusion of the alloying elements from the surface layer and weakening of the surface at elevated temperatures (more than 700 °C). Work hardening of the surface layer also affects corrosion resistance of parts.

**Residual stresses.** Residual stresses greatly influence fatigue strength of the parts under the normal and elevated (up to 700 °C) temperature. Moreover, compressing residual stresses increase fatigue strength of the parts and the tensile one reduces it. It is explained by the fact that compressing residual stresses, by summing up with the environmental stresses (for example, in case of alternating shaft bending), reduce level of resultant tensile stresses in the part surface layer and, thus, prevent the creation of the fatigue cracks.

It was found that compressing residual stresses can increase fatigue strength of steel parts by 50 %, while tensile residual stresses can reduce it by 30 %.

Residual stresses relax (reduce) faster under high temperature and their influence on the fatigue strength of the parts turns to be negligible.

### 3.1.3 Ensuring Surface Layer Quality during Manufacturing

#### 3.1.3.1 Ensuring Surface Layer Quality during Machining

**Forming of the surface roughness during cutting.** Surface roughness forms mostly during the one or two last operations (processing steps) of the manufacturing process, though it depends to a certain extent on the earlier performed operations, for example, heat treatment operations. Each method has one or another range of roughness parameters and also the direction of the machining marks (lay pattern).




Fig. 3.9 Dependence of roughness in turning on:  
*a, b, c* – angles  $\varphi$  and  $\varphi_1$ ; *d, e* – cutter nose radius  $r$ ;  
*f, g* – feed rate  $S$  per revolution

*Forming of surface roughness during cutting.* In cutting, surface roughness depends on the geometrical parameters of the tools (angles of the cutting

edges  $\varphi$  and  $\varphi_1$ , nose radius  $r$ , rake and clearance angles), feed rate  $S$ , cutting speed, cooling conditions, physical-mechanical properties of the part material, kinematics of the machining method, stiffness of the technological system and other factors. Influence of the geometrical parameters  $\varphi$ ,  $\varphi_1$ ,  $r$  and feed rate  $S$  on the surface roughness in turning is shown in Fig. 3.9. As it seen in the given diagrams, reduction of the roughness height can be achieved by reducing angles  $\varphi$  and  $\varphi_1$ , (Fig. 3.9, *a*, *b* and *c*), feed rate (Fig. 3.9, *d* and *e*) and increasing nose radius (Fig. 3.9, *f* and *g*). For the given diagram (Fig. 3.9, *a* and *b*) the calculated roughness height  $Rz_{\text{calc}}$  is


$$Rz_{\text{calc}} = \frac{\text{tg}\varphi \cdot \text{tg}\varphi_1}{\text{tg}\varphi + \text{tg}\varphi_1} S.$$

For the diagram (Fig. 3.9, *d* and *e*)  $Rz_{\text{calc}}$  is defined by the professor V. L. Chebyshev's formula

$$Rz_{\text{calc}} = \frac{S^2}{8r}.$$

If a cutter has minor cutting edge with  $\varphi_1 = 0$  and the length  $f > S$  (Fig. 3.9, *c*) then  $Rz_{\text{calc}}$  will be equal to zero. Such a cutter was called V. A. Kolesov's cutter (according to the surname of the lathe operator who offered this tool design).


Actual roughness height in cutting, as a rule, turns to be higher than the calculated. It happens due to plastic-elastic deformations, formation of a build-up edge on the tool, presence of roughness on the cutter working surfaces, tearing of metal particles from the machined surface (for example, during the machining of cast-iron workpieces) and vibrations in the technological system that periodically change the relative position of the tool and the workpiece. The scheme of increase of the roughness height due to plastic flow of the material from the minor cutting edge is shown as an example in Fig. 3.10. In the result of the plastic flow, the actual surface finish  $Rz_{\text{actual}}$  turns to be larger than  $Rz_{\text{calc}}$  by the value of  $\Delta$ .



*Fig. 3.10 Representation of micro-irregularity raise due to plastic flow caused by the minor cutting edge*

Cutting speed and feed rate have the most influence on the surface roughness from all the cutting parameters. The influence of the depth of cut  $t$  on the surface roughness is usually not essential.

Cutting speed influences the roughness mostly through the forming of the built-up edge on a cutter. Built-up edge distorts the shape of the cutting part and causes the increase of surface roughness. The distinctive dependence of the roughness parameter  $Rz$  on the cutting speed  $V$  is shown in Fig. 3.11 (curve 1). For constructional carbon steels, the total lack of built-up edge and the minimum roughness have place if  $V > 70$  m/min. The actual roughness height turns to be close to its calculated values (the straight line 2 in Fig. 3.11) in this case.



*Fig. 3.11 Influence of cutting speed on the roughness parameter  $Rz$  in turning workpieces of steel 45 (0.45% C)  
(curve 1):  $S = 0.5$  mm/rev;  $t = 1$  mm;  
 $r = 1.5$  mm;  $\gamma = 12^\circ$ ;  $\varphi = \varphi_1 = 45^\circ$ .  
Line 2 – calculated value of micro-irregularities height*

The distinctive dependence of the roughness parameter  $Rz$  on feed rate is shown in Fig. 3.12 (the curve 1). Feed reduction in the range 0.17–0.09 mm/rev reduces the actual roughness height that turns to be close to the calculated one (the curve 2 in Fig. 3.12). Further feed reduction (to 0.03 mm/rev) doesn't provide reduction of the actual roughness height that becomes practically constant and significantly higher than its calculated values. It is explained by the fact that surface layer plastic-elastic deformations, that increase actual roughness height, increase in the range of smaller feed rates.

Thus, in turning with the standard cutters, the use of feeds less than 0.06–0.08 mm/rev is unreasonable as it doesn't give any possibility to decrease roughness, but leads to reduction of the production efficiency. However, in high-speed diamond turning of aluminum and copper workpieces, much smaller feed rate is used (about 0.005 mm/rev). In this case, surface roughness equal to  $Rz = 0.025 \dots 0.050 \mu\text{m}$  is achieved thanks to cutting edge sharpness. It should be noted that larger feed rates (about 1 mm/rev) help to obtain relatively small roughness height of the machined surface, if to use cutters of V. A. Kolesov and their various versions.






Fig. 3.12 Influence of feed rate on the roughness parameter  $R_z$  in turning workpieces of steel 18X2H4BA (curve 1):

$V = 130 \text{ m/min}$ ;  $t = 0.25 \text{ mm}$ ;  $r = 0.5 \text{ mm}$ ;  $\phi = 60^\circ$ ;  $\phi_1 = 30^\circ$ . Curve 2 – calculated value of micro-irregularities height (after A.D. Makarov)

The essential influence on the surface roughness in cutting has the chemical composition, grain size and structure of the workpiece material. When machining workpieces made of low-carbon steels, the surface roughness turns to be higher compared to that in turning of less plastic high-carbon steels. The lower surface roughness parameters of steel parts can be ensured in case of homogeneous fine-grain structure. Such grain structure can be obtained in normalizing or annealing of workpieces. The use of lubricating cooling agents reduces friction of the tool against the workpiece and helps to reduce values of roughness parameters.

*Forming of roughness in abrasive machining.* The most types of abrasive machining (grinding, polishing, honing, superfinishing) represent a mass micro-cutting – scratching of the workpiece material and its plastic deformation with the abrasive grains (grits) of the tool. In abrasive machining, particularly in grinding, the roughness profile is formed by the multiple pass of the abrasive grains through the specified workpiece cross-section. (Fig. 3.13).





Fig. 3.13 Roughness formation in grinding:

1 – initial form; 2, 3 – scratches formed after passage of grains of the first and the second rows, respectively; 4 – resulting roughness profile

Roughness depends on the group of factors: grain size of the abrasive wheel, wheel speed  $V_w$ , workpiece rotation speed  $V_{work}$ , longitudinal feed  $S_{long}$  (in the parts of a wheel width  $B_w$  or in millimeters for 1 revolution of a workpiece), sparking-out time, parameters and conditions of the wheel dressing and other factors in cylindrical external grinding with longitudinal feed (Fig. 3.14).

Reduction of the wheel grain size, workpiece rotation speed and longitudinal feed rate and increase of the wheel speed lead to increase in the quantity of grains that pass through the given workpiece cross-section and reduction of the roughness parameters.



*Fig. 3.14 External cylindrical grinding*

The important influence on roughness has the last stage of grinding – sparking-out that is performed without in-feed. With the increase of sparking-out period, not only the quantity of interacting with the workpiece grains increases but also the quantity of grains that perform only plastic deformation (smoothing) of the surface layer that provides essential roughness reduction.

Surface roughness in grinding significantly depends on the wheel dressing parameters. Dressing is mostly done with diamond dressing sticks or diamond crystals that cut the grinding wheel that rotates at working speed. The irregularities that are formed on the wheel surface during the dressing period will form the irregularities on the ground surface of the workpiece. Thus, dressing should be performed with small feed rates of a dressing tool equal to 0.01...0.02 mm/wheel rev. to minimize the roughness of the wheel.

It should be noted that reduction of the wheel grain sizes that provides reduction of roughness parameters leads to the reduction of grinding productivity. To increase productivity grinding is performed in two operations. Coarser grained wheels are used in preliminary grinding when relatively large allowance is removed, and finer grained wheels are used in final grinding. In a number of cases fine grinding is used when allowance for diameter is not more than 0.05...0.1 mm.

Preliminary grinding provides  $Ra = 1.25 \dots 2.5 \mu\text{m}$ , final grinding provides  $Ra = 0.2 \dots 1.25 \mu\text{m}$ , fine grinding provides  $Ra = 0.025 \dots 0.1 \mu\text{m}$ .

**Forming of waviness in cutting.** Waviness forming in cutting happens mostly because of vibrations in technological system machine–fixture–tool–workpiece and also because of transferring waviness of manufacturing datums and cutting edge of a tool onto the machined surface. In turning external surface, for example, the tool can vibrate radially with respect to the workpiece. It results in forming the longitudinal (coinciding with the cutting speed direction) and transversal (coinciding with the feed direction) waves on the workpiece surface (Fig. 3.15).





Fig. 3.15 Formation of longitudinal and transverse waves:  
 $f$  – frequency of cutter vibration

To decrease waviness it is necessary to:

- increase rigidity of the technological system;
- provide thorough balancing of the rotating parts of the technological system (abrasive wheels, spindles, etc.); use counterweights when machining asymmetrical workpieces;
- provide machine isolation from external sources of vibrations (use vibration isolation pads, vibration isolation foundations, etc.);
- reduce waviness of the manufacturing datums and cutting edges;
- optimize geometry of cutting tools and cutting parameters (increase tool angles specified in the reference plane, increase ratio of the cutting layer thickness to its width, use the tools with inclined teeth or with irregular teeth spacing, avoid cutting speeds that correspond to the range of the intensive chattering in the technological system, etc.);
- use tools with vibration dampers.

Layout of one of the most simple and effective vibration dampers – ring-shaped percussion vibration damper – is shown as the example in Fig. 3.16. It

is an additional mass (ring 3) that vibrates with the phase shift on  $\pi$  in relation to the holder 1 vibrations, thus allowing damping of the vibrations.



*Fig. 3.16 Ring-shaped percussion vibration damper:*

*1 – boring bar; 2 – guiding rings; 3 – vibrating ring; 4 – boring cutter*

Minimal waviness is provided in case of using such finishing methods as fine grinding, lapping, superfinishing and honing. For example, the waviness height  $W_z$  in cylindrical external grinding is  $1 \dots 3 \mu\text{m}$  for normal accuracy machines and it is  $0.3 \dots 0.5 \mu\text{m}$  for high-accuracy machines. The waviness height  $W_z = 0,1 \mu\text{m}$  and less in lapping and superfinishing.

**Work hardening of the surface layer in cutting.** Work hardening parameters are defined by the competitive influence of the cutting force, with the increase of which the workpiece surface layer plastic deformations and work hardening intensify, and cutting temperature that promotes release of work hardening.

The rate of work hardening and work hardening layer depth depend on the method and parameters of cutting, geometry of the cutting tool, its wear and also on the chemical composition and structure of the workpiece material that define its hardenability.

It can be roughly considered that any change in cutting parameters that causes cutting force to increase leads to increase of the work hardening rate and depth of the work-hardened layer. Vice versa, any change in cutting parameters that is accompanied with the increase of cutting temperature determines the decrease of work hardening parameters.

For example, in turning the reduction of cutter rake angle and cutting speed and with the increase of the feed rate and depth of cut causes the parameters of surface layer work hardening to increase. Increase of rake angle and cutting speed and reduction of the feed rate and depth of cut leads to the opposite result.

In cylindrical grinding surface layer work hardening increases with the increase in wheel grain size and workpiece rotation speed. With the increase of wheel speed the loading of abrasive grains reduces and grinding temperature increases that reduces work hardening parameters.

Microhardness distribution along the surface layer depth of the workpiece

after finish turning is shown as the example in Fig. 3.17. The data about the rate and depth of work hardening in different machining methods are given in Table 3.1.




Fig. 3.17 Microhardness distribution along the depth of the surface layer of a turned workpiece made of alloy XH77T10P:  $t=1$  mm;  $S=0.08$  mm/rev;  $V=34$  m/min. Cutter made of carbide grade BK6M;  $\gamma=10^\circ$ ;  $\alpha=\alpha_1=10^\circ$ ;  $r=1$  mm;  $\varphi=\varphi_1=45$ ;  $\lambda=0^\circ$  (after A.D. Makarov)

Table 3.1

Rate and depth of work hardening in different machining methods (according to E. V. Rizhov's data)

Machining methods	Work hardening rate, %	Work hardening depth, $\mu\text{m}$
Turning:		
common	20...50	30...50
fine	40...80	20...60
Milling:		
face	40...60	40...100
slab	20...40	40...80
Drilling and core-drilling	60...70	160...200
Reaming	--	150...200
Broaching	50...100	20...75
Gear milling and gear shaping	60...100	120...150
Teeth shaving	--	to 100
Cylindrical grinding:		
soft carbon	40...60	30...60
hardened low-carbon steel	25...30	20...40
Surface grinding	50	16...35

**Residual stresses in cutting.** Formation of residual stresses in surface layer of workpieces in cutting happens under the influence of force and temperature factors (the same way as work hardening forms).

The force factor dominates in cutting. Different signs of plastic deformations in a surface layer are possible under the influence of cutting forces depending on the material plasticity of the workpieces.

Surface layer undergoes plastic stretching and lower layers stretch elastically when machining low-ductility steels and alloys that give discontinuous chip. After the cutting, elastically stretched layers tend to turn to the initial condition but the plastically deformed external layer prevents this. As a result, compressing residual stresses are formed in the surface layer.

During the machining of workpieces made of ductile metals that give continuous chip, the sign of plastic deformation in a surface layer changes into the opposite one and stretching residual stresses appear in the layer.




Fig. 3.18 Distribution of hoop residual stresses along the depth of the surface layer of a turned workpiece of steel grade IIIX15 with HRC 23 (curve 1) and with HRC 62 (curve 2):  $V = 75 \text{ m/min}$ ;  $S = 0.078 \text{ mm/rev}$ ;  $t = 0.2 \text{ mm}$ . CBN cutter;  $\gamma = 0^\circ$  (after B.A. Kravchenko)

The above mentioned information is confirmed by the results of experimental analysis of residual stresses in turning of steel grade IIIX15 of different hardness shown in Fig. 3.18. It can be seen that in cutting with CBN cutters of “soft” workpieces (HRC 23), when continuous chip is formed, tensile residual stresses (curve 1) are induced in the surface layer. In cutting of highly hardened workpieces (HRC 62), when discontinuous chip is formed, the compressing residual stresses (curve 2) are generated in surface layer under the same conditions.

Residual stresses in grinding workpieces mostly forms under the influence of temperature factor. Rapid heating and cooling of a surface layer (instantaneous temperatures in grinding reach steel-melting temperature) can be

found in grinding. The surface layer tends to elongate during the heating but lower located layers prevent this. In the result, surface layer undergoes so-called thermo-plastic deformations, i.e. compression deformations, and tensile residual stresses appear in the surface layer.

Phase transformations accompanied by metal specific volume change in the surface layer can take place in cutting and especially in grinding. For example in grinding, tempering and formation of troostite and sorbite that have less specific volume than martensite structure can happen in separate sections of hardened steel workpieces with martensite structure. As a result, tensile residual stresses form in these areas in the surface layer.

By changing the parameters and conditions of cutting it is possible to influence residual stresses in a surface layer to some extent. For example, by increasing the rake angle of a cutter it is possible to increase the level of tensile residual stresses that form in cutting of plastic metals. Essential increase of the tensile residual stresses in a surface layer in grinding can be achieved thanks to increase of sparking-out duration.

Formation of compressive residual stresses in a surface layer is ensured if to use the finishing methods of abrasive machining: polishing, superfinishing and honing, which are performed with relatively low cutting speeds.

It should be noted that it is difficult to ensure required set of properties of surface layer in some cases during cutting. For example, to reach high fatigue strength of parts that work at normal temperature, it is necessary to ensure low roughness, essential work hardening and compressing residual stresses of the surface layer, which is practically impossible to achieve in cutting. In fact, to obtain low surface roughness the cutting should be performed at high cutting speed and with small feed rate and depth of cut, and to provide essential work hardening and compressing residual stresses the machining should be performed conversely, i.e. at relatively low cutting speed, high feed rate and depth of cut. That is why other machining methods are used to provide the necessary parameters of the surface layer quality. Some of machining methods will be considered below.

### **3.1.3.2 Ensuring Surface Layer Quality by Cold Working Processes**

Cold working processes (surface plastic deformation or SPD) are based on cold plastic deformation of the workpiece surface layer performed with the help of different tools. These processes are (Fig. 3.19): ball and roller burnishing; diamond burnishing; shot peening; mandrelling and the number of other methods.




Fig. 3.19 Various methods of cold working: a – ball burnishing; b – internal roller burnishing; c – external roller burnishing; d – diamond burnishing; e – shot peening; f – ball mandrelling; g – mandrelling with a multiple-teeth tool.  
1 – workpiece; 2 – tool

SPD provides essential work hardening of the surface layer and forming of the compressing residual stresses and also, as a rule, small surface roughness that increases fatigue strength, wear resistance, contact stiffness, reliability of fits and other performance properties of the components and their couplings.

SPD methods are quite simple in general. Ball, roller and diamond burnishing are done on metal lathes and milling machines in job and batch pro-




duction. Mandrelling is done on broaching machines and low-powered hydraulic and pneumatic presses. Special automatic machines are used for ball, roller and diamond burnishing and mandrelling in mass production. Shot peening usually requires application of special equipment.

### 3.1.3.3 Ensuring Surface Layer Quality by Electrochemical Machining and Vacuum Annealing

It follows from the above mentioned that if the component works under the high variable forces and high temperature, not only the surface layer work hardening, but also residual stresses should be minimal to ensure high fatigue strength of the component. Generally, the same requirements are necessary for the surface layer quality of the components that work in aggressive media. It is possible to provide the specified set of surface layer quality parameters if to use electrochemical machining (EM).

The scheme of EM of a turbine blade workpiece is shown in Fig.3.20. Processing is done in the airtight chamber simultaneously with the two tools that have the shape of the blade surfaces. The tools are usually made of brass or corrosion resistant steel. The workpiece is connected to the positive pole of the direct current power supply and the tool is connected to the negative pole. Electrolyte that is usually 20 per cent sodium chloride in water solution is pumped through the gap between the workpiece and the tools. Gap is 0.05...0.3 mm, voltage – 3...30 V, current density – 10...500 A/cm<sup>2</sup>. The feed  $S$  is not required strictly and it is adjusted according to the current strength and is 0,1...20 mm/min. EM can be performed with the stationary tools when removing small allowances.



*Fig. 3.20 Electrochemical machining of a turbine blade: 1 – tools; 2 – workpiece*

Metal removing in EM as it was mentioned before is done by its anodic dissolution. As a result, work hardening and residual stresses are eliminated in the surface layer and also small roughness of the machined surfaces

( $Ra=0.1\dots0.63\ \mu\text{m}$ ) is reached. The latter is explained by the concentration of the current lines on the protrusions of the initial micro-roughness and by the faster metal dissolving on them than on the valleys.

Etching at the grain boundaries with the depth up to  $30\ \mu\text{m}$ , as it was mentioned before, can happen in EM of the workpieces made of some metals and alloys. It can be avoided by increasing the current density in the end of EM. If this can not be done, the mechanical polishing that causes negligible work hardening and compressing residual stresses in the workpiece surface layer is used to remove the traces of the etching.

EM can turn to be unacceptable in some cases. Then, vacuum or neutral medium annealing is used to remove work hardening and residual stresses in the surface layer of the components after the finish cutting.

### **3.2 Ensuring Part Accuracy**

Relatively high accuracy of parts requires as a rule several processing steps or operations. For example, centering necks of shafts (*IT* 6,  $Ra \leq 0.63\ \mu\text{m}$ ) should be undergo rough and finish turning, and rough and finish grinding. Accuracy of axial sizes of a shaft can be a more difficult task as it is shown in Section 2. In regard to this it is reasonable to consider issues of errors formation and accuracy assurance within the separate processing step first and then within the whole manufacturing process.

#### **3.2.1 Causes of Machining Errors. Ensuring Accuracy during Machining**

General (total) error in machining on metal-cutting machines is caused by the following basic reasons:

- geometric errors of the machine tool;
- elastic deformations of the technological system because of the cutting forces;
- cutting tool wear;
- temperature deformations of the technological system;
- deformations of the workpieces due to residual stresses;
- error of the sizing cutting tools manufacture;
- error of the theoretical machining scheme;
- error of workpiece mounting;
- errors of setting and adjusting of the technological system;
- errors of measurement.

Each of the mentioned causes leads to machining errors, which are com-

monly called the individual machining errors. These errors can be systematic or random. Systematic errors can be constant, i.e. unchanged in machining of each workpiece and variable, i.e. changing from one workpiece to another according to the definite law.

Classifying the machining errors into systematic and random is relative as one and the same error, depending on the given conditions, can be regarded as either systematic error or as an accidental one. For example, thread angle error of the individual threading cutter in machining of a batch of workpieces will always cause systematic thread angle error of the resulting thread. If machining is to be done on different machines with different threading cutters that have different thread angles, the error of this angle will lead to a random thread angle error of the machined threads.

### **3.2.1.1 Geometrical Errors of Machine Tools**

Any machine tool has some errors of movement and location of working elements. These errors are defined in no-load state of the machine in slow and usually manual traveling of the working elements and they are called the geometric errors. They are the result of inaccuracies in manufacture and assembly of the machine tool components, as well as components wear. Geometrical errors of a machine can be caused by its deformations due to incorrect installation on the foundation or adjustable rests.

Geometrical errors of a machine tool are: radial and axial run-out of spindles; deviation from straightness of guideways; deviation from parallelism of the metal lathe longitudinal carriage with respect to the spindle axis in horizontal and vertical planes; deviation from perpendicularity of the drill press spindle axis with respect to the table plane, etc.

Geometrical errors of machines are limited by the standards of accuracy according to the correspondent GOST Standards. For example, tolerance of the spindle radial run-out for metal lathes and milling machines of normal accuracy is about 0.01...0.02 mm and the tolerance for the straightness of the guideways on the length of 1000 mm is 0.02 mm. The higher is the accuracy class of the machine (Table 3.2) the smaller are its geometrical errors and higher is the manufacturing labour-intensity.

Table 3.2

*Accuracy classes of machine tools*

Accuracy class of a machine	Error, %	Manufacturing labour-intensity, %
Normal accuracy (H)	100	100
Improved accuracy (II)	60	140
High accuracy (B)	40	200
Super accuracy (A)	25	280
Precision (C)	16	450

Geometrical errors of machine tools are more or less reflected on the errors of sizes, form and location of surfaces of the workpiece being manufactured.

Fig. 3.21 shows schemes of tapering of a workpiece on a lathe caused by the following deviations in the horizontal plane in relation to spindle axis: parallelism of the longitudinal carriage guide ways (Fig. 3.21, *a*); cross-slide guideways perpendicularity (Fig. 3.21, *b*); coaxiality of the tail stock center (Fig. 3.21, *c*). It can be seen that these deviations are completely transferred to the tapering of the workpiece surfaces.

The scheme of deviation influence from the guide ways parallelism of the longitudinal carriage relatively to the spindle axis in the vertical plane of a metal lathe on the errors of the workpiece surface form is shown in Fig. 3.22. With this deviation equal to  $b$  within the workpiece length  $l$ , the cutter travels along the straight line  $AC$ , that is, for example, if the center is at the center height in point  $A$ , then it is higher than the height by the value of  $b$  in point  $C$ . In the result workpiece surface gets the form of hyperboloid of revolution. If to denote the radius of the machined workpiece surface at  $x=0$  via  $r_0$  we will find the maximum  $r_{\max}$  that will have the workpiece in the farthest right section. From the right-angled triangle  $O_1BC$  we obtain

$$r_{\max} = \sqrt{r_0^2 + b^2}.$$




Fig. 3.21 Schemes of taper formation during the machining on a lathe due to its geometrical errors

For the random  $x$  the workpiece radius  $r$  will be

$$r = \sqrt{r_0^2 + \frac{x^2 b^2}{l^2}}.$$




Fig. 3.22 Form error during machining on a lathe caused by deviation from parallelism of the main slide guide ways relatively to the spindle axis in vertical plane

Let us consider an example. Consider that a workpiece with diameter 50 mm and length  $l=500$  mm is turned on a metal lathe. Let us assume that the deviation from the parallelism of the longitudinal carriage guideways in relation to the spindle axis in the vertical plane  $b$  within this length is 0.02 mm. Let us assume that the workpiece radius  $r_0$  is 25 mm. Then its maximum radius is

$$r_{\max} = \sqrt{(25)^2 + (0,02)^2} = 25.000008 \text{ (mm)}.$$

Therefore, we can state that the geometrical errors of this kind lead to negligible machining errors and can be neglected.

The scheme of forming the deviation from flatness in face milling, caused by the deviation from perpendicularity of the vertical milling machine spindle axis in relation to its bed plane in feed direction is shown in Fig. 3.23. The machined surface of the workpiece cross-section becomes curved inward (ellipsoidal). Its deviation from the flatness  $\Delta$  is defined according to the formula

$$\Delta = 0.5 \left( D_{\text{mill}} - \sqrt{D_{\text{mill}}^2 + B^2} \right) \sin \alpha,$$

where  $D_{\text{mill}}$  – milling cutter diameter;  $B$  – the width of the surface to be milled;  $\alpha$  is the angle of inclination of the spindle axis relative to the bed plane in feed direction. If  $\alpha = 10'$ ,  $D_{\text{mill}} = 100$  mm,  $B = 80$  mm then the deviation from flatness in face milling will be

$$\Delta = 0.5 \left( 100 - \sqrt{100^2 + 80^2} \right) 0.0029 = 0.058 \text{ (mm)}.$$




Fig. 3.23 Formation of deviation from flatness in face milling

Therefore, even a small geometrical error of this kind of a vertical milling machine can cause essential error of the machined surface form.

In the process of operation machine tools are worn and their geometrical errors increase. Moreover, the wear in roughing machining, which is characterized by large amounts of severed allowances and high cutting forces, turns to be many times larger than in finishing machining. That is why high accuracy lathes are more reasonable to be used for precision machining only. Machine tools will have high accuracy during a long period of working time and will be paid off only in this case.

### 3.2.1.2 Elastic Deformations of Technological System due to Cutting Forces

In machining, machine tool, fixture, cutting tool and workpiece form the closed elastic system. The mentioned elements of the technological system are elastically deformed under the cutting force, leading to the mutual deflection of the cutting tool and the workpiece. In machining of a batch of workpieces, cutting force varies in a definite range. It is caused by change of the allowance value (depth of cut) due to, for example, errors of size, form and location of surfaces to be machined, also due to variation of mechanical properties of the material (hardness) and also because of progressing tool wear. Different cutting forces (often combined with variable rigidity of the technological system) cause different elastic deflections of the cutting tool and the workpiece and cause errors of machining. Elastic displacements (deflections) of any of the elements of the technological system are usually considered in normal direction to the machined surface. The main impact on these displacements has the cutting force component  $P_y$ . Displacement of the  $i^{\text{th}}$  element of the technological

system  $y_i$  (mm) is

$$y_i = \frac{P_y}{J_i},$$

where  $J_i$  – stiffness of the  $i^{\text{th}}$  element of the technological system (N/mm). From this it follows that stiffness  $J_i$  is the ratio of the force  $P_y$  to the displacement  $y_i$  in direction of the force.

The higher is the stiffness the lower is the rate of technological system reaction to the cutting force change and the higher are machining accuracy and productivity.

Stiffness of technological system elements is usually defined experimentally; rigidity of workpieces of simple shapes and of some tools can be calculated. Stiffness of the new machine units is 20000...100000 N/mm. Stiffness of the worn or misaligned units reduces to 10000 N/mm.

It is necessary to mention that elastic displacements of the technological system elements under the cutting force happen due to internal deformations of the elements, their contact deformations and elimination of clearances. Moreover, as it was mentioned before, the dominated deformations are often the contact deformations.

To calculate estimated machining error caused by elastic deformations of the technological system due to cutting forces let us consider deflections of a cutting tool and a workpiece in longitudinal turning. Fig. 3.24, *a* shows the position of a workpiece clamped in a chuck;  $t_{\text{spec}}$  is the specified depth of cut. The workpiece deflects by the  $y_1$  value and the tool deflects by the  $y_2$  value in the process of cutting (Fig. 3.24, *b*). As a result, depth of cut reduces from  $t_{\text{spec}}$  to the value  $t_{\text{act}}$  (actual depth of cut). For a separate cross-section of a workpiece it can be written

$$y_1 + y_2 = t_{\text{spec}} + t_{\text{act}}; \quad (3.1)$$

$$y_1 = \frac{P_y}{J_{\text{work}}}; \quad y_2 = \frac{P_y}{J_{\text{tool}}}, \quad (3.2)$$

where  $J_{\text{work}}$  is the stiffness of the system “workpiece-chuck-spindle assembly”;  $J_{\text{tool}}$  is the stiffness of the system cutter-tool post-saddle.

Radial component of the cutting force (N) is defined according to the formula

$$P_y = 10C_p t_{\text{act}}^x S^y V^n K_p,$$

where  $C_p$  is the constant value;  $x$ ,  $y$ ,  $n$  – determinants of depth of cut  $t_{\text{act}}$ , feed rate  $S$  and cutting speed  $V$ ;  $K_p$  is the correction coefficient that takes in-



to consideration actual machining conditions.




Fig. 3.24 Deflection of a cutter and a workpiece in longitudinal turning

If to denote  $10C_p S^y V^n K_p$  via  $C$ , then

$$P_y = Ct_{act}^x. \quad (3.3)$$

By substituting (3.3) into (3.2), and subsequent substituting the resulting expressions for  $y_1$  and  $y_2$  into (3.1), will have

$$\left( \frac{1}{J_{work}} + \frac{1}{J_{tool}} \right) Ct_{act}^x + t_{act} = t_{spec}.$$

If exponent  $x$  is a fractional value, then there is no exact solution of this equation with respect to  $t_{act}$ . If to neglect the influence of deflections of the cutting tool and the workpiece on the cutting force and to denote  $t_{spec} - t_{act} = t_{res}$ , we will have the following approximate equation

$$t_{res} = Ct_{spec}^x \left( \frac{1}{J_{work}} + \frac{1}{J_{tool}} \right). \quad (3.4)$$

With the known value of the difference between the maximum and the minimum values of  $t_{spec}$ , which is equal to the half of the diameter tolerance, it is possible to define error of the diametric dimension of the machined workpieces as the double difference between the maximum and the minimum values  $t_{res}$  with the help of this equation. Thus, diameter error of the workpieces after turning will be

$$\Delta_y = 2(t_{res_{max}} + t_{res_{min}}). \quad (3.5)$$

In accordance with Equation (3.4) we will write

$$t_{res_{max}} = Ct_{spec_{max}}^x \left( \frac{1}{J_{work}} + \frac{1}{J_{tool}} \right);$$

$$t_{res_{\min}} = Ct_{spec_{\min}}^x \left( \frac{1}{J_{work}} + \frac{1}{J_{tool}} \right).$$

By substituting these expressions into (3.5) we will eventually have

$$\Delta_y = 2C \left( t_{spec_{\max}}^x - t_{spec_{\min}}^x \right) \left( \frac{1}{J_{work}} + \frac{1}{J_{tool}} \right).$$

Let us find the numerical value of  $\Delta_y$ . Let us consider roughing turning of workpieces made of steel grade 45 ( $\sigma=668$  MPa) with a carbide cutter ( $\varphi=45^\circ$ ;  $\gamma=10^\circ$ ;  $\lambda=0^\circ$ ). The diameter error of the workpieces before the roughing turning is 4 mm. The given depth of cut  $t_{spec}=2\dots 4$  mm, the feed rate  $S=0.5$  mm/rev, the cutting speed  $V=100$  m/min. Stiffness of the technological system elements  $J_{work}=J_{tool}=10000$  N/mm. Coefficient  $C=370$  and the power exponent  $x=0.9$  for these machining conditions. The diameter error of the workpieces after the turning

$$\Delta_y = 2 \cdot 307 \left( 4^{0.9} - 2^{0.9} \right) \left( \frac{1}{10000} + \frac{1}{10000} \right) = 0.24 \text{ (mm)}.$$

Now, let us consider that roughing turning is followed by the finish turning. Let us accept that diameter error of the workpieces before the finishing turning is 1 mm. The specified depth of cut  $t_{spec}$  varies in the range 0.5 to 1 mm, the feed rate is 0.2 mm/rev, the cutting speed is 150 m/min. The rest machining conditions remain the same as in roughing turning. Coefficient  $C$  is equal to 187 for finish cutting. The diameter error of the workpieces after finish turning will be

$$\Delta_y = 2 \cdot 187 \left( 1^{0.9} - 0.5^{0.9} \right) \left( \frac{1}{10000} + \frac{1}{10000} \right) = 0.035 \text{ (mm)}.$$

The considered examples show that errors of workpieces extend in cutting. Machining errors of workpieces caused by elastic deformations of the technological system due to cutting forces can reach essential values. These errors are the most essential in roughing operations and can be greatly reduced in the subsequent finishing operations.

Nevertheless, essential form errors caused by workpiece elastic deflections under the influence of cutting forces can take place in machining of low-rigidity workpieces (even in cases of high accuracy of the workpieces). For example, in turning of a low-rigidity workpiece clamped at one side in a chuck (Fig. 3.25, *a*), the part takes a form of a cubic parabola. The maximum deflection (bending) is at the right end of the workpiece:

$$y_{work_{\max}} = \frac{P_y l^3}{3EI},$$

where  $l$  is the workpiece overhang;  $E$  – Young modulus of the workpiece ma-

terial;  $I$  – second moment of its cross section. The maximum deflection in turning of a non-rigid workpiece set in centers (Fig. 3.25, *b*) is in the middle of the workpiece:

$$y_{\text{work}_{\text{max}}} = \frac{P_y l^3}{48EI},$$

where  $l$  is the length of the workpiece. The shape of the workpiece, in this case, corresponds to the shape of the cubic parabola.




Fig. 3.25 Form error caused by workpiece deflections in longitudinal turning

When machining low-rigidity workpieces the errors caused by their elastic deflections can not only reduce but also increase with the increase of the number of cutting passes. Fig. 3.26 illustrates the increase of the low-rigidity rod form errors in cylindrical grinding with constant in-feed with the increase of the number of passes. The in-feed values for the first and the second passes

are denoted as  $t_{1spec}$  and  $t_{2spec}$  ( $t_{1spec}=t_{2spec}$ ) and the workpiece form errors after these passes are denoted as  $t_{1res}$  and  $t_{2res}$ . The second pass will be performed not with  $t_{2spec}$  but with  $t'_{2spec} = t_{2spec} + t_{1res}$  because of the form error  $t_{1res}$  that was formed after the first pass. This will result in the increase of the force  $P_y$  (in comparison to its value in the first pass) and the workpiece form error to  $t_{2res} > t_{1res}$ . Therefore, with the increase of the number of cutting passes the workpiece form error will increase. It is necessary to reduce the in-feed value for the every next pass in comparison to its value in the previous pass by the value that is higher than the workpiece deflection to reduce workpiece form error in this case.

Elastic deflections of the technological system elements depend in many cases on their mutual arrangement that varies during the machining process. Elastic deflections of the technological system elements in turning of the rod workpiece set in centers are schematically shown in Fig. 3.27. When the cutter is in the extreme right position, the force  $P_y$  is entirely carried by the tailstock center, which has the maximal deflection  $y_{ts_{max}}$ . Headstock center and workpiece deflections are equal to zero in this case. When the cutter travels to the left the tailstock center deflection reduces and the headstock center deflection increases and reaches the maximal value  $y_{hs_{max}}$  in the extreme left position of the cutter. The force  $P_y$  is entirely carried by the headstock center in this position and tailstock center and workpiece deflections are equal to zero. As it was mentioned before the workpiece deflection  $y_{work_{max}}$  is maximum when the cutter is in the middle of the workpiece. Deflections of the cutter and the carriage  $y_{tool}$  do not change.





Fig. 3.26 Diagram of form error increase in cylindrical grinding with the constant infeed rate

As the elastic deflections of the technological system elements (excluding the cutting tool) turn to be variable along the workpiece length, it causes not only diameter errors but also form errors of the machined surfaces. It is notable that the shape of this workpiece depends on the ratio between the elastic deflections (stiffness) of the technological system elements. If, for example, workpiece stiffness is essentially higher than the stiffness of centers, then its generating line turns to be concave, otherwise it is convex (Fig. 3.25, *b*).

In general, errors of machining caused by elastic deformations of the technological system can be 20 to 80 % of the total error.



*Fig. 3.27 Diagram of deflection of elements of the technological system in longitudinal turning*

To reduce these errors it is first necessary to increase the stiffness of the technological system, which can be achieved by:

- using additional supports for workpieces and tools (rests, guiding bushes, etc.);
- mounting stationary (during the machining) units of the machine on the guideways;
- preloading the rolling bearing of the spindle assemblies;
- reducing the amount of joints of components in the fixtures used for setting workpieces and tools.

The other way to reduce the considered machining errors is using the automatic control systems in the machines. These systems help to stabilize cutting force and elastic deflections in the technological system as they control the feed rate relatively to the variation of machining allowance and workpiece hardness.

The schematic diagram of the automatic feed control system for the vertical milling machine constructed under the lead of Professor B. S. Balakshin is shown in Fig. 3.28. The sensor S measures the force  $P_x$  that acts normally to the milled plane. Electrical signal from the sensor goes through the amplifier into the comparator CD where it is compared to the pre-set value  $P_{x_{set}}$  of the master device MD. Error signal is issued from the comparator to the adjusting device AD, which controls rotary speed of the direct current motor that controls the feed rate. So, if  $P_x > P_{x_{set}}$  then the feed rate is reduced, and if  $P_x < P_{x_{set}}$  then the feed rate is increased.




Fig. 3.28 Schematic diagram of a system of automatic control of feed rate on a vertical milling machine

Use of automatic control systems in vertical milling machines helps to significantly reduce errors caused by elastic deformations of a technological

system under cutting forces and at the same time to essentially increase productivity of the machining process. The main disadvantage of such systems is irregular roughness of the machined surface. That is why the use of these systems in final machining of the workpieces is impossible.

Machining with the variable feed rate can be performed on the usual machines, especially on the CNC machines to reduce the errors from elastic deformations of the technological system under the cutting forces. For example, turning with the variable feed rate on lathes helps to reduce form errors of non-rigid workpieces.

Errors caused by elastic deformations of a technological system under the cutting forces can be reduced by pre-distortion of the tool path on CNC machines.

Centerless machining methods (centerless turning, centerless grinding, etc.) help to essentially reduce errors of the considered type. High machining accuracy can be achieved in these methods even if the workpiece is of very low rigidity. For example, centerless grinding of the bars provides diameter accuracy that corresponds to *IT 5–IT 6*.

### 3.2.1.3 Cutting Tool Wear

Cutting tool wear is inevitable in cutting. In finish machining wear happens on the cutting tool flank (Fig. 3.29, *a*), which gradually moves the cutting edge from the workpiece. This results in formation of errors of size and form of the machined surfaces of the workpieces.




Fig. 3.29 On calculations of dimensional wear of a cutter

Tool dimensional wear is defined in a direction perpendicular to the machined surface. Characteristic dependence of the dimensional tool wear on the cutting distance is shown in Fig. 3.29, *b*. The wear is more intensive in the area

$l_1$  (the area of the break-in period) than in the area  $l_2$  of the steady-state wear that is practically straight. The wear is more intensive in the area  $l_3$  (the area of catastrophic wear) and quickly leads to cutting tool destruction.

Intensity of the dimensional wear (wear rate) in the area of the steady-state wear is characterized by the ratio

$$W_0 = \frac{W_2}{l_2},$$

where  $W_2$  – dimensional wear ( $\mu\text{m}$ ) developed on the cutting distance  $l_2$  (m). The general wear curve is substituted by the straight line  $aa$  to calculate the dimensional tool wear. It intercepts the section  $W_H$  on the vertical axis. This value is called initial wear and is expressed in  $\mu\text{m}$ . If the values  $W_0$  and  $W_H$  are known, it is possible to find dimensional wear  $W$  ( $\mu\text{m}$ ) for the cutting distance  $L$  (m) from the ratio:

$$W = W_H + W_0 L.$$

The length of the cutting distance  $L$  (m) in turning is

$$L = \frac{\pi D l}{1000 S},$$

where  $D$ ,  $l$  – is the diameter and the length of the workpiece surface to be machined, respectively, mm;  $S$  is the feed rate, mm/rev.

The length of the cutting distance  $L$  (m) in planning is defined according to the formula:

$$L = \frac{l B}{1000 S},$$

where  $l$ ,  $B$  are the length and the width of the workpiece, respectively, mm;  $S$  is the feed rate, mm per double stroke.

Therefore, tool dimensional wear in turning:

$$W = W_H + W_0 \frac{\pi D l}{1000 S};$$

in planning:

$$W = W_H + W_0 \frac{l B}{1000 S}.$$

Wear intensity  $W_0$  depends on the machining method, workpiece and cutting tool materials, geometrical parameters of the tool and cutting parameters (cutting speed and feed rate). Depth of cut slightly influences wear intensity.

Some data on tool life and wear intensity  $W_0$  of cutters in finish turning and boring with respect to the different materials are shown in Table 3.3.



Table 3.3

*Cutting parameters for finish turning and boring, cutters tool life  
(for  $R_z=10\ \mu\text{m}$ ) and wear intensity (according to A. A. Matalin's data)*

Material to be machined	Tool material	Cutting parameters			Tool life in meters of the cutting length	Wear intensity, $\mu\text{m}/\text{km}$
		Cutting speed $V$ , m/min	Feed rate $S$ , mm/rev	Depth of cut $t$ , mm		
Quality carbon structural steel	T30K4 CBN	100-180	0.04-	0.1...0.3	12500	6.5
		550-600	0.08 0.04- 0.06		25000	3.0
Alloy structural steel	T30K4 CBN	120-180 450-500	0.04- 0.08 0.04- 0.06	0.1...0.3	20000	4.7
Highly-alloyed stainless heat resistant and high-temperature steels	T30K4 CBN	80-120	0.02-	0.1...0.2	11000	6.5
		200-220	0.04		15500	3.0
Steel casting	T30K4 CBN	100-160	0.04-	0.1...0.3	7000	8.5
		200-230	0.06		12500	7.0
Structural steels, quenched and tempered ( $HRC\ 26-30$ )	T30K4 CBN	120-180	0.04-	0.1...0.3	8000	8.5
		350-400	0.08 0.04- 0.06		15000	4.5
Structural hardened steels ( $HRC\ 40-50$ )	T30K4 CBN	70-150	0.02-	0.1...0.2	7000	10
		300-350	0.05 0.02- 0.04		21000	5.0
Grey cast iron	BK3M	80-160	0.04- 0.08	0.1...0.3	18000	5.2

The initial wear  $W_H$  of carbide cutters in finish turning and boring of workpieces made of carbon and alloyed steels and grey cast iron is 2....10  $\mu\text{m}$ .

Dimensional wear leads to errors of form when machining large workpieces. Workpiece surface form errors are usually small when machining small

workpieces. Dimensional wear in this case lead to the steady increase or decrease of workpieces sizes in a batch.

Let us consider finish turning of workpiece made of steel grade 45 with the overall diameter  $D=200$  mm and the length  $l=400$  mm. The machining is performed with a cutter made of carbide grade T30K4, at cutting speed  $V=150$  m/min and feed rate  $S=0.06$  mm/rev. From Table 3.3 we can find that  $W_0=6.5$   $\mu\text{m}/\text{km}=0.0065$   $\mu\text{m}/\text{m}$ . Let the initial wear  $W_H$  be 5  $\mu\text{m}$ . The dimensional wear of the cutter in machining the workpiece will be

$$W = 5 + 0.0065 \frac{3.14 \cdot 200 \cdot 400}{1000 \cdot 0.06} \approx 32 \text{ } (\mu\text{m})$$

and will lead to the taper of the machined surface equal to  $W$ .

Now, let us suppose that a batch of the medium-sized workpieces made of steel 45 is turned under the same conditions. The diameter of the turned surface  $D=30$  mm, the length  $l=40$  mm. The batch volume  $n=100$  pieces. Let us define the diameter increase of the last workpiece, assuming that the whole batch of workpieces is machined without tool readjustment. Dimensional tool wear in this case will be:

$$W = 5 + 0.0065 \frac{3.14 \cdot 30 \cdot 40 \cdot 100}{1000 \cdot 0.06} \approx 46 \text{ } (\mu\text{m}).$$

The diameter of the last workpiece will increase by  $2W=92$  ( $\mu\text{m}$ ).

To reduce machining errors caused by dimensional wear of the cutting tool it is necessary to:

- increase the tool quality by using effective methods of its sharpening, application of wear resistant coatings, using other work-hardening methods;
- optimize cutting parameters and tool geometry;
- use highly effective lubricating-cooling agents and the ways of their delivery to the cutting area.

Periodic readjustment of the cutting tool helps to reduce the considered machining errors essentially.

Dimensional wear and the corresponding machining errors can be essentially reduced if to use cutting bits with a wide minor cutting edge (like V.A. Kolesov's cutters) in turning, boring and planning. Such cutters work with large feed rates that reduce the cutting distance and, hence, their dimensional wear.

The influence of the dimensional wear of a grinding wheel on the errors of the machined workpiece is usually compensated by its periodic dressing. Wheel wear intensity depends on its diameter. The large diameter wheels used in cylindrical external grinding wear slowly compared to the wheels used in internal grinding.

In cylindrical external grinding, the grinding wheel is dressed in 15... 20 min and in automatic internal grinding machines, for example, it is dressed for machining of every workpiece. Wheel dressing is continuously done in some cases. High accuracy of machining in this case is provided by the application of in-cycle gauging.

### 3.2.1.4 Thermal Deformation of Technological System

Elements of a technological system, such as machine tool, fixture, tool and workpiece, are heated during the machining. The major source of heat is mechanical work of a cutting process and work that is spent to overcome forces of friction between the moving components of a machine tool. In addition to this, heat is generated in hydraulic and electric systems of a machine and comes from external heat sources (nearby machine tools, heating systems, etc.). Because of heating, elements of a technological system undergo elastic deformation, which affects their position and movement leading to machining errors, which may constitute up to 30...40% of the total error.

**Thermal deformation of a machine tool.** Heating of a machine tool comes from the specified sources and is no uniform.

Temperature in various points of a machine bed may vary within the range of 10°C and greater. Therefore, beds deform elastically and warp, which in turn affect accuracy of the machine tool components mounted on the bed.


One of the major sources of heat in a machine tool is a spindle assembly. Temperature in various points of a head stock varies within the range of 10°...50°C. The maximum temperature is observed at bearings of a spindle and high speed shafts. The temperature of the spindle and the shafts is found to be higher by 30...40% than the average temperature of the headstock. Warming of a headstock leads to deflection of a spindle position. For example, spindle of a lathe can displace in horizontal and vertical planes by a few hundredths of a millimeter. Axial thermal deformations can also be considerable. In case axial displacement of a spindle is constrained by the back bearing, then, for a spindle with length  $L$  and temperature difference between the spindle and a housing  $\Delta t$ , the axial displacement of the spindle will be:

$$\Delta L = \alpha L \Delta t,$$


where  $\alpha$  is the coefficient of thermal expansion of the spindle material. Assuming  $L=800$  mm,  $\Delta t=10$  °C,  $\alpha =0.000012$  1/°C, we will get  $\Delta l=0.1$  mm, i.e. displacement of the front end of the spindle is quite essential and can cause considerable machining errors, unless the displacement is not compensated by periodic readjustment of the tools.

Warming and cooling of a machine continue for some period of time after the machine has stopped. Fig. 3.30 shows diagrams of thermal deformations of

a spindle end with respect to the time of machining and time of subsequent cooling. It can be seen that the thermal equilibrium of the machine (when a heat gain is balanced by its dissipation into environment) is set only after 5 hours of operation. Deflection of a spindle end in vertical plane reaches 0.048 mm and in a horizontal plane it equals to 0.011 mm. Machine tool cooling is much slower than its warming up.



a



b

Fig. 3.30 Dependence of thermal deflections of a spindle end of a lathe on warming time (cutting time) and cooling time [3]:  
a – in a vertical plane; b – in a horizontal plane

Reduction of thermal deformations and corresponding machining errors is achieved as follows:

- use of machines of the most symmetrical construction, which eliminates thermal bending deformations;
- application of forced cooling of separate machine tool components (spindles, feed shafts);
- use of materials with low thermal expansion (e.g. beds of precision machines are made of granite);
- application of systems of automatic compensation for thermal deformation of the CNC machines headstocks by means of on-line correction of the program;
- use of precision machine tools in climate-controlled shops with the temperature maintained at  $20 \pm 0.5$  °C;
- preliminary warming up of a machine tool in no-load operation conditions, after which thermal deformation stay unchanged.

**Thermal deflections of a workpiece.** Warming of workpieces occurs due to heat generated in cutting zone. In most cases (in turning, milling, shaping, surface broaching), most of the heat is accumulated in the chip. In drilling, the heat mostly remains in the workpiece.

In turning, approximately 50...85 % of heat goes to the chip, and more than 90 % is carried by the chip in high speed machining; 10...40 % of heat goes to the cutter; 3...9 % goes to workpiece and near 1 % dissipates into the environment. In drilling, chip carries away 28 % of heat; 14 % is dissipated into the drill; 55 % remains in the workpiece and 3 % dissipates into the environment.


Thermal deformations of workpieces lead to generation of errors of sizes, form and location.

Let us assume that a through hole of 20 mm in diameter is drilled and reamed in a cast iron workpiece 30 mm in length. Let us assume that the temperature of the workpiece after drilling has increased to 100 °C. Let us find the value of the hole diameter reduction after cooling the workpiece to 20 °C. Leaving the warming of the workpiece and the reamer out of consideration, we can get:

$$\Delta d = \alpha \Delta t d = 0.00001 \cdot 20 = 0.016 \text{ (mm)}.$$

The found value is significant because it constitutes a significant part of the hole diameter tolerance for reaming. It should be noted that the thermal deformation of the workpiece after drilling is difficult to compensate for by increasing the diameter of the reamer, as this deformation is random. This deformation varies due to hardness fluctuations of the workpieces of the batch and their thermophysical properties, and also due to wear of the drill.

In many cases, thermal deformations of a workpiece vary along the length of machining. Fig. 3.31 shows temperature field in the workpiece during longitudinal turning and form of its surface after machining (cooling to ambient temperature). There are three periods of heat distribution and thermal deformations generation during the machining. The first period (when the tool is at the right end) is characterized by low temperature rise of the workpiece, since metal before the cutter is cold. The second (steady) period is characterized by the raise of thermal deformations to a certain level, which then remain constant for most of the length of the workpiece. Temperature field behind the cutter is constant. The third period (when the cutter is close to the left end) is characterized by raise of the workpiece temperature due to reflection of heat waves from the left end. Thermal deformations increase during this period. Thus, unequal allowance is removed from different parts of the workpiece due to variation of the thermal deformations (the smallest allowance is at the left end and the largest one is at the right end), which causes formation of form errors of the workpiece after machining.



*Fig. 3.31 Temperature field (a) and form of a workpiece surface after machining (b) [9]*

The most significant errors caused by thermal deformations are in thin-walled workpieces that are machined by severing large allowances. These errors are especially significant during the machining of thin-walled workpieces of great length on one side (plates, rods, etc.). Errors caused by thermal deformations of massive workpieces are usually small, and they can often be neglected.

Reduction of thermal deformations of workpiece and the machining errors caused by the deformations is achieved as follows:

- by the use effective cooling of workpieces;
- by increasing the cutting speed, which reduces temperature flow into the workpiece;

- by cooling the workpiece, heated by roughing operations, prior to finishing machining (e.g., after drilling a relatively large diameter hole on a CNC machine, it is appropriate to perform machining of small mounting holes, during which the workpiece will cool down, and then perform finish machining of the large diameter hole);
- by using the rational schemes of workpiece mounting (for example, a spring-loaded tailstock center should be used during the machining of a long non-rigid shaft mounted in centers, to prevent thermal buckling of the shaft).

**Thermal deformations of a cutting tool.** Cutting tool is subject to intense heating and essential thermal deformations that contributes to the formation of machining errors. For example, temperature of the working surface of cemented carbide insert can reach 900...950 °C. Although temperature of a tool holder is much smaller than these values, the cutters undergo significant thermal deformations (elongation).

The characteristic dependence of thermal elongation of the cutter on the time of continuous operation is shown in Fig. 3.32, *a*. Elongation of the cutter  $\Delta L_p$  increases until thermal equilibrium, which occurs after approximately 10...20 min in finish machining. When machining is performed without cooling, thermal elongation of a carbide cutter at thermal equilibrium  $\Delta L_{pt}$  equals to 0.03...0.05 mm. It was found that elongation increases with increasing feed rate, depth of cut, workpiece hardness and cutter overhang  $L_p$ , and decreases with increasing cross section area of the holder.

Elongation of carbide cutters at thermal equilibrium can be determined from the empirical formula:

$$\Delta L_{pt} = C \frac{L_p}{F} \sigma (tS)^{0.75} V^{0.5}.$$

where  $C$  is constant value ( $C=0.45$  for cutting depth  $t < 1.5$  mm, feed rate  $S < 0.2$  mm/rev, cutting speed  $V=100...200$  m/min);  $L_p$  is the cutter overhang, mm;  $F$  is the cross-sectional area of the tool holder, mm<sup>2</sup>;  $\sigma$  – is the ultimate tensile strength of the workpiece material, MPa.




Fig. 3.32 Cutter elongation depending on the time of continuous operation (a) and ring the machining of a batch of workpieces (b)

Variation of the cutter length during the machining of a batch of workpieces is shown in Fig. 3.32, b. Cutter cools down during the breaks  $t_1$ ,  $t_2$ ,  $t_3$  in machining. If machining is performed rhythmically, then the breaks periods  $t$  are equal and cutter elongation during machining of all workpieces is also equal. In the absence of rhythmicity ( $t \neq t_1, t_1 \neq t_2$ ), the elongation becomes larger, which leads to increased size errors in the batch of workpieces.

Thermal deformations of a cutter during machining large workpieces can cause errors of the machined surface form. Thermal deformations during machining workpieces of small size may cause dimensional errors.

To reduce workpiece errors caused by thermal deformations of a cutter, it is needed to:

- use efficient cooling of the cutter;
- exclude long breaks in machining;
- reduce the cutter overhang.

### 3.2.1.5 Warping of Workpieces due to Residual Stresses

As mentioned, residual stresses in workpieces occur after casting, hot and cold forming, welding, heat treatment, chemical-heat treatment, machining and other types of processing, as well as after coating operations. Residual stresses are always balanced across the cross-section of the workpiece and are not outwardly apparent. These stresses may cause substantial deformation of the workpieces and lead to errors of size, form and location.

Deformation of workpieces due to residual stress occurs in the following situations.

1. The removal of allowance from the workpiece with residual stresses disturbs the equilibrium of the latter, and after the workpiece is unclamped



causes the workpiece to distort until the new equilibrium state of the remaining residual stresses is established. The higher is the level of residual stresses in workpieces and higher is the allowance, the higher is the workpiece deformation.

2. When workpieces with residual stresses are stored or heated the relaxation (decrease) of the residual stresses takes place and elastic deformation converts to plastic one. The intensity of the residual stresses decrease depends on their magnitude and sign, and the relaxation resistance of the workpiece material, and the decrease intensity is usually different in different locations. This upsets the balance of residual stress and strain causes blanks.

3. The residual stresses caused by machining or other processing methods also lead to deformation after the workpieces is unclamped. The most significant stresses arise in low-rigid asymmetrical workpieces, when different layers of material are removed from their opposite sides. For example, significant deformations caused by residual stresses are observed when long box-shaped workpieces are machined by end mills.

Let's consider, as an example, formation of residual stresses in the beam-shaped workpiece during its straightening by plastic bending, and its subsequent deformations due to machining. Assume that the beam of rectangular cross-section is straightened according to the scheme shown in Fig. 3.33, *a*. In this case, the beam is exposed to pure bending on the length  $l$ . Assume that the beam material is not work hardened, its yield strength is  $\sigma_T$ , and plastic deformation due to straightening is spread over the entire beam cross-section. Stress diagram  $\sigma_{PL}$  for the plastic bending due to moment  $M$  is shown in Fig. 3.33, *b*. The beam unloading is equivalent to the application of moment equal and opposite to the moment, that is  $M' = -M$ . The diagram of the elastic stresses  $\sigma_E$  in the beam due to this moment is shown in Fig. 3.33, *c*. (Values of  $\sigma_E$  in the outer fibers of the beam are defined by the condition that the absolute values of the moment  $M$  and  $M'$  are equal.) Residual stresses in the beam (Fig. 3.33, *d*) will be equal to the algebraic sum of the stresses due to plastic bending (Fig. 3.33, *b*) and elastic stresses due to unloading (Fig. 3.33, *c*).




Fig. 3.33 Scheme of a beam straightening (a) and stress distribution: during its plastic bending (b), unloading (c) and residual stresses (d)

The maximum elastic stresses in the beam during the unloading is equal to  $1.5\sigma_T$  (Fig. 3.33, c). Of course, there is no such stresses in the beam, since immediately after the unloading the formation of residual stresses begins. Nevertheless the described analysis of elastic-plastic deformation of a beam helps to calculate residual stresses and is widely used in engineering practice.

As can be seen from Fig. 3.33, d, significant residual stresses arise due to straightening, the value of the stresses in the outer fibers is  $0.5\sigma_T$ . The diagram of the residual stresses is balanced, i.e. the resultants of the forces and moments are zero.

If the beam is now subjected to, for example, one-sided machining, the equilibrium of residual stresses will be disturbed and the beam will warp after unclamping, i.e. acquire form error.

To define to which deformations this warping will lead, let's consider a numerical example.

Let the sizes of a beam subjected to straightening are as follows: length  $L=500$  mm; width  $b=40$  mm; height  $h=20$  mm. Material: steel with  $\sigma_T=400$  MPa and Young's modulus of  $E = 2 \cdot 10^5$  MPa. Let's assume that the

beam is straight after the straightening. The diagram of residual stresses in the beam after the straightening is as shown in Fig. 3.33, *d*. Assume that the upper surface of the beam is face milled and allowance  $Z=1$  mm is removed (Figure 3.34, *a*). For simplicity, assume that the tensile residual stresses are constant both within the allowance and within the beam length and are  $\sigma_{res}=0.5\sigma_T=200$  MPa. The removal of allowance is equivalent to application to the beam with height  $h_1$  of a moment  $M$  (Fig. 3.34, *b*), the value of which is

$$M = \sigma_{res} b Z \frac{h_1}{2} = 200 \cdot 40 \cdot 1 \cdot \frac{19}{2} = 76000 \text{ (N}\cdot\text{mm)}.$$

Deflection of the beam subjected to pure bending is defined as

$$f = \frac{ML^2}{8EI}$$

where  $I = \frac{bh_1^3}{12}$  is the second moment of area of the beam.

For the given example we obtain

$$I = \frac{40(19)^3}{12} = 22863 \text{ (mm}^4\text{)};$$

$$f = \frac{76000(500)^2}{8 \cdot 2 \cdot 10^5 \cdot 22863} = 0.52 \text{ (mm)}.$$

Thus, it can be seen that the deformation of the beam as a result of removal of even a relatively small allowance is very significant.




Fig. 3.34 Scheme of face milling of a beam after straightening (*a*) and its deflection after unclamping (*b*)

In general case, in machining the deformation of workpieces may be caused either by the redistribution of the available residual stresses and due to the residual stresses caused by the cutting process. In this case, the pattern of formation of machining error due to residual stresses is much more complicated.

Obviously, to reduce machining errors caused by action of the residual stresses, it is necessary to reduce these stresses as during the production of workpieces, as well as during the subsequent machining.

The radical method of suppressing residual stresses is a workpiece annealing, which practically eliminates these stresses. If it is necessary to prevent oxidation of workpieces, annealing is performed in vacuum or in a neutral medium. In manufacture of precision parts, annealing can be performed more than once – it alternates with the cutting operations. The removal of residual stresses by annealing is explained by the fact that the yield strength of the metal at high temperatures rapidly decreases. Thus the plastic flow begins and residual stresses are reduced to the yield point.

To reduce residual stresses in large castings due to the lack of furnaces of large size the natural aging is used. It consists in the long-term storage (aging) of workpieces in the air. The duration of aging often ranges from 6 to 12 months. It is found that natural aging of gray iron castings reduces residual stresses in average by only 5...20%, but concentration of residual stress at graphite inclusions sharply decreases and spontaneous castings deformation over time substantially stops.

Castings of machine tool beds, in particular, are subjected to the natural aging. Before the natural aging, the roughing operation is performed. In rough machining, relatively large allowances are removed from the bed and thereafter considerable bed deformation may occur due to residual stresses redistribution. During finishing of the bed, which is performed after the natural aging, much smaller allowances compared to roughing are removed. Deformation of the beds due to redistribution of residual stresses, which in natural aging also slightly decrease, is slight, which ensures high precision of the machine beds.

In addition to annealing and natural aging, vibratory stress relief (VSR) is used to reduce residual stresses in castings. It is carried out at special stands or with portable vibrators fixed on the castings.

During the VSR of cast iron castings, the processes similar to those that occur during the natural aging take place. The VSR, which is much faster than natural aging, mainly reduces concentration of residual stresses at the graphite inclusions, which ensures stabilization of sizes, form and location of the casting surfaces. However, the VSR should be applied with care, since in case of large residual stresses it may lead to cracking and fracture of castings.

To reduce residual stresses in steel workpieces after hardening, their subsequent tempering is used. In some cases, tempering of low-rigid workpieces, such as plates, discs, etc. is performed in a predeformed state that helps to reduce deformation of the workpieces caused by hardening.

Residual stresses in workpieces of simple shape can be eliminated by uniform plastic deformation, the value of which is less than 1...2 %. For example, residual stresses in rods are eliminated by plastic stretching, stresses in thin-walled bushings – by plastic expansion with the help of special expandable mandrels.

The reduction of residual stresses and deformations formed during machining can be achieved by optimization of parameters and conditions of cutting.

### **3.2.1.6 Error of Sizing Tool Manufacturing and Error of Theoretical Machining Scheme**

**Error of manufacturing of sizing tools.** Machining errors are caused by errors of sizing cutting tools manufacturing. Such tools include: threading cutters, grooving cutters and form cutters, taps, threading dies, drills, core drills, reamers, broaches, slot and form milling cutters, form grinding wheels, etc.

For example, diameter of a twist drill, measured near the top of the drill body, is machined relatively to the drill accuracy class with tolerance zones  $h8$  and  $h9$ . It is clear that the range of dispersion of diameters of the holes drilled in a lot of workpieces can't be less than this tolerance.

Twist drills diameter is usually reduces toward the shank (back taper) by 0.02...0.08 mm per 100 mm of length. Therefore, when a drill is reground, its diameter decreases, leading to increase in the range of dispersion of the drilled holes diameters.

Deviations from symmetry of the drill web relatively to the axis of the drill, radial run-out of margins and run-out of cutting edges relatively to the drill axis lead to unbalanced radial force during the process of drilling and thus, hole oversizing, as well as hole axis deflection. The hole oversizing and axis deflection is different for different drills of a type.

Thus, a number of errors of the twist drills manufacture, directly or indirectly affects the accuracy of drilled holes.

To reduce the errors of this type it is necessary to improve manufacturing accuracy of the sizing cutting tools, as well as to raise the accuracy of resharpening. Along with this, machining errors can also be reduced with the help of technological methods.

For example, a significant reduction of hole oversizing and axis deflection during the drilling of holes with twist drills can be achieved through the use of

drill bushings. Another method to reduce hole oversizing and axis deflection is predrilling with rigid center drills.




Fig. 3.35 Diagrams for milling the keyways by pendulum (a) and planetary (b) methods

Fig. 3.35, *a* shows milling of a keyway with an endmill by the so-called pendulum method (the axial plunge of an endmill for the each longitudinal pass is 0.1...0.3 mm). With this method of milling, the error of the cutter diameter, which tolerance is  $e_8$ , is entirely transferred to the error of the slot width. This error can be significantly reduced by means of milling the keyway slot by so-called framework method (Figure 3.35, *b*), when the opposite sides of the slot are milled separately.

**Error of theoretical scheme of machining.** This kind of machining error takes place due to simplification of either machining kinematics or profile of a form tools. Such errors, for example, occur when gears are cut with involute milling cutters (Fig. 3.36). Theoretically, milling cutter profile must be designed for the each number of teeth of a given module. However, to cut gears of a given module  $m$ , sets of cutters, consisting of 8 (for  $m \leq 8$  mm) and 15 (for  $m > 8$  mm) cutters are used. Thus, in practice, gears with teeth numbers of a certain range are cut by a single cutter, which leads to some error of tooth profile.




Fig. 3.36 Gear milling by an involute milling cutter:  
1 – milling cutter; 2 – workpiece

### 3.2.1.7 Error of Workpiece Mounting

By the *mounting error*, the deviation of the workpiece position on the machine from the required position is meant. For example, it is desired for the shaft workpiece clamped on a lathe to have its axis concentric with the axis of the spindle. In fact, there is always one or another deviation of workpiece location from the required, which is directly or indirectly transferred to the error of machining.

Mounting error is a sum of locating error, clamping error and error of the fixture used.

**Locating error.** *Locating error* is the deviation of the actual position of a workpiece achieved by locating from the required position. This error can be regarded as a departure of the manufacturing datums from the locating elements of the fixture during the process of locating. This error is defined as the maximum possible for the batch of workpieces.

Let's consider examples of workpiece set-ups in which locating errors take place.

Fig. 3.37 shows set-up of a housing. Manufacturing datums of the housing include lower plane and two holes perpendicular to the plane. The holes are usually machined with an accuracy of not less than *IT7*. The housing is installed by its left hole on a cylindrical pin, and by the right hole – on the diamond (relieved) pin. Note that such scheme, due to its simplicity, is widely used in practice.




Fig. 3.37 Housing located with a plane and two holes

Because of the clearance between the pins and the holes *I* and *II* the deviation of the left hole axis from the axis of the cylindrical pin may appear, which value is calculated as

$$e = \frac{S_g}{2} + \frac{Td_0}{2} = \frac{Td_p}{2},$$

where  $S_g$  is the guaranteed clearance between the pin and the hole;  $Td_0$ ,  $Td_p$  are the diametric tolerances of the hole *I* and the cylindrical pin, respectively. Twice the value of  $e$  is the error of the housing locating in the direction of axes  $X$  ( $\varepsilon_{lx}$ ) and  $Y$  ( $\varepsilon_{ly}$ ), i.e.

$$\varepsilon_{lx} = \varepsilon_{ly} = 2e = S_g + Td_0 + Td_p.$$

In addition to the locating errors  $\varepsilon_{lx}$  and  $\varepsilon_{ly}$  of this scheme, deflection of the housing in the  $XOY$  plane is possible (Fig. 3.38). The tilt angle  $\alpha$  is calculated as

$$\operatorname{tg}\alpha = \frac{S_{1\max} + S_{2\max}}{2A_0},$$

where  $S_{1\max}$ ,  $S_{2\max}$  are the maximum clearances in couplings of the cylindrical and the diamond pins with the holes *I* and *II*, respectively;  $A_0$  is the distance between the holes. Locating error in the direction of the  $Z$  axis is equal to zero.






Fig. 3.38 Graphic representation of tilting of the housing located with a plane and two holes

Obviously, during the boring of the hole *III* of the housing on the machine tool with a cutting tool set at the constant position relative to the axis of the cylindrical pin, it is impossible to obtain the size *A* (refer to Fig. 3.37) with an error lesser than the error  $\epsilon_{lx}$ . Deviation from parallelism of the hole axis relative to the, for example, side surfaces *IV* and *V* machined on the previous operation cannot be less than the tilt deviation that arise during locating. The housing locating error has no direct effect on the accuracy of the hole *III* diameter, however, it leads to uneven allowance and form error of the hole. Thus, the locating error leads to errors of size, form and location of the machined surfaces.

Errors of housing locating can be avoided or at least reduced, by the use of spring-loaded conical pins (Fig. 3.39, *a*) or elastical pins (Fig. 3.39, *b*) instead of the rigid pins.




Fig. 3.39 Workpiece mounted on a spring-loaded pin (*a*) and elastic pin (*b*)

Fig. 3.40 shows a graphic representation of a bushing mounted on a cylindrical mandrel (with clearance) for subsequent machining of external surface. The maximum possible eccentricity of the mandrel axis with respect to the axis of the hole, for a batch of workpieces, represents the locating error of a bushing in radial direction  $\epsilon_{\delta r}$ . The locating error of a bushing in axial direction is equal to zero.




Fig. 3.40 Mounting of a bushing on a solid cylindrical mandrel

It is quite obvious that the given scheme can't provide radial run-out of the outer surface of the bushing relative to the surface of the hole lesser than  $2\varepsilon_{\delta r}$ . The accuracy of the outer surface diameter is not influenced by the locating error  $\varepsilon_{\delta r}$  directly, but this locating error can cause errors of form of the surface.

The locating error  $\varepsilon_{\delta r}$  can be eliminated as follows:

- use of a mandrel with small taper;
- use of an expandable mandrel;
- mounting on a solid cylindrical mandrel with a guaranteed interference.

The examined example shows that the selection of a scheme of workpiece locating must be in the first place guided by the requirement to ensure accurate location of workpiece surfaces, and then – by the requirement to ensure the specified sizes.

**Clamping error.** Clamping of a workpiece can more or less disturb the position reached by locating – that is an *error of clamping*. This error can be regarded as a departure of the manufacturing datums from the locating elements of the fixture during the process of clamping. This error is defined as the maximum possible for the batch of workpieces.

The reasons of the clamping error formation are as follows:

- contact deformation in the joints of manufacturing datums with locating elements of the fixture;
- errors of form of manufacturing datums and surfaces of the workpiece which interact with the clamping elements of the fixture;
- variability and non-simultaneous application of the clamping forces.

Fig. 3.41 shows a graphic representation of a housing clamping. During the clamping, contact deformation of the joint "bottom plane of the housing – locating pins" occurs and the housing shifts down by the value  $\Delta_z$ . During machining (clamping) of a batch of parts, the value  $\Delta_z$  is variable due to fluctuations in roughness and waviness of the lower surface and the forces of clamping. The difference between the maximum and minimum values of  $\Delta_z$  represents error of the housing clamping in the vertical direction  $\varepsilon_{3z}$ . It should be

noted that this error has the same effect on the machining accuracy as the locating error.




Fig. 3.41 Diagram of a housing clamping.  
 $P_3$  – clamping force

Fig. 3.42 shows diagrams of a shaft clamped in a three-jaw self-centering chuck. Due to conicity of the workpiece (Fig. 3.42, *a*), the axial force  $P_o$  arises during the clamping, and shifts the workpiece by the value  $\Delta_o$ . This displacement during the machining (clamping) of a batch of parts can vary from zero to some maximum value, which is considered as an error of clamping in the axial direction  $\epsilon_{30} = \Delta_{o \max}$ .

Since cylindrical surface of a workpiece generally has errors of form both in axial and transverse direction, process of clamping can generate a system of forces that will cause axial displacement of the workpiece as well as its skewing relatively to the chuck. Thus the clamping errors in axial ( $\epsilon_{30}$ ) and radial ( $\epsilon_{3r}$ ) directions arise (Fig. 3.42, *b*).




Fig. 3.42 Clamping of a shaft in a three-jaw chuck: *a* – the outer cylindrical surface of the shaft is tapered; *b* – cylindrical surface has errors of form in axial and radial directions

It is obvious that during facing of the shaft on the pre-set machine (when a cutter is in constant position relative to the bored shoulder in the jaws), the error of the dimension from the left-hand end (manufacturing datum) to the faced end can't be less than the error  $\epsilon_{30}$ . The clamping error  $\epsilon_{3r}$  has no direct influence on the accuracy of the workpiece diameter. However, this error re-




Fig. 3.43 Diagram of displacements and deformations of a prismatic workpiece during clamping

sults in uneven machining allowance for turning and may cause errors of form of the machined surface.

Along with the workpiece displacement and skewing during the clamping, the deformation of the workpiece also takes place, and this deformation also is an error of clamping. These deformations are closely related to the errors of form of the manufacturing datums of the workpiece.

Fig. 3.43 shows clamping of a prismatic workpiece with the help of clamps.

Face milling of the upper surface of the workpiece is performed. Workpiece lower surface, which is a plane datum, and surface of the workpiece shoulders, which interact with the clamps, have errors of form. The position of the workpiece after locating is shown in Fig. 3.43, *a* (point *A* belongs to the workpiece). Let's assume that the clamps are applied non-simultaneously. Firstly the right clamp acts. Under the force  $P'_3$  the workpiece turns about point *A*. At the same time, this force (its component  $P_x$ ) shifts the workpiece to the right by the  $\epsilon_{3x}$  to the position shown in Fig. 3.43, *b*. Under the force  $P'_3$  of the left clamp, the workpiece, under certain conditions, would be elastically deformed by  $\epsilon_{3z}$ . Clamped and machined workpiece is shown in Fig. 3.43, *c*. After releasing the workpiece, the bottom surface of the workpiece will take its initial form due to elastic forces. The

upper surface of the workpiece will acquire corresponding form error  $\Delta_\phi$  (Figure 3.43, *d*).

It is obvious that in the given example, the workpiece deformation can be drastically reduced by applying clamping forces perpendicular rather than parallel to the plane  $XOZ$ .

Assuming all said above, we can state that reduction of clamping error can be achieved by:

- ensuring accuracy and surface layer quality of the manufacturing datums;
- providing rational direction and points of application of clamping forces;
- controlling the values of clamping forces through the use of mechanized drives for fixtures.

**Error of a fixture.** The fixture error  $\varepsilon_f$  is due to inaccuracies of fixture manufacture and location on a machine tool, as well as uneven wear of the locating elements from the repeated interactions with the workpieces.

For example, a commonly used self-centering three-jaw chucks every time it is mounted on the machine spindle will take different positions with respect to the clearance between the centering necks of a spindle and chuck bore. As a result, the workpiece mounted in the chuck is eccentric relative to the spindle axis. Clearance between chuck jaws and guides will deflect the jaws during the clamping, leading to skewing of the workpiece relative to the machine tool spindle. Mounting surfaces of the jaws are also subjected to wear in the course of the work. This wear of the different jaws can be uneven. This wear may also be accompanied by the formation of form errors for the surfaces. All this increases the error of workpiece locating.


To reduce fixture error it is needed to:

- improve accuracy of fixtures and accuracy of their mounting on a machine;
- use fixtures with a minimum number of movable interfaces;
- perform machining of the mounting surfaces of a fixture directly on the machine, for which the fixture is intended.

For example, the error of a sleeve mounting on an internal grinding machine can be drastically reduced, if a diaphragm-operated chuck is used instead of a three-jaw chuck.

The simplest diaphragm-operated chuck (Figure 3.44) consists of a faceplate *1*, diaphragm *2* with a lot of jaws *3* and push rod *4*. Under the action of the push-rod upon the diaphragm, the latter deflects, the jaws opens and machined sleeve *5* is removed from the chuck (Fig. 3.44, *a*). Then the next sleeve is mounted, the push-rod is moved to the left and under the action of the elastic

forces the diaphragm returns to its initial shape, closing the jaws and clamping the sleeve (Fig. 3.44, *b*).



*Fig. 3.44 Diaphragm-operated chuck:  
a – jaws are opened; b – jaws are closed*

After a diaphragm-operated chuck is mounted on the machine, the jaws surfaces are ground. This helps to virtually eliminate the influence of chuck mounting error and jaws wear on the accuracy of the workpiece mounting.

The same is true in other cases. The self-centering three-jaw chucks are equipped with "soft" jaws that are bored directly on the lathe. After installing an electromagnetic chuck on a surface grinder, the mounting plane of the chuck is mandatory ground on the machine. The same is done in case the mounting surface of the chuck is worn.

**Determination of mounting error.** Error of workpiece mounting  $\varepsilon_y$  (in a given direction) is found as the sum of its components. Considering  $\varepsilon_l$ ,  $\varepsilon_3$ ,  $\varepsilon_f$  as ranges of dispersion of random variables with normal distribution, we obtain

$$\varepsilon_y = \sqrt{\varepsilon_l^2 + \varepsilon_3^2 + \varepsilon_f^2}.$$

The locating error ( $\varepsilon_l$ ) is determined by geometrical calculation. Clamping error ( $\varepsilon_3$ ) and fixture error ( $\varepsilon_f$ ) are found in reference books. Since it is difficult to separate these components of the mounting error, usually handbooks specify only the value of the clamping error that includes error of a corresponding fixture. Thus

$$\varepsilon_y = \sqrt{\varepsilon_l^2 + \varepsilon_3^2}.$$

When workpieces are mounted in centers, self-centering chucks, on expandable mandrels etc. locating and clamping of the workpieces is carried out simultaneously, so it is difficult to separate them from each other. It is assumed

that in these cases the locating error in the radial direction is zero. Thus  $\varepsilon_y = \varepsilon_3$ .

**Mounting of workpieces with alignment.** Along with the mounting of workpieces without their alignment discussed above, the mounting with alignment of the position of each workpiece with respect to the layout lines or directly to the surface of the workpiece is widely used in job production and small-batch production. Fig. 3.45 shows a schematic diagram of alignment of the sleeve position on the internal grinding machine. To ensure tight tolerance of run-out of the ground hole 1 with respect to the previously ground hole 2, proceed as follows. With the help of shims 3 and repeated clamping-unclamping of the sleeve the permissible radial run-out of the hole 2 with respect to the axis of the spindle is achieved. This run-out is measured in two sections of the hole 2 using a dial indicator. After alignment is performed, the hole 1 is ground.




Fig. 3.45 Scheme of a sleeve position alignment

The error of mounting with alignment is equal to the error of the alignment. For example, if after sleeve alignment the run-out of the hole 2 with respect to the spindle axis is up to 0.01 mm, then the mounting error in radial direction is  $\varepsilon_y=0.005$  mm. The  $\varepsilon_y$  includes both clamping error and fixture error.


It should be noted that the alignment helps to ensure high accuracy of workpiece set-up, but is very time consuming. Therefore, even in conditions of batch production the mounting with alignment is avoided. However, in some cases, the alignment process is automated and is effectively used in large-batch production for mounting complex-shaped workpieces.

### 3.2.1.8 Error of Manufacturing System Setting

*Dimensional setting* of a manufacturing system involves setting of the cutting edges of a tool in the required position relative to the manufacturing

datums of the workpieces. The task of dimensional setting is to ensure size of the workpiece within a specified tolerance zone.

The basic method of dimensional setting is the method of trial cuts, the essence of which is as follows (Figure 3.46). The cutting tool is fed to the workpiece mounted on the machine tool, and is set into the position at which the risk of a defective workpiece is reduced to zero; afterwards a small area of the workpiece surface is machined. After that, the machine is stopped, the obtained size is measured, and its deviation from the required value (for example, size from the part drawing) is determined and position of the tool is adjusted. Then a trial cut is repeated, the obtained size is measured and, if necessary, a new adjustment to the position of the tool is made. Thus the size within the specified tolerance zone is ensured by trial cuts. Afterwards the workpiece is machined on the entire length. These trial cuts are executed for machining of each surface of the workpiece. The whole process is repeated with each subsequent workpiece.




*Fig. 3.46 Graphic representation of dimensional setting through the trial cuts:  $l_1, l_2$ —distances of steady cutting process for the first and second cuts, respectively*

To make the cutting process steady, the cutting distance at each subsequent trial cut should be slightly longer than in the previous one (Fig. 3.46). If the length of the workpiece is small, the trial cuts are performed over the entire length.

It must be emphasized that during the method of trial cuts, the cutting tool is set to different positions before machining different workpieces with respect to the manufacturing datums. For example, in turning of the outer surface (Fig. 3.46), the higher is the hardness of the workpiece and the higher is the allowance the closer is the cutter to the axis of the workpiece before the cutting. Due to this, the machining errors caused by elastic deformations of the technological system due to cutting forces are largely reduced. Obviously, with the trial-cuts method, the errors of machining due to tool wear may also be sub-



stantially reduced. Thus, the method described above provides high accuracy of machining, but is very time consuming. That is why this method is used mainly for job production and small-batch production.



*Fig. 3.47 Cylindrical grinding with in-process gauging:  
1 – workpiece; 2 – grinding wheel; 3 – in-process gauge*

In batch production, the method of trial cuts is effectively used for grinding and honing operations, in this case machine tools are equipped with active control gauges. Fig. 3.47 shows a diagram of cylindrical grinding with continuous in-process measurement of the actual size of the workpiece. When the actual size is close to the desired value, the device firstly issues a command to stop the radial feed, i.e. start the process of sparking-out, and then, when the actual size is within the tolerance it issues a command for the grinding wheel withdrawal. Almost all CNC grinding machines are equipped with in-process gauges. Moreover, these devices are made wide-range and programmable, which allows one device to measure different sizes.

In batch and mass production, dimensional setting is made for a batch of parts. Cutting tool is set in the constant position relative to the locating elements of the fixture, and a batch of workpieces is machined before the fixture readjustment. This type of machining is called "machining on pre-set machines". Fig. 3.48 shows endmilling of a shoulder, carried out by an end mill on a vertical milling machine. The milling cutter, with the help of trial-cuts, is given a constant position relative to the fixed jaw 1 and base 2 of the vice and workpiece manufacturing datums, which provide ensuring of manufacturing dimensions  $A_1$  and  $A_2$  within the specified tolerances zones. Actions of an operator are reduced to the installation and removal of workpieces, switching on and off the table feed and periodic inspection of the  $A_1$  and  $A_2$  dimensions, which are obtained automatically.




Fig. 3.48 The scheme milling blanks on a vertical milling machine

When value of  $A_1$  and (or)  $A_2$  approaches to the limits of tolerance zones, which in most cases is due to tool wear, readjustment of the manufacturing system is made.

For dimensional setting of a manufacturing, a setting size (desired size of the workpiece) is used. *Setting size* (see Fig. 3.46) is the size of the workpiece which should be obtained during the setting.

In a trial-cuts method the average size  $A_{av}$  of the workpiece is normally used as the setting size  $A_H$ , i.e.

$$A_H = A_{av} = \frac{A_{nu} + A_{nl}}{2},$$

where  $A_{nu}$  and  $A_{nl}$  are, respectively, the maximum and minimum limits of the manufacturing dimension which is obtained on the given processing step (operation). Actual values of the manufacturing dimension are always in some degree deviate from  $A_H$ . The largest deviation of the actual manufacturing dimension  $A_H$  of a batch of parts, measured on the surface of trial cuts, can be considered as an error of setting. This error  $\Delta_H$  is a sum of error  $\Delta_{ad}$  of adjustment of the cutting tool position (with the help of the handwheel dial or limb) and error  $\Delta_{meas}$  of the workpiece measurement. Considering that the distribution of errors of measurement and adjustment is normal, the error of setting with trial-cuts method is calculated as follows

$$\Delta_H = \sqrt{\Delta_{ad}^2 + \Delta_{meas}^2}.$$

The error  $\Delta_{ad}$  is determined by the scale interval of the machine dial, the error of the measurement  $\Delta_{meas}$  depends on the type of the measuring instrument. Values of these errors are given in handbooks.

During the manufacturing system setting for machining of a batch of parts, the setting size  $A_H$  should be of such value so that it is possible to machine the greatest possible number of workpieces before the readjustment. To determine the  $A_H$  that meets this requirement a scatter diagram is needed. This diagram is used to assess random and systematic errors of machining depending on the time  $t$  and number of the machined workpieces  $n$ . However, a scatter diagram can be obtained only on the basis of measurements of the dimensions of workpieces in the previous period of work. There is no scatter diagram at the time of the first setting. Thus, the dimensional setting for machining of a batch of workpieces should be carried out in two stages, as shown in Fig. 3.49 for machining of “shaft” sizes.

During the first stage, to avoid reject, the setting is performed by trial-cuts method with the average manufacturing dimension  $A$  used as a setting size  $A'_H$ . With this setting a batch of workpieces is machined and sizes of the machined workpieces are measured. Thus, a scatter diagram of machining results is built. The systematic errors due to tool wear are determined by the tangent of the angle of inclination of  $\bar{A}'_t = f(t)$  to the abscissa axis, where  $\bar{A}'_t$  is the current average size of the workpieces. Random errors are characterized by the range of size dispersion, the limits of which are shown by the lines parallel to the line  $\bar{A}'_t = f(t)$ . Parameters of the function  $\bar{A}'_t = f(t)$  are found by the least square method. The current value of the standard deviation of the machined sizes is calculated for the group (*I, II, III ...*) of sequentially machined workpieces. The number of workpieces in a group  $n_{gr}$  is usually equal to 5. Since standard deviations of workpieces of different groups are somewhat different from each other, the deviation that is maximum is selected. Considering that the size distribution within the range of dispersion is normal,

$$\omega_t = 6\sigma_{t_{max}}.$$




Fig. 3.49 The scheme of dimensional configuration for processing batch of blanks

During the second stage of setting, to get the greatest possible number of accepted workpieces without readjustment, the range of size dispersion  $\omega_t$  is shifted to the lower limit of the tolerance zone of the manufacturing size  $A$ . (Tangents of angles of  $\bar{A}'_t = f(t)$  and  $\bar{A}_t = f(t)$  are considered equal.) The  $A_{nl} + 3\sigma_{t \max}$  is taken as the setting size  $A_H$ . The method of trial cuts is used to set the manufacturing system to this size. Then several workpieces are machined and measured, and if the average value of the actual sizes  $\bar{A}_{ta}$  is close to the  $A_n = A_{nl} + 3\sigma_{t \max}$ , then the machining of batch of workpieces is performed. Otherwise a correction in position of the cutting tool is made.

Similarly, the dimensional setting for machining of “hole”-sizes of parts of a batch is made. In this case, the setting size of the second stage will be

$$A_n = A_{nu} - 3\sigma_{t \max}.$$

Error of setting  $\Delta_H$  for machining of a batch of workpieces can be considered as a deviation of  $\bar{A}_{ta}$  from  $A_H$ . This error is defined by the formula

$$\Delta_H = \sqrt{\Delta_{ad}^2 + \Delta_{meas}^2 + \Delta_{calc}^2},$$

where  $\Delta_{calc}$  is the error of  $\bar{A}_{ta}$  calculation due to limited number of workpieces in the group  $n_{gr}$ . The error  $\Delta_{calc}$  is found on the relations of mathematical statistics. For example, if  $n_{gr}=5$  and  $\sigma_{\max}=0.02$  mm, with a probability of 0.9 the  $\Delta_{calc}$  will be equal to 0.02 mm.

Taking into account the error of setting, the equations for calculation of the setting size for machining “shaft”-sizes and “hole”-sizes, respectively, will be

$$A_n = A_{nl} + 3\sigma_{t\max} + \Delta_H;$$

$$A_n = A_{nu} - 3\sigma_{t\max} - \Delta_H.$$


Dimensional setting of the manufacturing system, especially during multiple-tool machining, is rather time-consuming. To simplify this setting, the setting with the help of an etalon is used; this etalon is an analogue of the machined workpiece.

The etalon is set on the idle machine instead of a workpiece, then slides are moved to the position corresponding to the end of the pass. The cutting tools are installed and secured in holders so that their cutting edges touch the corresponding surfaces of the etalon. Further the etalon is removed from the machine and a workpiece is mounted.

The etalon is made with high accuracy (its surfaces are ground). Sizes of an etalon are a little bit different from the sizes of a workpiece to be machined. For example, diameter  $D_{et}$  of the etalon (Fig. 3.50), intended for setting for machining of shafts, is less than the workpiece diameter by the value of correction  $C$ . This correction includes elastic deflection of a cutting tool and a workpiece  $\Delta_e$  and roughness of the machined surface  $R_z$ , all this increase diameter of the workpiece compare to the etalon diameter. It is clear that for machining of holes the impact of  $\Delta_e$  and  $R_z$  on the diameter will be opposite and the sign of the correction will be positive. Thus, for machining of “shafts” and “holes” the etalon diameter, respectively, is calculated as follows:

$$D_{et} = D_{work} - C = D_{work} - 2(\Delta_y + Rz);$$

$$D_{et} = D_{work} + C = D_{work} + 2(\Delta_y + Rz).$$




*Fig. 3.50 Relationship between diameters of an etalon and a workpiece*

During the process of setting with an etalon, it is important to precisely define the moment of a cutter touching the corresponding surface of the etalon.

For this purpose a thin paper is placed and is constantly displaced between the etalon and a cutting tool. When the paper is jammed by a tool, then it is considered that the tool has touched the etalon surface.

The error of setting with an etalon depends on a number of components: error of etalon manufacture, error of mounting on a machine tool, error of touching determination, etc. In general, this method of setting has a significant error, which is 0.05...0.1 mm.

In some cases a previously machined part is taken as an etalon. In this case, correction to the position of the cutting tools set by an etalon is to be made with respect to the results of machining of the first workpieces.



*Fig. 3.51 The scheme of interchangeable setting:  
a – position of a cutting tool on a machine; b – setting of a tool length off-the-machine. 1 – adjusting screw; 2 – lock nut; 3 – measuring head*

To reduce time needed for readjustment of manufacturing systems in batch and mass production, the interchangeable tools are used. Fig. 3.51 shows a graphical representation of the so-called interchangeable setting. The required length of the tool  $L_p$  (Fig. 3.51, a) is initially defined by the trial-cuts method. When the cutter is worn, it is replaced by a new one. The length of the new cutter  $L_p$  is adjusted off-the-machine with the help of the screw 1 and locknut 2 (Fig. 3.51, b).

In some cases, the entire removable slides with clamped multiple tools (also set off-the-machine) are made interchangeable. This significantly reduces machine downtime related to the dimensional setting.

### 3.2.1.9 Determination of Total Machining Error of Processing Step

During the design of manufacturing processes, the total machining error is of major interest.

In the simplest case, the total error of the size of workpieces machined on a pre-set machine is found as an algebraic summation of the individual errors:

$$\Delta = \varepsilon_y + \Delta_H + \Delta_e + \Delta_w + \Delta_t + \sum \Delta_f, \quad (3.6)$$

where  $\varepsilon_y$  is the error of workpiece mounting;  $\Delta_H$  is the error of manufacturing system setting;  $\Delta_e$  is the error due to elastic deformation of the system under cutting forces;  $\Delta_w$  is the error due to tool wear;  $\Delta_t$  is the error due to temperature deformations of the manufacturing system.

The first five components in Equation (3.6) are the ranges of dispersion of the corresponding individual errors and reflect their effect on the dispersion of workpieces size. The sixth component  $\sum \Delta_f$  reflects the influence of the geometric errors of the machine tool, workpiece deformation due to clamping forces and elastic deformations of the manufacturing system due to cutting forces on the error of form of the workpiece machined surface.

The error  $\sum \Delta_f$  must be found for the workpieces cross-sections, in which the rigidity of the technological system is minimal. For example, for turning of a workpiece clamped at one side the  $\Delta_e$  value should be determined at its right end.

Total error of the diametrical size should be determined with the mounting error  $\varepsilon_y$  excluded, since, as shown above, this error has no direct effect on the error of these dimensions. For this reason,  $\varepsilon_y$  should be excluded from the total error of the size that connects two opposite elements of a workpiece that is simultaneously machined by a set of cutting tools.

The error  $\sum \Delta_f$  must be found with respect to the mutual compensation of its individual components. For example, in turning of a shaft clamped at one side, its diameter at the right end is larger than that near the chuck due to deflection under the cutting forces (see Fig. 3.25, *a*). At the same time, if the spindle axis is not parallel to the guideways in the horizontal plane, the machined surface of the workpiece will be tapered (see Fig. 3.21, *a*). If the vertex of the cone faces the tailstock, then the form errors are partially or fully compensated. If reversed, the form errors are summed together.

The calculation of the total error of a size by Equation (3.6) is quite simple. However, values of  $\Delta$  are considerably high.

The total error of a size can be estimated more precise, if the probabilistic nature of individual errors is considered. The first five terms in Equation (3.6) are random errors (value). The term  $\sum \Delta_f$  is a constant systematic error. Distributions of  $\varepsilon_y$ ,  $\Delta_H$  and  $\Delta_e$  to a high accuracy can be considered normal, and distributions of  $\Delta_w$  and  $\Delta_t$  – can be considered as distributions of equal probability. Then [in analogy with Equation (2.22)] the total error of machining can be written as

$$\Delta = t_{\Delta} \sqrt{\lambda_1^2 (\varepsilon_y^2 + \Delta_H^2 + \Delta_e^2) + \lambda_2^2 (\Delta_w^2 + \Delta_t^2)} + \sum \Delta_f . \quad (3.7)$$

Usually  $t_{\Delta}$  is taken equal to 3. For normal distribution the coefficient  $\lambda_1^2 = \frac{1}{9}$ ; for distribution of equal probability  $\lambda_2^2 = \frac{1}{3}$ . With this Equation (4.7) takes form

$$\Delta = \sqrt{\varepsilon_y^2 + \Delta_H^2 + \Delta_e^2 + 3\Delta_w^2 + 3\Delta_t^2} + \sum \Delta_f . \quad (3.8)$$

For diameters

$$\Delta = \sqrt{\Delta_H^2 + \Delta_e^2 + 3\Delta_w^2 + 3\Delta_t^2} + \sum \Delta_f . \quad (3.9)$$

Equations (3.8-3.9) are the most common. The main advantage of these equations is that with the elementary errors given, the expected accuracy of a size can be calculated. This allows engineers to compare different versions of the manufacturing process and to select the most appropriate one at the early stages of manufacturing process design. In addition, it is important for the development of new manufacturing processes, for example, when there is a task to establish the causes of unacceptably low accuracy of machining and find the ways to improve it.

However, it should be borne in mind that the calculation of the total error of workpieces machining in a number of cases is difficult in the absence of reliable initial data (e.g., data on the dimensional wear of cutting tools, the rigidity of elements of technological systems, etc.), as well as the lack of methods for calculating the individual elementary errors, such as errors due to thermal deformation of a machine tool, for example. Therefore, in addition to the calculation of the machining error, the tables of data on machining accuracy are widely used in mechanical engineering. These tables are obtained by statistical studies of machining accuracy in production conditions.

### 3.2.2 Ensuring Accuracy During Manufacturing Process

As noted, the workpiece cannot be machined entirely at one processing step. To do this, a number of processing steps or operations, which together form a manufacturing process, is required. As this manufacturing process is



executed, the workpiece becomes closer to the shape of the finished part, and after the last operation the workpiece turns into the part.

The process of converting the initial workpiece into a part may be performed by various methods and means of manufacturing. For example, cutting, EDM and electrochemical machining can be used to ensure the desired size and shape of the part.

In establishing the relations between the parameters of accuracy of the workpiece, which are obtained in the course of the manufacturing process, the concept *refinement* is used. This concept reflects the relationship between accuracy (error) of machining before and after the operation (processing step) or the whole manufacturing process.

By the actual refinement  $\varepsilon_a$  of the manufacturing process the relation of the initial workpiece error  $\Delta_{\text{workin}}$  to the error of the part  $\Delta_p$  on the given parameter (size, shape, location of surfaces) is meant:

$$\varepsilon_a = \Delta_{\text{workin}} / \Delta_p$$

After each processing step (operation), errors of the workpiece decrease in accordance with the value

$$\varepsilon_{a_i} = \frac{\Delta_{\text{work}_{i-1}}}{\Delta_{\text{work}_i}},$$

where  $\Delta_{\text{work}_{i-1}}$ ,  $\Delta_{\text{work}_i}$  are respectively errors before and after the  $i^{\text{th}}$  processing step.

Obviously, after the  $m$  processing steps of the manufacturing process, the refinement

$$\varepsilon_a = \varepsilon_{a1} \varepsilon_{a2} \dots \varepsilon_{am} = \prod_{i=1}^m \varepsilon_{a_i}.$$

To ensure a particular parameter of accuracy during the production of parts, it is necessary that the corresponding tolerance of the part is

$$T_p \geq \Delta_{\text{work}_i} / \varepsilon_a = \Delta_{\text{work}_i} / \prod_{i=1}^m \varepsilon_{a_i}. \quad (3.10)$$

In the designing of manufacturing process the first and foremost task is to define a list of processing steps (operations) for machining of every surface of the workpiece and to define the refinements  $\varepsilon_{a_i}$  at each processing step to ensure Equation (3.10). Solution of this task is examined in Section 5.

As shown in Section 2, the individual dimensions of a part (functional dimensions) can be obtained as the resulting dimensions of manufacturing dimensional chains the component dimensions of which are the manufacturing dimensions. In other words, accuracy of individual functional dimensions can be determined as accuracy of several manufacturing dimensions obtained on

various processing steps and operations of the process. Accuracy of these functional dimensions can be ensured only when these dimensions are in relation to the corresponding manufacturing dimensions. Such relation is made during the tolerance analysis of the designed process. The procedure of the tolerance analysis is discussed in Section 5.

### **Review Questions**

1. How can you enhance material properties of the cast and formed workpieces?
2. How does heat treatment (annealing, normalizing, hardening, tempering) change properties of steel workpieces?
3. How does chemical-heat treatment (carburizing, nitriding, carbonitriding) change properties of workpieces?
4. List the main parameters of the surface layer quality.
5. How does quality of the surface layer influence on performance of parts and their joints?
6. How do cutting parameters influence surface layer quality?
7. How do grinding parameters influence surface layer quality?
8. What is the purpose of cold working of parts?
9. How can work hardening and residual stresses be eliminated in surface layer of a part?
10. List the main causes of errors of workpiece machining.
11. Why precision machine tools should be used only for finishing operations?
12. How can you reduce machining errors caused by elastic deformations of the technological system due to cutting forces?
13. How can you reduce the machining errors caused by thermal deformations of the technological system?
14. How can you reduce machining errors caused by cutting tool wear?
15. How can you reduce machining errors caused by residual stresses?
16. How can you reduce machining errors caused by inaccuracy of sizing cutting tools?
17. List the components of error of workpiece mounting.
18. How can you reduce the error of workpiece mounting?
19. How does mounting error influence the accuracy of machining?
20. What is the nature of the installation pieces with alignment? When is it applied?
21. What is working setting size and how is it determined?

22. Why does the method of trial cuts provide higher accuracy compared to machining on pre-set machine tools?
23. What is the aim of setting a manufacturing system for machining a batch of workpieces?
24. What methods can be used for a manufacturing system setting?

## 4. Improving Technical-Economic Efficiency of Manufacturing

The main criteria of technical and economic efficiency of manufacturing are productivity and prime cost. The sections that follow consider the key methods to increase productivity and reduce costs.

### 4.1 Technological Ways of Increasing Machining Productivity


#### 4.1.1 Operation Cycle per Part Minimization

The main share of operation cycle per part (OCP) is the operation time, which is equal to the sum of the machining time and the portion of the auxiliary time that is not overlapped by the machining time. Therefore, the OCP can mainly be cut down by reducing the machining time, reducing the auxiliary time directly or by overlapping it by the machining time.

The machining time, which is determined for each processing step by the equation as

$$t_0 = \frac{Li}{S_M},$$

can be cut down by reducing estimated cutting length  $L$  and number of passes  $i$  and increasing millimeters per minute feed-rate  $S_M$ .



*Fig. 4.1 Face milling operation*

The estimated cutting distance, in its turn, can be decreased by:

- reducing the distance of engagement;
- changing from the machining with longitudinal feed to the cross-feed (infeed) machining;
- combining the processing steps, i.e. simultaneous (parallel) execution of simple processing steps.

Fig. 4.1 shows the diagram of milling a flat surface by a face mill. It can be noted that the increase of the milling cutter diameter can greatly reduce the engagement distance ( $l''_{en} = l'_{en}$ ) and, thereby reduce the  $t_m$ .

A much more significant reduction in the estimated cutting length and machining time can be achieved, for example, by replacing longitudinal turning for cross-feed turning with a form cutter (Figure 4.2.).





Fig. 4.2 Longitudinal turning by a general purpose cutter (a) and form cutter (b)

To reduce the estimated cutting length and machining time, the combination of processing steps is widely used. These steps can be performed with either identical (Fig. 4.3, a) or different (Figure 4.3, b) tools. During the simultaneous drilling of identical holes in a workpiece by means of multi-spindle drilling heads (Fig. 4.3, a), the estimated cutting length and machining time are reduced in proportion to the number of the holes. During the simultaneous turning of different surfaces of a workpiece with the different cutting tools, clamped in different supports of the machine (Fig. 4.3, b), the estimated cutting length and machining time are reduced to the estimated cutting length and machining time of the limiting step.



*Fig. 4.3 Diagrams of machining by combining processing steps:  
 a – on a vertical drilling machine equipped with a multi-spindle head;  
 b – on a lathe with a longitudinal and cross slide*

It should be noted that the in-feed machining and combination of processing steps are often impeded by the lack of rigidity of the technological system and, above all, by the low rigidity of the workpieces. Therefore, in many cases, methods of in-feed machining are rejected, and different surfaces of a workpiece are machined one by one.

To reduce machining time by decreasing the number of passes, it is necessary to reduce allowances and redundant allowances. This can be achieved with the help of workpieces, which shape and dimensions as close as possible to the finished part. Moreover, it is important to decrease allowances both during the preliminary machining of workpieces and during the finish operations, for example, for internal grinding, which is characterized by small in-feed values and a great number of passes.

One of the major ways of machining time reduction is the use of high-performance cutting tools, which allow higher cutting speed and (or) feed rate per revolution (or per double stroke) of a workpiece or of a cutting tool to be used, and thus helps to increase the feed rate per minute.

Most of the OCPP time can be presented by auxiliary time. In some cases, for example in cylindrical grinding on universal cylindrical grinding machines, auxiliary time is several times the machining time.


The direct reduction of auxiliary time is provided by:

- use of fixtures with a high-performance mechanical drives (pneumatic, hydraulic, electromagnetic, etc.), which can reduce time needed for loading and unloading the workpiece;

- reduction of time needed to operate the machine and fixtures through proper allocation of control units, mechanization and automation of fixture, increase of idle run speed;
- reduction of time needed to measure workpieces through the use of high-performance instrumentation.

The significant reduction of both the machining and auxiliary time is achieved through the multiple-workpiece machining, in which from two to several dozen of workpieces are mounted on the machine.

Fig. 4.4 shows a diagram of a multiple-workpiece machining (turning of rings). In this case the distances of engagement, approach and over-travel are reduced in proportion to the number of workpieces, leading to reduce in machining time. Auxiliary time, spent on loading the workpieces and controlling the machine, is also significantly reduced.



*Fig. 4.4 Diagram of a sequential multiple-workpiece machining*

In parallel multiple-tool machining (Fig. 4.5) it becomes possible to combine processing steps. In this case, machining time is reduced to the machining time of the limiting step divided by the number of workpieces, and as well as a reduction in the above-mentioned components of the auxiliary time is provided.




Fig. 4.5 Diagram of a parallel multiple-workpiece machining

Multiple machining methods give an opportunity to overlap auxiliary time by the machining time that is not possible with the single machining.

In the simplest case this is achieved by so-called "pendulum" machining, when, for example, the table of a vertical milling machine carries two fixtures for mounting of workpieces (Fig. 4.6). While one workpiece is being machined, the previously machined workpiece is unloaded from the machine and is replaced by the next workpiece to be machined.

The most successful overlapping of the auxiliary time by the machining time is performed with a continuously rotating table or drum. Fig. 4.7 shows face milling on the two-spindle vertical milling machine with a continuously rotating table. Milling cutters, clamped in spindles *I* and *II*, perform rough and finish milling, respectively. Loading and unloading of the workpieces are performed in the loading area without stopping the machine.





Fig. 4.6 "Pendulum" milling. 1 – fixture; 2 - workpiece



Multiple machining with combination of steps is effectively implemented on automatic and semi-automatic multi-spindle machines, modular multi-spindle and multiple-station machines and automated production lines.



*Fig. 4.7 Diagram of a multiple parallel-sequential machining with continuous loading of workpieces*

Fig. 4.8 shows, as an example, a diagram of machining on an automatic 4-spindle bar machine. Each workpiece sequentially passes through the working positions *I-IV*, in which parallel processing steps are executed by a series of tools installed in the longitudinal and cross slides. As the spindle drum indexes through  $90^\circ$ , another machined workpiece comes off.




Fig. 4.8 Diagram of the machining on an automatic 4-spindle bar machine

### 4.1.2 Setup Time Minimization. Multiple Machining

As noted above, when workpieces are machined in batches, standard time for an operation is the sum of OCPP  $t_{oc}$  and standard setup time  $t_s$  divided by the batch volume  $n$

$$H_t = t_{oc} + \frac{t_s}{n}.$$

According to this equation, the portion of setup time for the operation can be reduced by either direct decreasing  $t_s$  or increasing the batch volume  $n$ .

Recall that the setup time is spent on familiarization with the task (drawings, technical documentation, getting instructions from the master), setting up tools and fixtures, jaws, templates, replaceable gears, setting of the machine tool, test-part machining, removal of fixtures and tools from the machine tool, handling finished parts, remains of materials, fixtures, tools, technical documentation and work-order.

Clear written manufacturing process documentation and drawing reduce the time spent on familiarization with the task.

Reduction of time needed for installing fixture and tools on the machine tool is ensured by interchangeability principle. For example, to ensure required accuracy of the fixture position on a milling machine table, the fixture is provided with locating keys that fit into the table central slot, which tolerance is  $H7$  or  $H8$ .

To reduce the time required for setting the technological system, interchangeable tool holders, turrets and interchangeable tool magazines with the preset tools are widely used. Modular machine tools are equipped with the re-


placeable spindle drums, which are used for machining workpieces of several types.

One of the most important ways to reduce setup times is *group technology*, scientific foundations of which were developed by Prof. S.P. Mitrofanov. The essence of the group technology is as follows. Parts that are close in size, weight, material, accuracy and surface layer quality and allow machining on the same equipment are combined into groups. For each group, an integrated (group) manufacturing process is designed, tool set-ups and fixtures, with the goal to minimize the set-up time, spent to change from machining one part to another part, and reduce equipment downtime.

As a result, careful selection of parts into a group, well designed group manufacturing process and rational design of group-fixtures that require minimal changeovers practically allow the batch production to be turned into mass production.

It should be noted that in many cases of group technology, it is economically feasible to apply equipment of higher productivity, including re-adjustable automatic production lines.

The simplest is the implementation of group operations. Fig. 4.9 shows an example of a fragment of group setup of the semi-automatic 8-spindle lathe for machining parts of three types. In this case, the machine tool is equipped with rotary tool plates (tool holders). Each side of the tool holder carries tools intended for machining respective types of the workpieces. When a workpiece *1* is being machined, these tool holders for all positions of the machine are indexed to the first position (tools for workpieces 2 and 3 are in the off-position). To change to machining of workpieces of other type (2 or 3) it is needed to only index the tool holders and clamp the workpiece in the corresponding surfaces of the chuck jaws.



*Fig. 4.9 An example of 8-spindle lathe set for machining parts of three types: 1-3 – workpieces; 4 – locking pin*

It should be emphasized that a group, particularly for the group operations, can be built of parts that differ in design, but have similarities in production allowing machining on the same machine tool. An example of a group of such parts is shown in Fig. 4.10.




Fig. 4.10 Example of parts grouped into a family

During the design of group manufacturing processes, after grouping the parts, a typical part of the group is allocated as a representative part or the complex part of the group is formed. A *representative part* shall have all the surfaces of the parts of the group. Usually, as a typical representative part, the most complex part of the group is taken. If there is no such part that can be taken as a typical representative of the group, an artificial complex-part, containing all the surfaces of the group parts, is created. An example of the complex-part formation for the group of parts is shown in Fig. 4.11.




Fig. 4.11 Formation of a complex-part: a-h – parts of a group; i – the complex-part.  
1-7 – elementary surfaces

Manufacturing processes and tooling setups are designed for a representative part or a complex-part. Machining of the certain parts of the group can be performed with the omission of certain operations or processing steps of the group manufacturing process.

## 4.2 Prime Cost Minimization

### 4.2.1 Multiple-machine Manning

Manning of several machine tools helps to raise productivity and reduce wages. Multiple-machine manning becomes practical for operations with quite long machining time. During the machining time, the worker is not employed on a machine tool and can perform work on the other machines tools.

Auxiliary time in multiple-machine manning is divided into two types: the overlapping auxiliary time ( $t_{ao}$ ) and non-overlapping auxiliary time ( $t_{an}$ ). By  $t_{ao}$  is meant the auxiliary time that is overlapped by machining time  $t_m$  of a sin-

gle machine tool, by  $t_{an}$  is meant the auxiliary time that is not overlapped by machining time  $t_m$  of a single machine tool.

The auxiliary time, except the specified components, also includes time the worker needs to walk from one machine to another one ( $t_{pass}$ ).

Equipment maintenance time ( $t_e$ ), workplace preparation time ( $t_{wp}$ ) and time for rest ( $t_r$ ) in multiple-machine manning make up extra-time ( $t_{ex}$ ):

$$t_{ex} = t_e + t_{wp} + t_r,$$

which is planned for a work shift.




Fig. 4.12 Sequence diagram of a multiple-machine manning with the full use of machining time

Let's consider the sequence diagram for the multiple-machine manning (Fig. 4.12), in which the same machines that perform the same operation are used. The worker removes a finished part from the machine, loads the next part and switches on the machine. The time spent on these actions forms non-overlapping auxiliary time ( $t_{an}$ ). Then the worker measures the finished part, spending overlapping auxiliary time ( $t_{ao}$ ), and walks to the second machine tool and so on. By the end of machining cycle on the first machine, the worker goes back to it. Further, the cycles of the multiple-machine operation are repeated.

Operation cycle ( $T_c$ ) in multiple-machine manning, i.e. the period of time during which the same actions are repeated on all the machines (Fig. 4.12), is as follows

$$T_c = t_m + t_{an}.$$

The machining time will be fully used, if

$$t_m = t_{an}(N - 1) + (t_{ao} + t_{pass})N,$$

where  $N$  is the number of the machines being manned.

Hence

$$N = \frac{t_m + t_{an}}{t_{an} + t_{ao} + t_{pass}}$$

Standard production rate per shift for manning of  $N$  machines is

$$H_{pr} = N \frac{T_{sh} - t_{ex}}{T_c},$$

where  $T_{sh}$  is the duration of the shift.

The given sequence diagram of multiple-machine manning is an idealized one. In fact, it is difficult to achieve such a sequence diagram in practice. Thus, in cases when simple low-cost machines are manned, the full-time work of a worker and some downtime of the machines are usually accepted. And vice versa, downtime is eliminated and the worker is not fully loaded, when expensive machinery is used.

It should be noted that in practice, in many cases the multiple-machine manning is organized in such a way that the worker operates the machines (of one group) which perform various operations or even the machines that belong to different groups, such as turning and milling.

#### 4.2.2 Reduction of Materials Cost

A significant portion of the prime cost of a part is the cost of materials. Reducing these costs can be achieved by:


- near net-shape workpieces;
- economical use of expensive materials;
- produce waste, during the machining, in the most valuable form that can be used to produce other parts.

Using the workpieces of a shape and dimensions close to the finished part, helps to not only reduce material costs, but also reduce the amount of machining and associated costs.

To save expensive materials, the parts are made compound. For example, bearing sleeve is made bimetallic (inner part is non-ferrous metal, outer is structural steel). Many cutting tools are also made as compound (drills, end mills, etc.). The high speed steel or carbide working part is connected to the structural steel shank by welding or soldering.


Significant material saving is gained with the rational cutting of sheets. Fig. 4.13 shows, how by a small change in the part design (from the part shown in Fig. 4.13, *a* to the part shown in Fig. 4.13, *b*), it is possible to significantly reduce waste in cutting of sheets.





*Fig. 4.13 The impact of the part design on the amount of wasted material*

An example of wastes in the most valuable form is a core, formed after trepanning operation (Figure 4.14). Trepanning drills are used for making holes with diameters of 70... 200 mm and larger. The produced core is used for manufacture of other parts. It should be noted that trepanning can not only save material, but also significantly increase productivity, as well as reduce energy and tool costs.



*Fig. 4.14 Drilling of holes with a trepanning drill*

#### **4.2.3 Reduction of Costs for Manufacturing Process Planning. Typification of Manufacturing Processes**

The costs of manufacturing process planning (MPP) can contribute significantly to the prime cost of parts. MPP involves designing of manufacturing process, designing and manufacturing of fixtures and organization of manufacturing process inspection.

One way of reducing time and cost of the designing of manufacturing process and tooling is the extensive use of standard (or typical) manufacturing processes.

The idea of the manufacturing process typification was expressed in the 30-60-ies of XX century by prof. A.P. Sokolovsky. In line with this idea the

parts of the machines, according to similarities in design and production, are divided into classes (shafts, gears, brackets, levers, bushings, etc.). Each class is divided into subclasses, groups, subgroups and types. An example of classification of parts (brackets) is shown in Fig. 4.15.




Fig. 4.15 An example of part classification

For the parts of each type, considering the manufacturing conditions (production method), a typical manufacturing process is developed. This also requires to set type of the workpiece, type of the equipment used, sequence and content of the machining operations, fixtures and schemes of parts locating. The degree of detailed elaboration of the typical manufacturing process can be different and depends on the degree of unification of parts covered by this

type. With a high degree of parts unification the typical process contains all information necessary to manufacture the parts of the type. Otherwise, the typical process can be represented as a list of sequentially performed operations, with the machine tool models specified (route typical process typical process route sheet). This process serves as the information basis for the development of the typical process operation sheet

Typical processes are developed as industry-wide or enterprise-based, on the analysis and summarizing of the experience of advanced mechanical engineering plants. These processes use the most efficient and reliable engineering solutions, tested and proved in production environment.

Designing of a manufacturing process for a particular part, on the basis of a typical manufacturing process, can significantly reduce time and costs for the project, as well as significantly improve quality of design activities. However, it should be borne in mind that the typical manufacturing processes reflect past experience. Thus, the typical manufacturing processes, as the mechanical engineering advances, must be periodically adjusted.

The most common application of typical manufacturing processes is found in large-batch production and mass production.

Application of computer-aided systems, which are largely based on the use of typical processes, can sharply reduce time and costs for fixture design and process planning. It is important that this not only reduces production costs, but also provides a higher, compared to manual design, quality of design decisions and reduces the time and cost for revision and implementation of manufacturing processes.

### **Review Questions**

1. How can you reduce machining time?
1. How does rigidity of technological system affect the possibility of combining the processing steps?
2. How can you reduce auxiliary time?
3. What are advantages of multiple-machining?
4. How can you reduce setup time?
5. What is the essence of group technology?
6. How can you reduce materials costs?
7. When multiple-machine manning is applicable and what advantages it provides?
8. What is the essence of process typification and what advantages it provides?

## 5. Fundamentals of Manufacturing Process Design

### 5.1 General Concepts. Principles and Sequence of Manufacturing Process Design

**Types of manufacturing processes.** Manufacturing processes are classified according to the following features:

- form of the process organization, which is determined by the number of articles of manufacture covered;
- degree of the process implementation under specific production conditions.

Depending on the form of the process organization, there are three types of manufacturing processes:

- uniform;
- typical;
- group.

*Uniform manufacturing process* is a process of manufacture or repair of products of one type, size, and configuration, regardless of the method of production.

*Typical manufacturing process* is a process of manufacturing a group (family) of products similar in design and production.

*Group manufacturing process* is a process of manufacturing products, which are different in design, but similar in production.

Depending on the degree of process implementation in production, two types of process are distinguished:

- working;
- prospective.

*Working manufacturing process* is a process of manufacture of one or more products according to the implemented manufacturing process documentation.

*Prospective manufacturing process* is an up-to-date manufacturing process that is to be implemented at the enterprise (used as information basis for designing of working manufacturing processes during the technological and organizational retooling of production).

Depending on complexity, cost and method of production of products, the different manufacturing process documentation, depending on degree of detailed elaboration of the documentation, are used:

- routing;
- operational;

– route-operational.

The *route description of the manufacturing process* briefly describes all production operations in a route sheet, in the sequence of their execution without specifying the processing steps and manufacturing parameters.

The *operational description of the manufacturing process* gives a complete description of all manufacturing operations in the sequence of execution, specifying processing steps and manufacturing parameters.

*Route-operational description of the manufacturing process* briefly describes all production operations in a route sheet, in the sequence of their implementation, with a complete description of individual operations in other manufacturing documents.

In accordance with the adopted process description, the routing, operational and route-operational manufacturing processes are distinguished.

Routing and route-operational description are used in job production and small-batch production, operational description is mainly used in medium-batch, large-batch and mass production. When large (expensive) parts are manufactured, the operational description also is used in job and small-batch production.

Below we will mainly consider the design of a uniform operational manufacturing process.

The design of a uniform operational manufacturing process is aimed at giving a detailed description of all stages of parts manufacturing along with the technical and economic calculations and validation of decisions. As a result of technical documentation design, engineering and technical personnel and workers receive all the necessary information for the implementation of the developed process. During the design process the manufacturing means (equipment, fixtures, cutting and measuring tools), the labour-intensity and manufacturing cost of parts are determined. This serves as a basis for organizing the supply of basic and auxiliary materials, for production scheduling, engineering inspection, tooling and transportation maintenance, as well as for definition of the production area, necessary energy and labour resources.

It is necessary to distinguish design of manufacturing processes for existing factories from the processes for the newly designed (reconstructed) factories. In the first case, manufacturing processes are designed for manufacture of new or improved products or products that are in production to improve the technical and economic characteristics of the manufacturing process, based on application of modern science and technology advances. In the second case, the manufacturing processes developed on the basis of these advances are the foundation for the whole project of a new (reconstructed) factory.

**Principles of the manufacturing process design.** Design of manufacturing processes is carried out on the basis of two principles: technical and eco-

conomic. According to the technical principle, the manufacturing process should comply with all the technical requirements. These requirements can be met in several variants of the manufacturing process, which differ, for example, in the methods of workpiece production, in machine tools and tooling applied. In accordance with the economic principle, the adopted version of the manufacturing process should be the most cost effective.

**Initial data and sequence of the manufacturing process design.** The initial information needed for design of the manufacturing process is divided into the basic, reference and guidelines information.

For designing processes for new factories or enterprises, basic information include part drawing, drawing of the assembly that includes the part, volume of production.

For design of a manufacturing process for existing factories the basic information is supplemented with information about equipment, fixtures, tools, production facilities available in the factory and other manufacturing conditions. Moreover, manufacturing engineer, in making decisions, is often forced to focus primarily on the use of manufacturing means available in the factory.

Reference information is represented in a form of catalogues and production equipment documents, fixture albums, standards for cutting and measuring tools, guidelines on the machining accuracy and surface layer quality of the workpieces, standards for the calculation of allowances, cutting parameters and standard times, wage rate handbooks, etc.

Guidelines include information about the prospective manufacturing processes of the industry, standards of manufacturing processes and technical documentation, main requirements for the current state and future prospects of production development at the factory.

The manufacturing process is developed in a certain sequence.

1. Firstly, the analysis of technical requirements of the part is performed, then the possibility of meeting and inspecting these requirements, in the factory conditions, is defined, and the most complex technological problems of the manufacture are identified.

2. The method of production and the form of its organization is determined (mode of production).

3. The drawing is analyzed for manufacturability in the factory conditions.

4. Workpiece type and the method of its manufacture is chosen.

5. Manufacturing datums are assigned.

6. Sequence of surface machining is defined, i.e. the sequence of processing steps needed to comply with the accuracy and surface layers quality specified on the drawing.

7. Route of manufacturing is designed, then manufacturing means are chosen and manufacturing process operations are designed.
8. Tolerance analysis of the process is performed (calculation of machining allowances and manufacturing dimensions of the workpiece).
9. Cutting parameters are calculated.
10. Calculation of standard times or production rates.
11. Technical and economic parameters of the manufacturing process are determined.
12. Technical documentation is drawn up.

## **5.2 Analysis of Drawing Specifications and Identification of Part Manufacturing Objectives**

Before the design of a manufacturing process, the working drawings of the part and the product (assembly unit) which include the part are studied in detail. Then the functions and operation conditions of the part are revealed.

The part drawing should give a comprehensive concept of the part. The drawing must contain a sufficient number of projections, sections and views; it should contain all the necessary dimensions (with limit deviations), tolerances of form and location, parameters of roughness and waviness, heat or chemical heat treatment, type of coating, hardness of the material and specific technical requirements (for example, the permissible degree of unbalance).

The specifications given in the drawing are considered from the following perspective:

- rationality of the specifications set by a design-engineer (e.g., whether the requirements aren't raised too high, correctness of part dimensioning, etc.);
- possibility of meeting the specifications with the help of the common and available in the factory tooling;
- possibility of inspection by the common methods and instruments.

For example, if the size of the analyzed part is a component dimension in a dimensional chain, then, by analyzing this chain, one can assess whether the tolerance for the size was appointed correctly.

Analysis of the technical requirements helps to identify technological problems that can arise during manufacturing. To perform the analysis, the sets of surfaces that are subject to the highest requirements for dimensional and geometrical (form and location) accuracy and quality of the surface layers are revealed. These requirements determine selection of manufacturing datums and methods of workpiece mounting, finishing operations and manufacturing process as a whole, the necessary means of manufacture. For example, an im-

portant technological goal for a stepped shaft manufacture is to provide high accuracy of sizes, form and location of its necks. Such a task for an inner ring of a bearing is to obtain high accuracy of size and form of the raceway, small values of the amplitude parameters of roughness and waviness of the raceway surface, minimum radial run-out of the race relative to the bore.

Design of a manufacturing process for an operating factory requires careful study of the manufacturing environment. It is needed to establish availability of production floor space and equipment needed for manufacture, to determine possibility of equipment upgrading and expanding production facilities to increase production of the parts, to find out possibility of application of advanced cutting tools and new methods of workpiece manufacture and machining, etc.

Design of a manufacturing process for operating factories also requires to analyze the possibility of parts manufacture by the available on the factory typical or group manufacturing processes. In the absence of such a possibility, the design of a uniform manufacturing process is started.

### 5.3 Production Method Identification

The method of production influences: form of production organization (mode of production); type and method of production of a workpiece; type of the applied equipment, fixtures and tools; degree of detailed elaboration of the manufacturing process design.

At the stage of the manufacturing process planning, the production method can only be determined approximately. For this purpose the data given in Table 5.1 can be used.

Table 5.1

*Dependence of production method on the production volume, pcs., and part mass*

Part mass, kg	Method of production				
	Job	Small-batch	Medium-batch	Large-batch	Mass
<1.0	<10	10...1500	1500...100000	75000...200000	200000
1.0...2.5	<10	10...1000	1000...50000	50000...100000	100000
2.5...5.0	<10	10...500	500...35000	35000...75000	75000
5.0...10	<10	10...300	300...25000	25000...50000	50000
>10	<10	10...200	200...10000	10000...25000	25000



The method of production is also evaluated with the help of production factor  $K_{\text{pf}}$ , the calculation of which and its values for different methods of production are given in Section 1.

The production factor is calculated as follows

$$K_{\text{pf}} = \frac{t_{\text{T}}}{t_{\text{aoc}}},$$

where  $t_{\text{T}}$  is the Takt time;  $t_{\text{aoc}}$  is the average OCPP.

Takt time, as already noted, is determined by the equation  $t_{\text{T}} = 60\Phi_a / N$ , where  $\Phi_a$  is the actual annual available hours of the equipment,  $N$  is the annual production volume.

The average OCPP can be determined with the help of data of the existing process of manufacture of a similar part or by rationing the process being developed with the help of the extended standards. The average OCPP is calculated by the equation

$$t_{\text{aoc}} = \sum_{i=1}^n t_{\text{oci}} / n,$$

where  $t_{\text{oci}}$  is the OCPP of the  $i^{\text{th}}$  operation of manufacturing process;  $n$  is the number of basic operations in the process.

The  $t_{\text{oci}}$  is calculated, taking into account only the basic operations, excluding, for example, operations of heat treatment, deburring, cleaning and labeling.

Further, the method of production found with the help of production factor is compared with the method found by Table 5.1. In case they do not match, the adopted method of production is the one that calculated by production factor.

When the method of production is found, the mode of production is defined (flow or non-flow). The possibility to use flow production is determined by the workplace load factor

$$K_{\text{work}} = \frac{t_{\text{aoc}}}{t_{\text{T}}}.$$

If the workplace load factor is  $K_{\text{work}} > 0.6$ , then the flow method of production is taken.

## 5.4 Analysis of a Drawing for Manufacturability

Analysis of a drawing for manufacturability process, as noted in Section 1, is performed by a manufacturing engineer to assess the capability of the part design to meet the requirements for manufacturability with respect to the

method of production and specific production conditions, in particular, technological capabilities and features of the equipment.

General requirements for manufacturability can be summarized as follows.

The part should be a combination of surfaces of simple shapes. The part should be composed of standardized and unified geometrical elements (threads, grooves, recesses, modules, splines dimensions, keyways dimensions, etc.) to the utmost, or be a standard as a whole. This creates background for unification of cutting and measuring tools, used in manufacture and repair of parts.

The part should be sufficiently rigid, have reliable manufacturing datums, allow easy movement of high-performance cutting tools to all surfaces to be machined and the free withdrawal of the tools. All this as a whole allows implementation of high-performance machining.

The accuracy parameters and surface layers quality of the part must strictly correspond to its functional purpose. Excessive demands on these parameters lead to the necessity of introducing additional processing steps, extend operation cycle, increase complexity of manufacturing parts and increase cost of manufacturing.

To reduce amount of machining is necessary to reduce the length of the machined surfaces of parts and increase accuracy of the workpieces, making them closer to the finished parts in shape.

Dimensioning of the parts (functional dimensions) should take into account technological requirements and provide:

- coincidence of functional, manufacturing and measurement datums;
- machining on the machines preliminary set to the required dimensions;
- use of the simplest fixture, cutting tools and measuring tools;
- reliability and ease of inspection;
- absence of need for recalculation of dimensions during production and inspection;
- rational sequence of the part manufacturing.

For example, drawings of parts that are produced from forgings and castings and require machining of individual surfaces should have the following three groups of sizes specified (see Fig. 5.1). Dimensions of the first group interconnect unmachined surfaces and are used in workpiece production (dimensions 20 and 10 in Fig. 5.1, *a*); the second group interconnects surfaces to be machined (dimension 40 in Fig. 5.1, *a*); the third group of dimensions for each coordinate direction should contain only one size that connects a system of machined surfaces with a system of unmachined surfaces (size 10\* in Fig. 5.1, *a*).

If this requirement is violated and a drawing is dimensioned as shown in Fig. 5.1, *b*, then the facing of the left end of the part will directly ensure only one of the dimensions (e.g., 10\*). The other two dimensions (20 and 30) will be obtained in the form of resulting dimensions in the manufacturing dimensional chains; the accuracy of these dimensions will be significantly lower than the accuracy of the workpiece dimensions.

If the part is to be heat or chemically heat treated, its form should be symmetric with no sharp edges, sharp thin webs and abrupt changes in cross-section, surface roughness should be  $Ra \leq 10$  microns. Violation of these requirements during hardening may cause cracking and fracturing of the workpiece.


























Fig. 5.1 Variants of the part dimensioning (machined surfaces are in bold):  
*a* – correct; *b* – wrong









Some examples of correct and wrong geometrical elements, in terms of manufacturability, of parts are given in Table 5.2 [16].

Table 5.2

Examples of wrong and correct designs for manufacturability			
Basic manufacturing requirements	Designs		Advantages of a correct design
	wrong	correct	
Surfaces to be machined shouldn't be continuous			Lower tool wear. Higher accuracy and better surface finish. Lower labour intensiveness.

Basic manufacturing requirements	Designs		Advantages of a correct design
	wrong	correct	
Surfaces to be machined should be located in the same plane			<ol style="list-style-type: none"> <li>1. Possibility to machine at one pass by face-milling, surface grinding or surface broaching.</li> <li>2. Possibility to machine several workpieces simultaneously.</li> <li>3. Simplified inspection.</li> </ol>
Surfaces to be machined should be open. Long and narrow surfaces should be located so that they can be machined along a plane			<ol style="list-style-type: none"> <li>1. Possibility to apply face-milling.</li> <li>2. Raise of productivity and accuracy.</li> </ol>
Surfaces to be machined shouldn't be placed in recesses or pockets			<ol style="list-style-type: none"> <li>1. High productivity machining.</li> <li>2. Lower labour intensiveness.</li> </ol>
The most accurate step in a stepped bore should be made as a through hole			<ol style="list-style-type: none"> <li>1. Lower labour intensiveness.</li> <li>2. Higher machining accuracy and tool life.</li> <li>3. Simpler design of cutting tools.</li> </ol>
Splined holes should be continuous			<ol style="list-style-type: none"> <li>1. Elimination of tool breakage and higher tool life.</li> <li>2. Lower labour intensiveness in hole machining.</li> </ol>

Basic manufacturing requirements	Designs		Advantages of a correct design
	wrong	correct	
Blind splined holes should be avoided			Possibility to apply high-productive broaching.
Grooves or recesses in holes shouldn't require any machining			<ol style="list-style-type: none"> <li>1. Lower labour intensiveness.</li> <li>2. Possibility to apply high-productive methods of machining.</li> </ol>
Consideration should be given to the best conditions of the cutting tool guiding			<ol style="list-style-type: none"> <li>1. Higher machining accuracy.</li> <li>2. Higher cutting tool rigidity.</li> <li>3. Higher productivity.</li> </ol>
Possibility for a cutting tool to enter and exit freely			<ol style="list-style-type: none"> <li>1. Elimination of tool breakage.</li> <li>2. Higher accuracy of drilling.</li> <li>3. Higher productivity.</li> </ol>
Holes location should provide usage of cutting tools of normal length			<ol style="list-style-type: none"> <li>1. Application of standard cutting tools and its full usage.</li> <li>2. Higher machining accuracy.</li> </ol>
Blind threaded holes should have grooves for the tool over-travel or provide thread run-out			<ol style="list-style-type: none"> <li>1. Higher quality of the thread.</li> <li>2. Better cutting conditions.</li> <li>3. Lower labour intensiveness.</li> </ol>

Basic manufacturing requirements	Designs		Advantages of a correct design
	wrong	correct	
The design of a threaded hole should provide possibility to a threading tool to work through the hole			<ol style="list-style-type: none"> <li>1. Higher productivity.</li> <li>2. Better cutting conditions.</li> <li>3. Application of cutting tools with better cutting performance.</li> </ol>
Inclined position of the hole axis should be avoided			<ol style="list-style-type: none"> <li>1. Simpler design of fixture.</li> <li>2. Possibility for simultaneous machining of holes with the parallel axes.</li> <li>3. Lower labour intensiveness.</li> </ol>
Closed slots for endmilling should be avoided			<ol style="list-style-type: none"> <li>1. Application of cutting tools of higher productivity.</li> <li>2. Better cutting conditions, especially conditions of engagement.</li> <li>3. Lower labour intensiveness.</li> </ol>
Closed pockets or slots should be avoided			<ol style="list-style-type: none"> <li>1. Reduction of passes.</li> <li>2. Simpler design of cutting tools.</li> <li>3. Lower labour intensiveness.</li> </ol>

The requirements for manufacturability should be met not only by the parts, but by the workpieces as well.

Castings must meet the following basic requirements:

- wall thickness of castings should be as uniform as possible, as it provides a homogeneous structure and reduction of residual stress;
- form of a casting should provide simple and easy model opening;
- casting surfaces that are perpendicular to the parting plane of the model should have draft and taper to facilitate production of molds and cores and pulling of patterns out of the molds.

Forgings produced by stamping and forging must meet the following requirements:

- no abrupt changes in cross-section;
- junction of different cross-sections should be in a form of arcs of relatively large radii;
- a sharp edges of forgings produced by stamping should be rounded;
- forging surfaces, that are perpendicular to the parting plane of the mold, should have draft to pull the forging out of the mold.

Analysis of a drawing for manufacturability is to a compare design solutions to some decision that is taken as a reference standard. On the basis of this comparison, the assessment as "good – bad" or "rational – irrational" is made. The references for comparison purposes are: design of a similar part that is produced in batches; standard technical requirements for the part; personal experience of the engineer that performs the analysis.

On the basis of the analysis for manufacturability, a list of the comments and proposals on changing the elements of the component design is compiled and then submitted to designer's approval. The latter, after reviewing this list, can make appropriate changes to the part drawing to improve its manufacturability.

## **5.5 Selection of a Workpiece**

The workpieces are distinguished in type that reflects the technology of their manufacture. The following types of workpieces are distinguished:

- casting;
- forgings produced by forging and die-stamping;
- rolled stock;
- welded workpieces;
- workpieces produced by powder metallurgy.

Workpieces of each type can be manufactured by one or more methods. For example, castings can be produced by sand casting, die casting, permanent- mold casting, etc.

Casting produces workpieces of almost any size, of both simple and very complex shape, of almost all metals and alloys.

Forming processes (rolling, forging, stamping) produces workpieces from metals and alloys with necessary plasticity.

Welded workpieces are obtained from the individual components produced by rolling, casting or stamping by welding them together.

Powder metallurgy produces workpieces which material has special, often unique physical and mechanical properties (ceramics, carbides, etc.).

Selection of the type and method of workpiece production depends on the following factors:

- required level of physical-chemical properties of the part material;
- manufacturing properties of the workpiece material;
- structural shape, size and weight of the part;
- method of production (volume of production);
- availability of manufacturing equipment at the enterprise (casting, forging, welding, etc.), as well as possibility and feasibility of workpieces to be purchased from external suppliers.

Selection of the workpiece type is mainly guided by the demand to provide required level of physical-chemical properties of the workpiece material, which depends on the nature and intensity of the loads acting on the part during operation of the product. For example, if a part is operated under high dynamic loads, then it is desirable to produce workpiece, as mentioned above, using forming methods, which generally provide a fine-grained structure and a higher level of mechanical properties of the workpiece material (fatigue strength, impact strength, toughness, ultimate strength) than the conventional casting techniques.

Technological properties of the workpiece material (casting characteristics, deformability, weldability, etc.) determine the ability to obtain the workpiece by casting, forming, welding and powder metallurgy. Thus, if the part material is gray cast iron, then the only possible type of a workpiece is a casting. If the part material has low fluidity and a high tendency to shrinkage, then it is impossible to produce workpiece by die-casting or permanent-mold casting due to rapid cooling of the melted material and low malleability of molds.

A very significant impact on the type and method of production of workpiece has the shape, size and weight of a part. As the size and weight of a part increase, then the variety of possible methods of workpiece production decreases. For example, a steel stepped shaft with a largest diameter of 200 mm and a total length of 2000 mm can be manufactured from a round hot-rolled bar or from a forging produced by open-die forging. If the diameter of the shaft is increased to 500 mm, then the only method of workpiece production is open-die forging. Such effective methods as die-casting, permanent-mold casting, evaporative-pattern casting and die forging are only applicable for the manufacture of workpieces of relatively small mass. For example, upsetting machines are capable of forging parts weighing up to 30 kg, by evaporative-pattern casting it is possible to cast steel parts weighing up to 150 kg, by mold casting a steel casting weighing up to 4000 kg can be made.

Largely, the type and production method of workpiece depends on volume of production (method of production). As the production volume increas-



es, the more economically feasible technique of workpiece production becomes the production of workpieces close in shape and size to the finished part. For example, if in job production and small-batch production a steel stepped shaft is commonly manufactured from a round hot-rolled bar, in large-batch production and mass production these shafts are usually made of forgings produced by open-die forging.

During the manufacturing process design, the issues of selection of the method of workpiece production are cooperatively solved by manufacturing engineers of mechanical and workpiece workshops. Here, two situations are possible:

- when a method of workpiece production is specified by a design engineer, and manufacturing engineers only refine it;
- when a designer reserves the selection of a method of workpiece production to manufacturing engineers.


The first situation is typical for mass, large-batch and medium-batch production, the second one - for job and small-batch production.

A designer selects a workpiece based on the long-term collaboration with manufacturing engineers of mechanical and workpiece workshops. This selection is aimed at creating such a method for workpiece production that would ensure high reliability and, at the same time, the smallest cost of the part. This work covers various tests of a part, the workpieces for which are manufactured by different methods, and analysis of the machine operation with its modifications and enhancement considered. The said above is typical for most critical components that determine reliability of machines (parts of an engine block, crankshafts and camshafts of internal combustion engines, blades and discs of gas turbine engines, etc.).

In case of an independent decision on the choice of the method of the workpiece production, the manufacturing engineers of mechanical and workpiece workshops consider several methods and choose one that provides the lowest cost of the parts, with respect to the factors above.

The more the shape and size of the workpiece are close to the shape and size of the part, the more expensive is the workpiece to produce, but the easier and cheaper is the subsequent machining and lesser the material consumption. Thus, the lowest cost of the part will correspond to the minimum total cost of production of the workpiece and its subsequent machining.

To produce more accurate and complex workpieces, a relatively expensive tooling (complex dies or sets of patterns) is required, costs of design and manufacture of the tooling could justify itself only when a sufficiently large volume of parts is produced.



*Fig. 5.2 Types of workpieces of a gear:  
 a – forged; b – stamped in lower die  
 blocks; c – stamped in closed dies (dotted  
 line is an outline of a gear) [15]*

Thus, for example, the gear workpiece (see Fig. 5.2) of steel grade 18XГТ (0.18% C, 1% Cr, 1% Mn) can be produced by forging (Fig. 5.2, *a*) stamping in lower die blocks (Fig. 5.2, *b*) and stamping in closed dies (Fig. 5.2, *c*). The second and, especially, the third method, compared with the first one, produce a workpiece with a shape the most closest to the finished part and reduce material consumption, but requires additional costs for design and mold manufacture. For small volume of production these costs are relatively high and the lowest cost (see Fig. 5.3) of workpiece production will be ensured by forging. As the volume of production increases, the share of the mold cost in the cost of the workpiece decreases and the most effective method of workpiece production firstly becomes the stamping in lower die blocks, and then – stamping in the more complex and expensive closed dies, which gives the most significant material savings.




Fig. 5.3 Dependence of the gear workpiece cost  $C$  on a the volume of production  $N$  for different methods of workpiece production:  
 1 – forging; 2 – stamping in lower die blocks; 3 – stamping in closed dies [15]

It should be noted that in mechanical engineering for manufacture of several non-similar in design and manufacturing technology parts, the group (complex) workpieces are used. This helps to increase the total output of the workpieces and to make, for example, stamped workpieces more economically feasible than the rolled ones. An example of a group (complex) workpiece is shown in Fig. 5.4.




Fig. 5.4 An example of a group (complex) workpiece:  
 1 – complex part; 2 – part of the group;  
 3 – group workpiece [15]

## 5.6 Selection of Manufacturing Datums

### 5.6.1 Principles of Manufacturing Datums Selection

Selection of manufacturing datums should be guided by two principles: principle of permanent datums and principle of coincident datums.

**Principle of permanent datums.** *In accordance with the principle of permanent datums, it is desired to ensure that throughout the entire manufacturing process the same manufacturing datums are used, except the first operations on which the manufacturing datums itself are machined.*

This principle is explained by the fact that the errors of sizes between surfaces and the errors of location of the surfaces, which are obtained from different datums, are affected by the errors of dimensions between these datums and errors of location of these datums.

The influence of errors of manufacturing datums location on errors of location of the surfaces machined from these datums is clearly demonstrated in Fig. 5.5. In drilling hole A (Fig. 5.5, a), the plane I is used as a plane datum and the plane II is used as a guiding datum. In drilling hole B (Fig. 5.5, b) quite the contrary, the plane II is used as a plane datum and the plane I is used as a guiding datum. As can be seen from Fig. 5.5, the error of manufacturing datums location (deviation from perpendicularity of the plane I to the plane II) is completely transferred to the location error of the holes A and B.




Fig. 5.5 Influence of location error of manufacturing datums on location error of machined surfaces

Let's consider another example. It is necessary to ensure functional dimensions  $K_2$  and  $K_3$  of the plate shown in Fig. 5.6, a, the dimension  $K_1=A_1=100\pm 0.1$  mm was obtained earlier. The first operation, boring of the hole with diameter of 40 mm, is performed on a lathe, and drilling of two holes of 6 mm in diameter (the second operation) is performed with the help of a drilling jig on a vertical drilling machine.




Fig. 5.6 On influence of the manufacturing datums change on the functional dimension error

Let's analyze the two variants of machining. In the first variant, both operations (Fig. 5.6, *b* and 5.6, *c*) are performed using the same manufacturing datums. In the second variant, the first operation (Figure 5.6, *b*) is performed with the plane *I* used as a guiding datum, and the second operation is performed with the plane *II* used as a guiding datum (Figure 5.6 *d*).

In both variants of machining, functional dimension  $K_2=A_2$  (Fig. 5.6, *b*) is obtained directly.

Functional dimension  $K_3$ , in the first variant, is a resulting dimension of the dimensional chain shown in Fig. 5.6, *e*. Tolerance of this dimension is

$$TK_3=TA_2+TA_4=0.2+0.2=0.4 \text{ mm}$$

complies with the tolerance value given on the plate drawing.

In the second variant, dimension  $K_3$  is a resulting dimension of a longer dimensional chain (Fig. 5.6, *e*). One of the component dimensions of this chain is the size  $A_1=100\pm 0.1$  mm between the guiding datums used on the first and the second operations. In this variant, tolerance of the dimension  $K_3$ , which is

$$TK_3=TA_1+TA_2+TA_3=0.2+0.2+0.2=0.6 \text{ mm,}$$

does not meet requirements of the drawing.

Thus, change of datums increases error (tolerance) of the obtained size ( $K_3$ ) by the error (tolerance) of the size ( $A_1$ ) between these datums.

The need to change manufacturing datums occurs when the workpiece must be machined on different manufacturing systems. The need to change manufacturing datums arises when the machined workpieces have significant residual stresses. In this case, firstly rough machining of the most surfaces is performed, which causes deformation of the workpiece due to redistribution of residual stress. Then rough machining is usually followed by annealing or natural aging to ensure elimination of residual stress and stabilization of dimensions and shape of the workpiece. Afterwards, finish machining of surfaces that would be used as manufacturing datums is performed.

It should be noted that along with the intentional change of datums throughout manufacturing process, a random change of datums may occur. For example, this change can take place during clamping of a prismatic workpiece in vices (Fig. 5.7). The upper surface of the workpiece is machined to make it parallel to the bottom surface B. Because of non-perpendicularity of the guiding datum (plane A) to the plane datum (plane B), non-perpendicularity of the working surface of a movable jaw to its guideways and because of clearance between the jaw and the guideways (Fig. 5.7, *a*), the workpiece will rock due to clamping force  $P_3$  and take position shown in Fig. 5.7, *b*. The datums are accidentally changed: the plane A becomes a plane datum and plane B becomes a guiding datum. After machining, the plane C would be non-parallel to the plane B (Fig. 5.7, *b*).




Fig. 5.7 Change of datums during clamping of a workpiece in vices

The principle of permanent datums is fully implemented in machining performed with a single set-up, when the unmachined surfaces are used as the datums. In this case, errors of sizes between the machined surfaces and errors of the surfaces location are practically independent of the error of workpiece mounting. This allows achieving the highest accuracy.

It should be noted that one of the motives for the creation of such machine tools as "machining center" was to ensure that the machining of complex workpieces with a minimum number of setups. Such machines, which allow machining of workpiece from different sides and by different methods, not only reduce influence of mounting errors on machining accuracy, but also reduce the time required for machining by reducing the number of setups.

Principle of permanent datums can be ensured by the application of artificially created datums (center holes in workpieces for shafts, special high precision holes in housings workpieces, various bosses, etc.).

**Principle of coincident datums.** *In accordance with the principle of coincident datums, it is essential to choose the surfaces from which the functional dimensions are specified as manufacturing datums.* Such surfaces can be presented by the functional datums (primary and auxiliary) of the part and by its free surfaces, which are not in contact with any other components in the product.

Let's show the advantages provided by the implementation of the principle of coincident datums on an example.

Milling of a shoulder of a prismatic workpiece, performed on the preliminary set to the required dimension machine (Figure 5.8), should ensure functional dimension  $K$ , which is specified from the upper plane  $I$  of the workpiece. Let's consider two variants of the workpiece locating.




Fig. 5.8 Diagrams of milling a shoulder on a prismatic workpiece

In the first variant (Figs. 5.8, *a*) the lower plane *II* is used as a plane datum, which determines position of the workpiece in a vertical direction. In milling of the shoulder, the manufacturing dimension  $A_2$  is obtained; manufacturing dimension  $A_1$  was obtained on the previous operation. Thus the functional dimension  $K$  is the resulting dimension in the manufacturing dimensional chain with  $A_1$ ,  $A_2$  and  $K$ . In order to ensure its accuracy it is necessary that  $TK \geq TA_1 + TA_2$ , i.e. tolerances of the manufacturing dimensions must be much smaller than the tolerance of the functional dimension. If the functional dimension  $K$  is assigned a tight tolerance, then ensuring of dimensions  $A_1$  and  $A_2$  (which tolerances are even tighter) may be difficult due to need for frequent adjustment of the machine tool, tool change, etc. or even practically impossible.

In the second variant (Fig. 5.8, *b*) the plane *I* is taken as a manufacturing plane datum. In milling of the shoulder, the manufacturing dimension  $A_3$  is obtained, which coincides with the functional dimension  $K$ . In other words, the functional dimension  $K$  is obtained directly. The condition of ensuring accuracy of the functional dimension is  $TK \geq TA_3$ .

Thus, the coincidence of manufacturing datums with surfaces (or axes) of parts, from which functional dimensions are set, helps to ensure their accuracy in the shortest route, ensuring minimal manufacturing costs.

It should be noted that the tolerance of the dimension that connects the surface from which the functional dimension is given with the manufacturing datum ( $TA_1$  for the given example) is called an error of noncoincidence of datums. It is clear that, on a pre-set machine tool, it is impossible to obtain a functional dimension with an error less than the error due to noncoincidence of datums.

It should be borne in mind that implementation of the principle of coincident datums is rather difficult. The surfaces, from which functional dimensions are specified, may have insufficient dimensions that, when they are used as manufacturing datums, can cause large errors of workpiece mounting. In some cases complex fixtures for mounting of workpieces can be needed. For example, to implement the locating scheme shown in Fig. 5.8, *b*, a fixture in which clamping forces directed upwards is required.

It should be noted that if workpieces (fig. 5.8, *a*) are machined with trial cuts method, the functional dimension  $K$  will be obtained directly.

In accordance with the principle of coincident datums, manufacturing datums should be also coincident with measuring datums, because otherwise error of measurement of a workpiece (or a part) will inevitably increase.



### 5.6.2 Selection of Manufacturing Datums for the First Operation

On the first operation (or several first operations) of the process, as already noted, surfaces, which further would serve as manufacturing datums, are machined. On the first operation unmachined surfaces are inevitably used as manufacturing datums. To ensure the highest possible accuracy these surfaces must have sufficient dimensions, more accurate form and location relative to other surfaces of the workpiece, as well as the smallest surface roughness. The surfaces of risers, sprues (castings), flash lines (forgings), etc. should not be used as manufacturing datums on the first operation.

It should be stressed that, because of poor accuracy and surface roughness of unmachined surfaces their use as manufacturing datums leads to a significant error of workpiece mounting. Therefore, unmachined surfaces should be used as manufacturing datums only once – on the first operation.

Selection of manufacturing datums for the first operation influence on:

- location accuracy of the workpiece surfaces with respect to the machined ones;
- allocation of allowances between individual surfaces of the workpiece.

The requirements for accuracy of location of unmachined surfaces relative to machined ones, i.e. accuracy of a dimension between these surfaces and accuracy of their location are defined by the functional purpose of the part (parameters of its strength, rigidity, dynamic balance, etc.).

*To achieve the highest accuracy of location of unmachined surfaces relatively to the machined surfaces, which are used as manufacturing datums, it is needed to use unmachined surfaces on the first operation.*

For example (Figure 5.9), to ensure the most accurate position of the housing shoulders *I* that do not undergo machining, relative to the bottom plane *II*, the surfaces of the shoulders should be taken as a manufacturing datum for the first (milling) operation.





Fig. 5.9 Milling of a bottom part of a housing

Selection of datums on the first operation determines how uniform the allowances for machining would be. It is particularly important to obtain uniform allowances for machining of inner surfaces (holes, grooves, etc.) which machined by tools of low rigidity. Indeed, the higher, for example, is the uniformity of allowance for hole machining, the more cutting passes, processing steps or operations is required for machining and the lower is the productivity and higher is the cost. In some cases, uniform allowance is needed to achieve high quality of the surface layer.

*To ensure the most uniform allowance for machining of individual surface, this surface should be used as manufacturing datum for the first operation.*

To illustrate this situation let's consider the example of machining of a lathe bed (Figure 5.10). Typically, the machine tool beds are cast with the bed guideways oriented downwards to get dense and homogeneous layer of metal. To save this layer and provide high wear resistance of guideways it is needed to remove small and uniform allowance from these surfaces. For this purpose, the guideways surfaces are used as manufacturing datums on the first operation (Fig. 5.10, *a*) and the highest, uneven allowance is removed from the surface of bed legs. On the next operation (Figure 5.10, *b*), surfaces of the legs are manufacturing datums, which makes it possible to remove uniform allowance from the guideways. Clearly, if the manufacturing datums on the first operation are legs surfaces, then the uneven allowance will be removed from the guideways. This will result in uneven wear of the machine guideways along the length during the operation of the machine tool.



*Fig. 5.10 Diagrams of lathe bed machining*

As can be seen from the above, selection of datums on the first operation influences the most important technical and economic characteristics of the manufacturing process. In this regard, the question of datum selection on the first operation should always be given due attention.

It should be emphasized that there is no such location on the first operation which would provide the most accurate position of the unmachined surfaces with respect to the machined surfaces and equal allocation of allowances for every surface of the workpiece. One variant of location will ensure higher

accuracy of the size between unmachined and machined surfaces and accuracy of their location, the other variant provides a more uniform allocation of machining allowances. Therefore there is a need to consider several variants of location on the first operation and choose the most appropriate. The easiest way this can be done is to use methods of tolerance analysis of manufacturing processes.

The procedure of selection of a workpiece location scheme on the first operation is considered on an example that follows. Suppose that the manufacture of the part, the sketch of which is shown in Fig. 5.11, *a*, should ensure functional dimensions  $K_1$ ,  $K_2$ ,  $K_3$  and  $K_4$ , while ensuring the smallest fluctuation of allowance for boring of the hole in vertical direction. The initial workpiece is produced by sand casting; its sketch with relevant dimensions is shown in Fig. 5.11, *b*. The surfaces *I* and *II* of the housing (Fig. 5.11, *a*) require no machining.

Consider two variants of workpiece machining. In both variants the first operation (Figs. 5.11, *c* and *d*) is milling of the lower plane. On the second operation, which is boring of a hole (Fig. 5.11, *e*), this plane is used as a plane datum. The difference consists only in datums selected for the first operation. In the first case the position of the workpiece in the vertical direction is determined by the plane datum (unmachined plane *I* of the shoulders), in the second case – by the double-guide datum (axis of the hole by which the workpiece is mounted on a cam-mandrel).




Fig. 5.11

Let's analyze how the datum selection on the first operation will influence accuracy of the functional dimensions and fluctuation of allowance for boring of the hole. To this end, let's construct dimensional diagram and graphs of the manufacturing dimensional chains for the first and the second variants, as shown in Fig. 5.12 and 5.13.

According to the dimensional diagrams or graphs (the latter makes analysis easier) let's find the manufacturing dimensional chains, in which the resulting dimensions are the functional dimensions that are of interest to us and allowance.




Fig. 5.12

In the first case (see Fig. 5.12, *a* and *b*), functional dimensions  $K_2$ ,  $K_3$  and  $K_4$  coincide with the manufacturing dimensions  $A_1$ ,  $A_3$  and  $A_2$ , that is ensured directly. The functional dimension  $K_1$  and allowance for boring of the hole  $I$  are resulting dimensions in the manufacturing dimensional chains, shown in Figs. 5.12, *c* and *d*. Three component dimensions of these chains are dimensions of the initial workpiece and, therefore have relatively large tolerances. Tolerance of the dimension  $K_1$  will be

$$TK_1 = TA_{01} + TA_{02} + TA_{04} + TA_1 + TA_2,$$

and tolerance (fluctuation) of the allowance  $Z$  is

$$TZ = TA_{02} + 0.5 \cdot TA_{03} + TA_{04} + TA_1 + TA_2 + 0.5 \cdot TA_3$$




Fig. 5.13

In the second variant of machining (see Fig. 5.13, a and b) the functional dimensions  $K_3$  and  $K_4$  are ensured directly, coinciding respectively with manufacturing dimensions  $A_3$  and  $A_2$ . The functional dimension  $K_1$  and allowance  $Z$  are resulting dimensions in a much shorter manufacturing dimensional chains, shown respectively in Fig. 5.13, c and d. Only one of the component dimensions of these chains is the dimension of the initial workpiece. Tolerances of dimension  $K_1$  and allowance  $Z$  are

$$TK_1 = TA_{01} + TA'_1 + TA_2;$$

$$TZ = TA'_1 + TA_2 + 0.5 \cdot TA_{03} + 0.5 \cdot TA_3.$$

Functional dimension  $K_2$  is the resulting dimension in the manufacturing dimensional chain shown in Fig. 5.13,  $e$ ; its tolerance is

$$TK_2 = TA_{02} + TA_{04} + TA'_1.$$

For example, if we assume that the tolerances of all dimensions of the initial workpiece (castings) are 1.0 mm, the tolerances of all dimensions obtained during machining are 0.2 mm, then for the first variant we will get  $TK_1=3.4$  mm,  $TZ=3.0$  mm,  $TK_2=0.2$  mm, and for the second variant –  $TK_1=1.4$  mm,  $TZ=1.0$  mm,  $TK_2=2.2$  mm.

Thus, the second variant of machining when compared to the first one allows considerably higher accuracy of the dimension  $K_1$ , smaller fluctuation of allowance  $Z$  for boring the hole, but less accuracy of the dimension  $K_2$ . When it is considered that from the point of functionality of the part, there usually is no high requirement for the accuracy of the dimension  $K_2$ , then the second variant of machining (Variant of location of the workpiece on the first operation) should be considered preferable.

### 5.6.3 Selection of Manufacturing Datums for most Operations

Selection of manufacturing datums on the most of the operations of a manufacturing process should be guided by the principles of permanence and coincidence of datums discussed above. However, as already noted, the simultaneous application of these principles is often impossible.

The most fully the principles of permanence coincidence of datums can be realized when all the functional dimensions of a part are given from the same surfaces. Most often, the primary datums of a part are used as these surfaces. These surfaces should be machined on the first operation (several first operations) and then used as manufacturing datums for the majority of manufacturing process operations.

Not only the principles of permanence and coincidence of datums should be observed, but it is also needed to reduce the number of workpiece set-ups during the manufacturing process, keeping in mind that each set-up, even if the manufacturing datums are unchanged, is accompanied by errors and decrease in machining accuracy.

If the datums are changed, the most accurately machined surfaces with the most accurate position relative to the previously used datums should be chosen as new datums. Thus, as already mentioned, the attention should be paid to accuracy of surfaces location first, and then to dimensional accuracy of parts.

## 5.7 Selection of Machining Routes for Individual Surfaces of a Part

At this stage of manufacturing process planning routes for machining of individual surfaces of a part are outlined, i.e. the list of sequentially executed processing steps or operations to achieve specified accuracy of the surfaces and quality of their surface layers is defined.

To solve the task tables of recommended routes can be used. Examples of routes for machining of outer cylindrical surfaces are shown in Table 5.3.

Arrows in Table 5.3 indicate that this set of routes can be moved into the columns of the coarser accuracy grades. For example, if the machining of external cylindrical surfaces with accuracy of IT 14-12 (first column) should ensure relatively small surface roughness ( $Ra=2.5$  micron), then it is possible to use a set of routes from the second column, which ensure this requirement.

As can be seen from Table 5.3 the number of possible routes of machining of individual surfaces can be quite large. It can be cut, taking into account a number of considerations. These include the possibility to machine a given surface on the same machine, the need to machine several surfaces in a single set-up to achieve the required accuracy of their location, limited possibility to use certain methods of machining due to low rigidity of parts.

Table 5.3

## Exemplary machining routes for external cylindrical surfaces [10]

Sequence of processing steps (operations) to obtain accuracy grade						Roughness, $\mu\text{m}$
<i>IT 14- IT 12</i>	<i>IT 11- IT 10</i>	<i>IT 9- IT 7</i>	<i>IT 6</i>	<i>IT 5</i>	<i>IT 4- IT 3</i>	
1, 2, 3 <b>O</b> 4 <b>O</b> , HT 1 <b>G</b> 4 HT, <b>G</b>						$R_z=80\div 20$
←	1, 2, 3 Op, <b>Of</b> 1, 2 O, <b>G</b> 4 Op, <b>Of</b> , HT 4 Op, HT, <b>G</b>					$R_z 20-R_a 2.5$
←	←	1, 2, 3 Op, Of, <b>Os</b> 1, 2 O, <b>G</b> 1 Gp, <b>Gf</b> 4 O, HT, <b>G</b> 4 Gp, HT, <b>G</b>				$R_a=1.25\div 0.63$
←	←	3 Op, <b>Of</b> , PO 3 <b>O</b> , POp, POf 3 O, Of, <b>Os</b>	1, 2, 3 Op, Of, <b>Os</b> , PO 1 O, Gp, Gs, PO  1 O, <b>G</b> , S 4 O, Gp, HT, <b>Gs</b> 4 O, Gp, HT, <b>Gs</b> , C 4 O, HT, <b>Gf</b> , C	4 Op, Of, HT, <b>Gf</b> , S 4 O, Gp, HT, <b>Gf</b> , <b>Gs</b> , S 4 O, Gp, HT, <b>Gf</b> , L 3 O, Of, <b>Or</b>		$R_a=0.32\div 0.16$
		3 Op, <b>Of</b> , POp, POf 3 Op, Of, <b>Os</b> , POf, POs  4 Op, HT, Gp, <b>Gs</b> , PO	←	1 Op, Of, Gp, <b>Gf</b> , Sp, Sf 4 Op, Of, HT, <b>Gf</b> , Sf 4 Op, Of, HT, <b>Gf</b> , Gr, L 4 Op, Of, HT, <b>Gf</b> , Lp, Lf 4 G, HT, <b>G</b> , Sp, Sf		$R_a=0.08\div 0.04$
			←	←	4 Op, Of, HT, <b>Gf</b> <b>Gs</b> , Lp, Lf, Ls 4 G, HT, Gp, <b>Gs</b> , Lp, Lf, Ls	$R_z=0.1\div 0.025$

Notation: O – turning; G – grinding; S – superfinishing; PO – polishing; L – lapping; HT – heat treatment; p – preliminary; f – finishing; s – fine; 1 – soft steels; 2 – cast irons; 3 – non-ferrous metals and alloys; 4 – hardenend steels.

Note. Operations given in boldface font form the location errors.



Having decided how to machine the each surface, the manufacturing engineer begins the designing of the manufacturing route.

### **5.8 Design of Manufacturing Process Route. Selection of Manufacturing Equipment and Operations**

Manufacturing process route is designed on the basis of the selected routes of machining of individual surfaces, as well as previously established method of production, method of workpiece production and manufacturing datums.

In determining the sequence of a workpiece machining, decisions are guided by the following principles. In the first place, the surfaces, taken as manufacturing datums for the majority of operations, are machined. Then the surfaces that can incorporate latent defects of the initial workpiece (shrinkage cavities, pores, cracks, etc.) are machined. In the presence of such defects, further machining of the workpiece is not performed; the workpiece is either rejected or reworked to eliminate the defects. Next, the rest of the surfaces are machined in the sequence reverse to their accuracy: the more accurate the surface should be, the later in the process it is machined. At the end of the process, the surfaces that are prone to damage, such as external threads, are machined.

The machining of precision components for critical applications are often divided into stages: roughing, finishing and superfinishing, which are performed on different machines. During the roughing, the most of the metal is removed in the form of allowances, which leads to relatively large errors of the workpiece due to the redistribution of the residual stresses, elastic deformations of the technological system due to cutting forces and temperature deformations of the system. During the finishing these errors are reduced. The purpose of the semifinishing process is to achieve required accuracy of the part and quality of its surface layers.

It should be emphasized that dividing of the process into the described stages is dictated not only by the need to ensure required accuracy of the part, but also by the need to use high-precision machine tools for finishing operations only.

At the same time, this dividing of the process is not always a must. Thus, for a workpiece of high accuracy, sufficient rigidity and without significant residual stresses, roughing and finishing treatments can be successfully performed on the same operation.

During the manufacture of precise parts, particularly of a complex shape and small rigidity cutting operations alternate with stabilizing heat treatment

(annealing in most cases). This reduces residual stresses, stabilizes the metal structure and helps to achieve required accuracy of the part.

If the part is to be hardened, the manufacturing process is divided into two parts that are performed before and after the heat treatment. Prior to hardening, machining is typically performed with cutting tools, after hardening - mainly by abrasive tools.

The designing of a manufacturing process is closely related to the choice of manufacturing equipment (machine tools, fixtures, tools).

Selection of machine tools is primarily dictated by the need to make surfaces of corresponding configuration and to meet the requirements for accuracy of size, form, location, and roughness. If it is possible to perform this on the different machine tools, the choice is made by considering the following factors:

- correspondence of the machine tool dimensions to the dimensions of the workpiece;
- correspondence of the machine productivity to the volume of production (method of production);
- possibility to use full horsepower of the machine without downtime;
- possibility to ensure the lowest labour costs and cost of manufacturing.

In job production the universal machine tools with manual control are typically used, for example, lathes, vertical turret lathes, radial and vertical drilling machines, vertical and horizontal milling machines, planners, slotters, cylindrical grinding machines, etc. In small-batch and medium-batch production the less versatile but more productive machine tools with automated control are used: semi-automatic turret lathe, semi-automatic single and multiple-spindle drilling machines, CNC lathes, CNC drilling machines, etc. The machine tools used in large-batch and mass production are characterized by specialization, high performance and a high degree of automation. These machines include semi-automatic and automatic multi-spindle lathes, modular machine tools, specialized automatic grinding machines, etc. Under conditions of these methods of production, automated production lines are widely used: flexible production lines composed of CNC machines are used in large-batch production; hard production lines composed of modular and special-purpose machines are used in mass production.

Along with the choice of the machine tools, it is needed to determine types of fixtures required and select cutting and measuring tools. If the fixtures are part of the machine (chucks, vise, rests), then only its name is specify. If a universal modular fixture is used, then the manufacturing engineer makes an appropriate indication. When the machining operation requires a

special fixture, the manufacturing engineer usually develops only its conceptual design, development of a design is made by a design-engineer. In job and small-batch production, universal fixtures (vice, universal dividing heads, rotary tables, etc.) as well as universal modular fixtures are mainly used; special fixtures are mainly used in large-batch and mass production.

Selection of cutting tools is defined by a model of a machine tool, part material (workpiece), part shape and size, required accuracy and quality of surface layers and method of production. Usually cutting tools are limited to standard and normalized cutting tools. In some cases, especially in large-batch and mass production, special cutting tools may be required such as: form cutters, form milling cutters, broaches, etc., which must be designed and manufactured.

Selection of measuring instruments is defined by the size and configuration of a part, its accuracy, and quality of surface layers and method of production. Measuring instruments must be capable of measuring linear dimensions of 1 to 500 mm with a permissible error of measurement according to GOST 8.051-81. Thus, for example, for tolerances of *IT*14 and *IT* 6, this error should not exceed 20 and 30%, respectively, of the tolerances. Furthermore, if, for example, in job and small-batch production inspection of diameters of external cylindrical surfaces is made with vernier calipers, micrometers or dial snap gauges, then in large-batch and mass production the limit gauges, which ensure higher performance of inspection, are used. Currently, complex inspections of parameters of accuracy are commonly made with the help of the coordinate measuring machines.

Machining operations a composed of those processing steps (contained in the routes selected for machining of different surfaces) which can be implemented on one machine. Moreover, workpiece surfaces with high accuracy of mutual position are desired to machine in a single set-up. Machining of splines, teeth (of gears), non-circular holes and other elements that require special cutting tools is set as separate operations.




Fig. 5.14 Part sketch




Fig. 5.15 Sketches of workpiece machining:  
a – the first operation; b – the second operation

During designing of operations, the possibility of combining the processing steps, overlapping machining time with auxiliary, the feasibility of a multiple machining is analyzed. In mass production, operations are composed so that the time needed for their execution is equal to or a multiple of the Takt time.

The sequence of processing steps in an operation relates to the method of dimensioning of the part on the drawing. For example, if the functional dimension are set as shown in Fig. 5.14, then it the machining should be performed as shown in Fig. 5.15 ( $A_i$  – manufacturing dimensions). On the first operation (performed on a CNC lathe) it is necessary to machine face A first, then faces B and C; the second operation (also performed on a CNC lathe) should start with the machining of face F, and then faces E and G. Such sequence of processing steps in the operation allows all functional dimensions to be ensured directly and dimensional accuracy to be ensured at the lowest cost.

## 5.9 Tolerance Analysis of Developed Manufacturing Process

Tolerance analysis includes the following steps:

- determination of tolerances for manufacturing dimensions;
- determination of minimum machining allowances;
- calculation of manufacturing dimensions.

### 5.9.1 Identification of Tolerances for Manufacturing Dimensions

Tolerances of workpiece dimensions are defined with the help of the relevant standards and reference materials.

Tolerances of dimensions, obtained on the machining operations are determined using the tables of accuracy. The most complete tables of accuracy are given in the book [10]. Extracts from these tables are given in Table 5.4. It presents, as an example, statistical data on errors of the workpiece dimensions ( $\omega_c$ ) machined on various turning machines. The errors are given for different groups of sizes. For example, for turret lathes the dimensions are divided into three groups:

- obtained from manufacturing datums;
- obtained from a novel datum<sup>†</sup> by using cutters set at different positions;
- obtained between the cutters set in a single holder.

Table 5.4

*Average error of machining ( $\omega_c$ )*

Type of operation	Machine tools	Method of ensuring accuracy	Pass	Accuracy		
				of diameters <i>IT</i>	of axial dimensions depending on their basic sizes, mm	
					to 80	80...260
Turning	Lathe	By preliminary set to dimension handwheel dial with the help of a toolpost	I	12...13	0.30	0.40
			II	10	0.12	0.20
	Precision lathe	The same	I	8...9	0.08	0.10
			II	6...7	0.04	0.054
	CNC lathe	By program	I	11	0.20	0.25
			II	10	0.12	0.17
	Vertical turret lathe	By a handwheel dial set to dimension	I	12...13	0.25	0.30
		By stops	II	8...9	0.07	0.10

<sup>†</sup> The term "novel datum" is used in engineering literature to designate a surface that is being machined on the given set-up and is connected by the functional dimension with the relevant manufacturing datum from which other manufacturing dimensions are ensured (on the same set-up). For example (see Fig. 5.16), the "novel datum" is the workpiece face *I*, which is connected by dimension  $A_1$  with the manufacturing datum from which the manufacturing dimension  $A_2$  is ensured.

Type of operation	Machine tools	Method of ensuring accuracy	Pass	Accuracy		
				of diameters <i>IT</i>	of axial dimensions depending on their basic sizes, mm	
					to 80	80...260
Production lathe	By stops		I	11	0.15	0.20
			II	8...9	0.06	0.08
Turret lathe	By stops from datums		I	12...13	0.25	0.30
			II	10	0.15	0.17
	From a datum between positions		I	12...13	0.30	0.35
			II	11	0.20	0.25
	Between cutters in a single holder		I	12...13	0.12	0.17
			II	10	0.08	0.10
Semi-automatic vertical multi-spindle lathe	By templates and stops from datums		I	12...13	0.20	0.25
			II	10	0.12	0.15
	Between cutters in a single holder		I	11	0.17	0.20
			II	8...9	0.08	0.10
	Between cutters from different tool slides and positions		I	12...13	0.20	0.25
			II	10	0.15	0.20
Swiss-type automatic screw machine	By a template from a datum		I	10	0.12	0.17
			II	7...8	0.08	0.10
	Between cutters from different tool slides		I	10	0.10	0.12
			II	7...8	0.06	0.08

Indeed, the errors for the given groups of dimensions would be different.




Fig. 5.16 Schematic illustration of faces machining


Fig. 5.16 shows a diagram of machining two faces of a workpiece by cutters mounted in a single holder. The error of workpiece clamping  $\varepsilon_3$  will directly be included into the error of the size  $A_1$ , ensured from the manufacturing datum, and will not practically influence on error of the size  $A_2$ , which is obtained as between the cutters. Wear of the right cutter and its elastic deflections will directly affect error of the size  $A_1$ . Combined effect of wear of the cutting tools and their elastic deflection on error of the size  $A_2$  will be significantly lower. If, for example, assume that the wear of both cutters is identical, the wear generally will not influence the error of the size  $A_2$ . Thus, in general, the error of the size  $A_2$  will be much lower than the error of the size  $A_1$ .

If cutting of the workpiece face 1 (see Fig. 5.16) is performed on one position of the lathe turret, and cutting of a face 2 – performed on the other position, then the error of the size  $A_2$  will be affected by the error of turret indexing. Therefore, the error of the size  $A_2$ , which in this case should be referred to the second group of dimensions, will be significantly greater than its error in situation of simultaneous facing of the surfaces 1 and 2.

Such groups of sizes are specified for the operations performed on the other machines, thus enabling to define tolerances of the manufacturing dimensions in the most reasonable way.

It should be emphasized that the tables of accuracy were built for conditions when the locating error is zero ( $\varepsilon_l=0$ ) and spatial errors of manufacturing datums are minimal ( $\rho_d \cong 0$ ). These conditions can not be observed in the real manufacturing process. In this regard, let's consider procedure of determining allowances for manufacturing dimensions in more detail, using particular examples.

**Example 1.** Fig. 5.17 shows facing and boring of a workpiece, which are performed on the first (turning) operation of the manufacturing process. The workpiece that arrive to this operation has significant spatial variations  $\rho_d$  of the manufacturing datum, from which the size  $A$  is obtained, and significant variations of the hole as well.



*Fig. 5.17 Facing and boring performed on the first operation*

In this case, it is impossible to ensure dimension A with error lesser than  $\rho_d$ , neither on a pre-set machine tool nor trial-cuts method. Therefore, value of  $\rho_d$  should be included into the tolerance of the dimension A:

$$TA_1 = \omega_{s_1} + \rho_d,$$

where  $\omega_{s_1}$  is the statistical error of the dimension A found from the tables of accuracy. Value of  $\rho_d$  is determined by the relevant standards for workpieces.

Tolerance of the bored hole diameter D is assumed to be equal to the statistical error  $\omega_{s_2}$ , as the tables of accuracy themselves were obtained for conditions when the machined surfaces also have significant spatial variations.

**Example 2.** Fig. 5.18 shows a diagram of milling a slot in a plate. Manufacturing datums include its bottom plane and two holes perpendicular to this plane. In such setup scheme, as indicated in Section 3, there is an locating error  $\varepsilon_l$  in the direction of the dimensions obtained on this operation. This error is equal to the maximum clearance in the coupling of a cylindrical pin with the left hole.






Fig. 5.18 Milling a slot in a plate

During machining on the pre-set machine, it is impossible to ensure the dimension  $A_1$  with an error smaller than the locating error. Therefore, the  $\varepsilon_1$  must be included into the tolerance of the dimension  $A_1$ :

$$TA_1 = \omega_{s_1} + \varepsilon_1.$$

The accuracy of the dimension  $A_2$  will not be affected by the locating error  $\varepsilon_1$ . Tolerance of  $A_2$  will be

$$TA_2 = \omega_{s_2}.$$

**Example 3.** Fig. 5.19 shows a diagram of grinding the outer surface of a sleeve, mounted with a clearance on a solid cylindrical mandrel. During the operation there is a locating error in the radial direction  $\varepsilon_1$ . However, the  $\varepsilon_1$  will not influence accuracy of the diameter  $D$  directly and its tolerance can be taken equal to the statistical error, i.e.  $TA_2 = \omega_{s_2}$




Fig. 5.19 External turning of a barrel, mounted with clearance on a cylindrical mandrel

Based on the above stated, the rules for allocation of tolerances for manufacturing dimensions using the tables of accuracy can be summarized as follows:

- *diametrical tolerances as well as tolerances for dimensions between the surfaces, machined with a single set-up, can be taken equal to the statistical error;*
- *tolerances for the dimension ( $A_i$ ) between a machined surface and manufacturing datum and can generally be identified by the formula*

$$TA_i = \omega_{s_i} + \rho_1 + \varepsilon_1.$$

When using the latter rule one should keep in mind that the other components of the mounting error (clamping error and error of a fixture) are included in the  $\omega_{s_i}$ , since the tables of accuracy made for the conditions when these error take place.

It should be noted that in some cases the larger tolerances for manufacturing dimensions, compared to the values identified with the tables of accuracy, can be used. Enlarged tolerances of the manufacturing dimensions help to reduce operational costs (it makes it possible to work with higher cutting parameters, reduce cost of setting and adjusting the machine tools, reduce the required qualification of workers, etc.). However, wider tolerances lead to the higher average value of machining allowances and, as a consequence, increase in the dimensions of the workpiece and its cost. Therefore, enlarged tolerances of the manufacturing dimensions should be used with due caution, taking into account all the costs of part production.

### 5.9.2 Identification of Minimum Tolerances for Manufacturing

Allowances for machining are divided into total and intermediate allowances. Total allowance is needed for all processing steps of machining of a given surface, and intermediate allowance is needed to perform separate processing step. Below, the term "allowance" shall mean an intermediate allowance.

It is accepted to distinguish between the minimum, maximum, average, and nominal value of an allowance for machining. However, the minimum allowance is the primary value, since it defines other categories of allowance.

The minimum allowance should be of value so that its removal was sufficient to ensure accuracy and surface layer quality of the machined surface.

Minimum allowance  $z_{i_{\min}}$  for machining can be defined by two methods: normative and calculation-analytical.

With the *normative method*, values of  $z_{i_{\min}}$  are found directly from the tables, which are made by compiling and organizing production data. This method is very simple and has been widely spread in mechanical engineering. The main drawback of the normative method is the incomplete account of the specific features of the operation (processing step). The values of allowances defined by the normative method are usually too large.

With the *calculation-analytical method*, proposed by prof. V.M. Kovan,  $z_{i_{\min}}$  is found by summing individual components that can more fully take into account specific conditions of machining. In this case, the following factors that determine the value of the minimum allowance are distinguished.

1. *The surface roughness  $Rz_{i-1}$  obtained on the previous processing step (operation) of surface machining.*

During the first operation the surface roughness of the workpiece must be removed. During the second operation the surface roughness obtained in the first operation must be removed, etc.

2. *The thickness of defective surface layer  $h_{i-1}$  generated on the previous processing step (operation) of surface machining.*

For instance, surface layer of steel workpieces produced by hot working (rolling, stamping, forging) is decarbonized. Decarbonized layer is also generated during heating of the steel workpieces prior to hardening. Obviously, this layer must be removed during the subsequent machining. Castings made of gray cast iron generate the so called pearlitic skin with high hardness and traces of the molding sand. The satisfactory machining of workpieces by cutting tool is possible only if the cutter point is beneath the pearlitic skin. Processes of machining, especially at relatively elevated cutting parameters, create highly deformed surface layer with microscopic cracks, this layer is also must be removed during the subsequent finishing operation.

3. *Error of form of the machined surface  $\rho_{f_{i-1}}$  obtained on the previous processing step (operation), in case this error is not included in the tolerance of the corresponding dimension.*

For example, if the workpiece of a shaft is curved (Fig. 5.20, *a*), then this error won't be detected with the help of a vernier caliper, a micrometer, etc. during the measurement of the diameter in any section of the workpiece. Thus, this form error  $\rho_{f_{i-1}}$  won't be included in the workpiece diameter tolerance and must, therefore be compensated as a portion of the minimum allowance for machining. As follows from Fig. 5.20, *a*, to obtain the diameter  $D_i$  of the workpiece after machining, the diameter  $D_{i-1}$  prior the machining should be at least

$$D_{i-1} = D_i + 2\rho_{f_{i-1}}.$$




Fig. 5.20 Scheme of workpieces machining that illustrate influence of form error of the machined surface on the value of the minimum allowance

In other words, to compensate for the form error, the additional component  $2\rho_{f,i-1}$  should be included into the minimum allowance.

Fig. 5.20, *b* shows a diagram of facing a workpiece on a lathe. Dimension  $A_{i-1}$  is inspected with the help of limit gauges. Obviously, this method of inspection won't detect the flatness error  $\rho_{f,i-1}$ , i.e. it won't be included in the tolerance of the dimension  $A_{i-1}$  and, thus should be included into the minimum allowance for facing.

4. Error of the machined surface location relative to the manufacturing datums  $\rho_{L,i-1}$ , which arose on the previous processing step (operation).

Fig. 5.21, *a* shows turning of a shaft, clamped in centers. When these center holes are drilled there is always an inevitable eccentricity of their axis I-I with respect to the axis II-II of the shaft  $\rho_{L_{i-1}}$ . As can be seen from Fig. 5.21, *a*, that to obtain diameter  $D_i$  of the workpiece after machining, the diameter  $D_{i-1}$  prior the machining should be

$$D_{i-1} = D_i + 2\rho_{L_{i-1}},$$

i.e. the error of the machined surface location relative to the manufacturing datums should be compensated by a portion of the minimal allowance for turning, which is  $2\rho_{L_{i-1}}$ .

Fig. 5.21, *b* shows boring of a hole in a sleeve clamped in a three-jaw chuck. Axis of the hole (prior to boring) I-I is shifted relatively to the axis of external surface II-II by the value of  $\rho_{L_{i-1}}$ . Obviously, that to obtain diameter  $D_i$  after boring, the diameter  $D_{i-1}$  prior the boring should be at least

$$D_{i-1} = D_i - 2\rho_{L_{i-1}}.$$

Thus, the error of the hole location relative to the outer surface of the sleeve (manufacturing datum) should be compensated by a portion of the minimal allowance for machining, which is equal to  $2\rho_{L_{i-1}}$ .

Fig. 5.21, *c* shows machining of the workpiece face, which is not perpendicular to the workpiece axis used as a manufacturing datum. Measuring of the dimension  $A_{i-1}$  is performed with a vernier caliper. Therefore, error of the face location relative to the workpiece axis  $\rho_{L_{i-1}}$  is not included in the tolerance of the dimension  $A_{i-1}$  and, thus should be included into the minimum allowance for facing.




Fig. 5.21 Scheme of workpieces machining that illustrate influence of form error of the machined surface on the value of the minimum allowance

5. Error of the workpiece mounting on the given processing step (operation)  $\varepsilon_{y_i}$ .

Fig. 5.22, *a* shows turning of a workpiece clamped in a three-jaw chuck. There is a mounting error in radial direction  $\varepsilon_{y_i}$ , which is equal to the clamping error  $\varepsilon_{3_i}$ . As follows from the scheme to obtain diameter  $D_i$  of the workpiece by the turning, the diameter  $D_{i-1}$  prior the machining should be

$$D_{i-1} = D_i + 2\varepsilon_{3_i}.$$

Thus, the error of workpiece clamping should be compensated by a portion of the minimum allowance for turning that is equal to  $2\varepsilon_{3_i}$ .




Fig. 5.22 Scheme of workpieces machining that illustrate influence of mounting error on the value of the minimum allowance

Fig. 5.22, *b* shows a diagram of turning of a sleeve mounted on a solid cylindrical mandrel. The sleeve is mounted with an error in the radial direction  $\varepsilon_{y_i}$ , which is equal to the locating error  $\varepsilon_{l_i}$ . As can be seen from Fig. 5.22, *b* to obtain workpiece diameter  $D_i$  by the turning, the diameter  $D_{i-1}$  prior the machining should be at least

$$D_{i-1} = D_i + 2\varepsilon_{l_i},$$

i.e. the locating error must be compensated by a portion  $2\varepsilon_{l_i}$  of the minimum allowance for turning.

When calculating the minimum allowance for machining of a plane, the mounting error shouldn't be included into tolerance value, since this error is included in the tolerance of the relevant manufacturing dimension.

Errors  $\rho_{f_{i-1}}$  and  $\rho_{L_{i-1}}$  are vector quantities. Their sum  $\rho_{i-1}$  is called a spatial deviation of the machined surface.

For surfaces of revolution the direction of the vectors  $\rho_{f_{i-1}}$  and  $\rho_{L_{i-1}}$  is unknown. The most probable location of these vectors is at right angles to each other, so these errors are summed according to the rule of the square root, i.e.

$$\rho_{i-1} = \sqrt{\rho_{f_{i-1}}^2 + \rho_{L_{i-1}}^2}.$$

For planes these vectors are collinear. Therefore

$$\rho_{i-1} = \rho_{f_{i-1}} + \rho_{L_{i-1}}.$$

Mounting error on the given processing step  $\varepsilon_{y_i}$  (for surfaces of revolution) is usually calculated by the equation

$$\varepsilon_{y_i} = \sqrt{\varepsilon_{L_i}^2 + \varepsilon_{3_i}^2},$$

where  $\varepsilon_{L_i}$ ,  $\varepsilon_{3_i}$  are errors of locating and clamping on the given processing step. Moreover, it should be borne in mind that the clamping error typically includes the fixture error as well, which is difficult to identify as a separate value.

The spatial deviations of the machined surface  $\rho_{i-1}$  and  $\varepsilon_{y_i}$  are also vector quantities and are also summed by the rule of the square root.

Based on the above stated the equations for minimum machining allowance can be written as follows:

- allowance for diameter in machining of surfaces of revolution

$$z_{i\min} = 2\left(Rz_{i-1} + h_{i-1} + \sqrt{\rho_{i-1}^2 + \varepsilon_{y_{i-1}}^2}\right);$$

- allowance for machining of a plane

$$z_{i\min} = Rz_{i-1} + h_{i-1} + \rho_{i-1}.$$

In particular cases, these equations are simplified. For example, for machining of a cylindrical surface of the workpiece mounted in centers, mounting error can be assumed to be zero. Allowance for diameter in this case is determined by the equation

$$z_{i\min} = 2(Rz_{i-1} + h_{i-1} + \rho_{i-1}).$$

In reaming of holes by a floating reamer, the latter aligns self with the hole axis. As a result, the spatial deviation of the machined hole  $\rho_{i-1}$  and the error of workpiece mounting  $\varepsilon_{y_i}$  should not be included in the minimum allowance. Its value (allowance for diameter) will be

$$z_{i\min} = 2(Rz_{i-1} + h_{i-1}).$$

Allowance for polishing of a plane with an elastic abrasive tool, which is used only to ensure low surface roughness,

$$z_{i\min} = Rz_{i-1}.$$



Almost all components of the minimum machining allowances are defined with the help of the normative reference materials; locating error is calculated.

### 5.9.3 Calculation of Manufacturing Dimensions

The initial data for calculation of manufacturing dimensions include: part drawing, type of the workpiece, manufacturing process, tolerances of the manufacturing dimensions and minimum machining allowances.

The calculation is performed in general terms of ensuring the following:

- minimum machining allowances ;
- functional dimensions that are not directly ensured during manufacture.

To calculate manufacturing dimensions the dimensional diagram and graph of the manufacturing dimensional chains are built.

The calculation process can be carried out by the maximum-minimum or statistical method. The maximum-minimum method is recommended for manufacturing dimensional chains with the number of component dimensions (manufacturing dimensions)  $n + p \leq 3$ , a statistical method is used for chains with  $n + p \geq 4$ .

Let us consider solution of tasks that can be found during the calculation of manufacturing dimensions.

**Calculation of manufacturing dimensions in order to ensure a minimum allowance for machining.** Fig. 5.23 shows a simple manufacturing dimensional chain. Component dimensions of the chain include dimension of the workpiece prior to machining  $A_2$  and its size after the machining  $A_1$  (obtained dimension), resulting dimension is the allowance for machining  $Z_1$ . Moreover, the obtained dimension  $A_1$  coincides with the functional dimension  $K_1$  or found from the previously considered manufacturing dimensional chain.




Fig. 5.23 Simplest manufacturing dimensional chain with an allowance as the resulting dimension

Thus, in the considered manufacturing dimensional chain, the basic size and limit deviations of one component dimension ( $A_1$ ) are known, the tolerance of the second component dimension ( $A_2$ ) is known as well as the minimum size of the resulting allowance, which is the allowance  $Z_1$ . It is needed to determine basic size and limit deviations of the component dimension  $A_2$ . Such a task can't be regarded as either direct or inverse task of the tolerance analysis and can be called a mixed task.

This task is typically solved by the maximum-minimum method using average values of the dimensions. The essence of the solution consists in the following.

1. Average value of the component dimension  $A_1$  ( $A_1=K_1$ ) is found

$$A_1^c = A_1 + \Delta_0 A_1 = A_1 + \frac{\Delta_u A_1 + \Delta_l A_1}{2}.$$

This component dimension is presented in the following form  $A_1^c \pm \frac{TA_1}{2}$ .

2. The average value of the allowance  $Z_1$  is found:

$$Z_1^c = \frac{Z_{1\min} + Z_{1\max}}{2}.$$

Given that

$$Z_{1\max} = Z_{1\min} + TA_1 + TA_2,$$

we obtain

$$Z_1^c = Z_{1\min} + \frac{TA_1 + TA_2}{2}.$$

3. The average value of the component dimension  $A_2$ , which is found from the equation

$$Z_1^c = A_2^c - A_1^c,$$

whence

$$A_2^c = A_1^c + Z_1^c.$$

This component dimension is presented in the following form  $A_2^c \pm \frac{TA_2}{2}$ .

Let us consider solution of another variant of the considered task.

Fig. 5.24 shows the manufacturing dimensional chain which resulting dimension is the allowance  $Z_4$  and component dimensions are the manufacturing dimensions  $A_1 \dots A_4$ . Dimensions  $A_3$  and  $A_4$  coincide with the functional dimensions  $K_3$  and  $K_4$ , dimension  $A_1$  is found from the previously discussed dimensional chain. The minimum allowance  $Z_4$  and limit deviations of

the  $A_1$  are known values. It is necessary to determine basic size of  $A_1$  with the help of the maximum-minimum method.




Fig. 5.24 Manufacturing dimensional chain with an allowance in a capacity of a resulting dimension

The task is solved as follows.

Tolerance of the dimension  $A_2$  is found

$$T A_2 = \Delta_u A_2 - \Delta_l A_2 .$$

Average value of the allowance  $Z_4$  is found:

$$Z_4^c = Z_{4\min} + \frac{\sum_{i=1}^{n+p} T A_i}{2} ,$$

where  $\sum_{i=1}^{n+p} T A_i$  is the sum of tolerances of component dimensions (manufacturing dimensions) of the dimensional chains.

From the equation

$$Z_4^c = A_3^c + A_4^c - A_1^c - A_2^c$$

the average value of the  $A_2$  is found:

$$A_2^c = A_3^c + A_4^c - A_1^c - Z_4^c .$$

Basic size of the dimension  $A_2$  will be:

$$A_2 = A_2^c - \frac{\Delta_u A_2 + \Delta_l A_2}{2} . \quad (5.1)$$

**Task of calculation of the manufacturing dimensions in order to ensure functional dimensions that are not directly ensured during manufacture of the part.** Fig. 5.25 shows manufacturing dimensional chain, the resulting dimension of which is the functional dimension  $K$ . In this chain basic sizes and limit deviations of the component dimensions (manufacturing dimensions)  $A_1$ ,  $A_3$  and  $A_4$  are known. Dimension  $A_4$  coincides with the functional dimension, dimensions  $A_1$  and  $A_3$  are found from the previously discussed dimensional chains. Tolerance of the dimension  $A_2$  is also a known value. It is required to find the basic size and limit deviations of the dimension  $A_2$ . This task, which also considered as mixed, is solved as follows.




Fig. 5.25 Manufacturing dimensional chain with a functional dimension as a resulting dimension

Firstly, it is checked whether the designed manufacturing process ensures required accuracy of the functional dimension. This is done at the beginning of the calculation process.

For maximum-minimum method of calculation the condition of ensuring accuracy of the functional dimension can be written as

$$TK \geq \sum_{i=1}^{n+p} TA_i. \quad (5.2)$$

For statistical method of calculation (assuming a normal distribution of manufacturing dimensions and  $TA_i = 6\sigma$ ), this condition becomes

$$TK \geq \sqrt{\sum_{i=1}^{n+p} (TA_i)^2}. \quad (5.3)$$

When inequalities (5.2) and (5.3) are satisfied, then from the equation (see Fig. 5.25)

$$K^c = A_1^c + A_4^c - A_2^c - A_3^c$$

the average value of the dimension  $A_2$  is found:

$$A_2^c = A_1^c + A_4^c - A_3^c - K^c.$$

This dimension can be written as

$$A_2^c \pm \frac{TA_2}{2}.$$

If these inequalities are not satisfied, then it is needed either to tighten tolerances of manufacturing dimensions (this will require more frequent adjustments of the technological system) or to make some adjustments in the process of part manufacturing, for example, change manufacturing datums and (or) bring in additional processing steps.

If necessary to recalculate the nominal values of manufacturing dimensions (from their average values) the relation (5.1) should be used.

## 5.10 Selection of Cutting Parameters and Standards of Time

Cutting parameters are assigned, taking into account type of operation, type and dimensions of the tool, cutting tool material, workpiece material, type and condition of the machine tool. It is assumed that the cutting has optimal geometric parameters.

Calculation of cutting parameters for turning operations is conducted in the following sequence.

1. Depth of cut  $t$  (mm) is determined. Its value should be taken equal to the maximum allowance for machining. In case of low rigidity of the technological system (workpiece hardness) and low machine power, the allowance is removed in several passes.

2. Feed rate  $S$  (mm/rev) is found. In rough turning, the feed rate value is the maximum permissible by machine power, rigidity of the technological system, strength of the insert and toolholder. In finish turning, the feed rate is selected depending on the required roughness. In both cases, feed rates are selected according to the recommendations and then adjusted with the machine tool capability.

3. Cutting speed  $V$  (m/min) for external longitudinal and radial turning and boring is calculated by the known empirical equation

$$V = \frac{C_v}{T^m t^x S^y} K_v.$$

In this case, tool life  $T$  (minutes) of the cutting tool is selected by the relevant standard values.

According to the calculated cutting speed  $V$ , the spindle speed is found as a number of revolutions per minute

$$n = \frac{1000V}{\pi d_w},$$

where  $d_w$  is a workpiece diameter (mm). The RPM is adjusted with the capability of the machine tool. Moreover, as the actual spindle speed  $n_f$  the nearest lowest value to  $n$  is taken, and then the actual cutting speed is determined

$$V = \frac{\pi d_w n_f}{1000}.$$

4. The components of the cutting force ( $P_z$ ,  $P_y$ ,  $P_x$ ) are determined. Their values (in newtons) are determined by the well-known equation

$$P_{z,y,x} = 10C_p t^x S^y V^n K_p.$$

(The values of the exponents in the equations for cutting speed and cutting force components are different.)

5. The cutting power (kw) is determined

$$N = \frac{P_z V}{1020 \cdot 60}$$

Then the power of the machine tool drive is determined

$$N_{dr} = \frac{N}{\eta}$$

where  $\eta$  is the efficiency of the drive, which is taken according to the machine specification. Power of the drive is compared with the power of the main electric motor of the machine tool  $N_{mt}$ . If  $N_{dr} > N_{mt}$  then it is needed to reduce the cutting speed.

In multi-tool cutting, when several tools are in cut at the same time, the tool life should be increased compared to the single-tool cutting. This should be done for the multiple-machine manning as well.

It can be roughly assumed that the tool life for multi-tool cutting

$$T_{mt} = TK_{Tt}$$

and for multiple-machine manning

$$T_{mm} = TK_{Tm}$$

where  $T$  is the tool life of the limiting tool, which is the tool that cuts the surface of the largest diameter and length;  $K_{Tt}$  is the coefficient of tool life correction for multi-tool cutting;  $K_{Tm}$  is the coefficient of tool life correction for multiple-machine manning. Values of these coefficients are shown in Tables 5.5 and 5.6

Table 5.5

*Coefficient of tool life correction  $K_{Tt}$ , depending on the number of simultaneously working tools*

number of working tools	1	3	5	8	10	15
$K_{Tt}$	1	1.7	2	2.5	3	4

Notes: 1. When the tools are uniformly loaded the coefficient  $K_{Tt}$  should be increased by 2 times.

2. For tools loaded with a large inequality, coefficient  $K_{Tt}$  should be reduced by 25-30%.

Table 5.6

*Coefficient of tool life correction  $K_{Tm}$ , depending on the number of simultaneously manned machines*

Number of machines manned	1	2	3	4	5	6	7 and more
$K_{Tm}$	1.0	1.4	1.9	2.2	2.6	2.8	3.1

Grinding parameters are selected on the recommendations contained in the reference books. Power is calculated by empirical equations.

Standard times for cutting operations are determined using the relations given in Section 1. Machining time is calculated for processing steps. For processing steps executed simultaneously, machining time is equal to the time of the longest processing step. Auxiliary time is determined according to standard values for its elements that do not overlap the machining time. The other components of the OCPP are taken as a percentage of the operation time. Setup time is found according to the standard values.

Knowing the contents of the operations, labour grades are set according to the wage rate handbooks.

### 5.11 Definition of Technical-Economic Parameters of Manufacturing Process

The process of parts manufacture can be designed in several variants that are more or less different from each other, but ensure all the technical requirements for the parts. To select the most rational of these variants, it is needed to compare their technical and economic indicators.

On the early stages of the process planning, the special indicators are used.

When a type of workpiece is being chosen, the material usage ratios are determined

$$K_{\text{mu}} = m_p / m_w ,$$

where  $m_p$ ,  $m_w$  are the masses of a part and of a workpiece, respectively. Preference is given to the method that provides greater  $K_{\text{mu}}$ . Further, the expected reduction of the material consumption during production is calculated

$$\Delta M = (m_{w_1} - m_{w_2})N ,$$

where  $m_{w_1}$  and  $m_{w_2}$  are the masses of workpieces of the comparable versions of their production;  $N$  is the volume of production.

During the design stage of the manufacturing process, the machining time ratio is determined. It is found as follows:

- for operations

$$\eta_0 = t_{mi} / t_{oci} ;$$

- for entire manufacturing process

$$\eta_0 = \frac{\sum_{i=1}^m t_{mi}}{\sum_{i=1}^m t_{oci}} ,$$

where  $t_{mi}$  and  $t_{oci}$  are the machining time and OCPP of the  $i^{\text{th}}$  operation;  $m$  is the number of operations in the manufacturing process. The higher is the value  $\eta_0$ , the more efficiently the machine tools are used.

At this stage the complexity of parts machining is also found

$$T_d = \sum_{i=1}^m t_{oci} .$$

For batch production the complexity of machining of batch of parts is calculated

$$T_b = n \sum_{i=1}^m t_{oci} + \sum_{i=1}^m t_{si} ,$$

where  $t_s$  is the setup time of the  $i^{\text{th}}$  operation;  $n$  is the number of parts in a batch.

At the final stage of the process development, various variants of its implementation are assessed by comparing costs of production, which reflects costs of labour and materialized labour.

If the compared variants of the manufacturing process no additional capital investments (such as purchase of new equipment) are required, the cost saving is calculated as:

$$E = (C_1 - C_2)N ,$$

where  $C_1$  and  $C_2$  are the costs of components manufacture by the compared variants.

If the implementation of the variants requires additional capital investments, then the ratio of comparative effectiveness is calculated

$$E = \frac{C_{a_1} - C_{a_2}}{K_2 - K_1} ,$$

where  $C_{a_1}$ ,  $C_{a_2}$  are the manufacturing costs of the annual production for the compared variants;  $K_1$ ,  $K_2$  are additional capital investments for the variants. If  $E \geq E_n$  ( $E_n$  is a normative ratio of effectiveness, which is equal to 0.2 for mechanical engineering), then the second variant of the process is more advantageous. If  $E < E_n$ , then the first variant is better.



## Review Questions

1. Give classification of manufacturing processes.
2. What is the sequence of development of a uniform manufacturing process?
3. How can a method of production be defined during the manufacturing process designing?
4. What are the requirements that the part design must comply with for manufacturability?
5. What dimensions should be specified on the part drawing, when some surfaces of the part are not exposed to machining?
6. What factors define form and production method of a workpiece?
7. What are the requirements that the workpiece design must comply with for manufacturability?
8. What is a complex workpiece?
9. What are the principles of manufacturing datums selection, explain their essence?
10. What is influenced by the selection of manufacturing datums for the first operation?
11. How are manufacturing datums for the first operation selected?
12. How are machining routes for individual surfaces of the part formed?
13. How are operations of the manufacturing process formed?
14. What considerations guide the selection of machine tools, fixtures and tools?
15. How can you calculate minimum allowances for machining?
16. How are tolerances of manufacturing dimensions allocated?
17. How does the mounting error influence on manufacturing dimensions?
18. What are the conditions for calculation of manufacturing dimensions?
19. What is the sequence of calculation of cutting parameters for roughing and finishing?
20. How can you evaluate cost-effectiveness of manufacturing process variants?

## 6. Fundamentals of Product Assembling Processes

### 6.1 General Concepts. Classification of Joining Methods. Types of Assembly

Assembly is a final stage of production and it largely determines quality of products. For example, a rolling bearing mounted with a small misalignment or a slightly undertightened screw joint, can impair normal operation of the machine and cause its premature failure.

The assembly is notable for high labour intensiveness, which is about 20 to 50 % of the total complexity of manufacturing. The main portion (50...55%) of the bench work and assembly work is manual work, requiring great physical effort and highly skilled workers; currently only 6...7 % of total amount of assembly work is automated. Therefore, the actual task of mechanical engineering is mechanization and automation of the assembly.

*Assembly process* is a process that includes actions aimed at mounting and joining components of a workpiece or a product.

*Assembly operation* is a manufacturing operation aimed at mounting and joining components of a workpiece or a product.

All joints according to the integrity of components during the disassembly are divided into temporary and permanent joints. Disassembly of the first occurs without damaging components of a product; disassembly of the latter damages the components.

According to possibility of relative movement, all joints are divided into *movable* and *fixed* joints. In movable joints, it is possible to move components with respect to each other; in fixed joints, movements are impossible.

According to the shape of mating surfaces, the following joints are distinguished: *planar, cylindrical, conical, spherical, helical, profiled*.

According to the method of joining, joints are divided as follows: *threaded, wedge, pin, key, spline, welded, soldered, riveted, glued, flanged, nipple, connector, pressed, seamed, beaded, combination*.

Assembly is divided into subassembly and overall assembly. Subassembly is performed for *subunits* that can be assembled separately from the product or components of the product and can perform a certain function in a single product only in conjunction with other components. If the assembly unit has a complete interchangeability, has possibility to be assembled separately from the other components of the product or the product as a whole, and can perform a certain function in the product or by itself, then it is called an *ag-*

*gregate*. For example, engine of a vehicle is an aggregate. Assembly of a product or its part from the aggregates is called *aggregate assembly*.

According to stages of the assembly process, there are:

- preliminary assembly;
- intermediate assembly;
- assembly for welding;
- final assembly.

*Preliminary assembly* is an assembly of workpieces, components or products as a whole, which subsequently will be disassembled. Preliminary assembly, for example, is performed to determine a size of the fixed compensator.

*Intermediate assembly* is an assembly of workpieces performed for their machining as a whole. For example, the intermediate assembly is performed for a housing and a cover of a reducer for subsequent machining of holes (for mounting the bearings), surfaces adjacent to the holes and mounting holes for bearings covers.

*Assembly for welding* is performed to give the desired relative position of the connected components of a product, which are set-up and clamped in special fixtures.

*Final assembly* is an assembly of a product or its unit, when its subsequent disassembly, during the manufacturing, is not planned.

However, after the final assembly of large, unique products of heavy machinery (large steam and hydraulic turbines, machine tools, presses) they are partially disassembled for delivery to consumers.

According to the mechanization and automation, assembly is divided into *mechanized*, *automated* and *automatic*. In automated assembly, the manufacturing means are partly operated by humans; in automatic assembly, these means are operated without direct human intervention.

In addition to direct assembling actions aimed at joining parts of the product, assembly also involves a number of others activities. Types of activities that are performed during the assembly and labour intensiveness are shown in Table 6.1.

Table 6.1

*Activities performed during assembly [7]*

Activity	Short description	Share in total assembly work content, %	
		in small-batch production	in mass production
Preliminary	Preparing parts as well as finished products into the condition required by the assembly: deconservation, washing, sorting by size groups, packing into containers, etc.	5...7	8...10
Fitting	Ensuring joining operations and technical requirements: filing and deburring, lapping, polishing, scraping, drilling, reaming, leveling.	20...25	--
Assembling	Joining of two or more parts to obtain subassemblies and parts of the main production: by screwing, pressing, riveting etc.	44...47	70...75
Adjusting	Actions carried out during or after the assembly to achieve the required accuracy of the mutual position of parts and assembly units of the product.	7...9	6...7
Control	Actions carried out during or after the assembly to verify compliance of assembly units and products with the parameters specified on drawings and specifications.	10...12	8...10
Disassembling	Partial disassembling of an assembled product to prepare it for packaging and transportation to the consumer.	6...8	3...4

## 6.2 Forms of Assembly Organization

Organizational form of assembly is determined by method of production and size and weight of the assembled product.

Assembly is divided into *synchronous* (flow) and *non-synchronous* (non-flow) assembly. Synchronous assembly is characterized by continuous or periodic movement of products being assembled or workers that perform

assembly at a constant rate (Takt time). When these conditions are not met, the assembly is considered as non-synchronous.

During assembly, a product may remain in the same working place (assembly stand, shop floor) or move intermittently or continuously, for example, by a conveyor. In the first case, the assembly is called *stationary*, in the second case it is *continuous*.

In general, the organizational forms of assembly can be represented as shown in Fig. 6.1.




Fig. 6.1 Organizational forms of assembly

During non-synchronous stationary assembly, the product, during the whole process of assembly, remains on the same workplace, to which the components, subunits and aggregates are delivered. Assembly is performed by a worker or a group of workers. The workplaces are equipped with corresponding equipment (presses, machine tools, etc.), universal fixtures and lifting-transfer machines.

Assembly works in a non-synchronous stationary assembly include a variety of steps and operations, which places high demands on the skills of the workers. Assembly steps are usually performed in a sequence, which lengthens the assembly cycle and reduces other technical economic parameters.

The economical area of application of non-synchronous stationary assembly is job and small-batch production.

*Non-synchronous continuous assembly* differs in that the product being assembled periodically moves from one workplace to the other one. Assembly operations are performed by individual workers or groups of workers who specialize in particular jobs.

Workplaces are linked together with transfer systems (roller conveyors, rail cars, etc.). After finishing the operation, work moves the product to the next workstation. For small sized products, this can be done manually. To compensate for assembly time variation, storages (buffers) are created between the work stations.

Workplaces are equipped with workbenches, assembly fixtures and tools, measuring tools, shelves for parts and subassemblies.

Better technical equipment and specialization of workplaces increases productivity, assembly quality and shortens the cycle.

Non-synchronous continuous assembly is used in batch production.

During *synchronous stationary assembly*, all products remain at the same workstations, while workers or groups of workers move between the workstations in equal time intervals equal to the Takt time by a signal. Each worker (or a group) performs the same operation for each of the products being assembled at the workstations.

Particular specialization of workers improves assembly quality and productivity.

The economical use of synchronous stationary assembly is in large-batch production of heavy large-size machinery (heavy-duty vehicles, aircrafts, etc.).

In *synchronous continuous assembly* the product being assembled moves continuously (during the Takt time) or periodically (in a Takt time) from one workplace to the other one, on which one assembly operation is performed.

Various conveyors (belt, chain, etc.) are used to transfer assembled products. Belt conveyors are used in assembly of products of small size and weight, for example, watches, small motors, carburetors, etc. Chain conveyors move rail cars with fixtures, in which assembled products are clamped. Overhead chain conveyors that help to free floor space and improve working conditions for workers are widely used in mass production.

In synchronous continuous assembly, workplaces are placed on both sides of the conveyor and are equipped with fixtures, assembly and measuring tools, shelves for parts and subassemblies. If the conveyor is in continuous movement, the worker follows the conveyor during the operation and then returns to the initial position.

Synchronous continuous assembly compared to a non-synchronous provides higher technical and economic parameters. For example, at the Volga Automobile Plant (Volzhsky Avtomobilny Zavod or VAZ), cars are assembled on a continuously moving suspended chain conveyor with length of about 2 km, assembly Takt time is 1 min.

The economical area of continuous assembly application is a large-batch and mass production.

### **6.3 Fundamentals of Assembling Process Design**

Designing of assembly process is performed prior to manufacturing process designing. Such a sequence is explained by the fact that, during the as-

sembly process designing, a number of changes in product design and technical requirements (for accuracy, for example) can be made.

### **6.3.1 Input data and Sequence of Assembling Process Design**

Initial information needed for designing of assembly process is divided into basic, reference and guidelines information.

Basic information in designing assembly process for new factories and enterprises includes assembly drawings of a product and its subassemblies, parts lists, assembly and tests specifications, working drawings of parts of the product, annual volume of production. An assembly drawing should contain all necessary projection and sectional views, sizes ensured by assembly, fits, mass of the product and its component parts. Technical specifications indicate accuracy of assembly, quality and tightness of couplings, rigidity of joints, thread tightening torques, accuracy of balancing of rotating parts, instructions on how to make joints and methods of products control.

Information for designing assembly process for existing factories should also include information about manufacturing means and floor space available in the assembly shop and other industrial conditions.

Reference information include catalogues and handbooks on assembly equipment and fixtures, standard times for benchwork and assembly work, etc.

Guidelines is data about prospective processes used in the industry, standard for technical documentation, main requirements for trends in production development at the enterprise.

Assembly process is designed in the following sequence.

1. Method of production and corresponding organizational form of assembly are defined. Method of production is defined in the same way as for manufacturing processes. The average OCPP of the assembly operations is taken according to the assembly process of a similar product or it is calculated according to extended standard times for different sets of assembly work.

2. Assembly drawings of the product and its subassemblies are analysed for compliance with the requirements for design-for-assembly in the conditions of the enterprise.

3. Then sequence of assembling of all subassemblies and components of the product is established, and schemes for overall assembly and subassembly are built. It should be taken into account that the overall assembly shall be assembled from the greatest possible number of pre-assembled units and the least possible number of individual parts; assembly of small units, as well as auxiliary work should be avoided in overall assembly.

4. Then it is required to establish the most effective ways of joining the parts, checking their position, securing all subassemblies and components of the product. Structure and content of assembly operations is formed and methods of control and testing of the product are determined.

5. Next, special fixtures needed for the assembly process are designed.

6. Resources needed for assembly works are rated, and technical and economic parameters of the assembly process are assessed.

7. Technical documentation is issued.

### **6.3.2 Analysis of Assembly Drawings for Manufacturability**

Analysis of assembly drawings for manufacturability is performed to assess whether the product design meets requirements for assembly. These requirements can be summarized as follows.

First of all, machine design must permit its assembly of pre-assembled subunits. This helps to assemble subunits and overall assembly simultaneously, which reduces machine assembly cycle. A significant advantage is provided in case the subunit is an aggregate, which, before being supplied to the overall, undergoes tests and inspection to eliminate defects on the overall assembly and to improve product quality.

In general, machine should have a simple layout and don't cause troubles in assembly. The number of items of machinery components and subassemblies should be as small as possible; it is also desired to ensure their interchangeability. The use of standard components and subunits (aggregates) allows using relatively cheap ones. Reducing the range of screws and bolts used allows the most efficient use of threaded joints and power tools in the assembly.

The reduction of parts in the product is achieved through the combining several functions in one part. For example, a screw with a collar (Figure 6.2, *a*) serves as a screw and as a washer as well. By manufacturing a screw of nylon, the sealing of a joint is provided. By bending the edge of a screw collar (Fig. 6.2, *b*) or by making the support surface of a nut conical (Fig. 6.2, *c*), their locking (retaining) is achieved.

The machine design must allow easy and free application of high-performance power tools to join the parts; ease of hoisting for transportation and installation of the parts into the product being assembled. Assembly of machines must be carried out without the use of complex tools, preferably without rotating the base component (from which the assembly begins), through simple actions aimed at mounting parts for assembly, applying and



withdrawal of assembly tools. A base component must be sufficiently rigid and have reliable manufacturing datums, which ensure high accuracy of its mounting. It is required to reduce machining of assembled parts during the assembly, as well as fitting works.




Fig. 6.2 Examples of parts and couplings designs for assembly

In addition to these general requirements, it is also needed to take into account special conditions of various joining operations. For assembling couplings with clearance or interference fit, the components should be supplied with chamfers (Fig. 6.2, *d*), or guiding lands A (Fig. 6.2, *e*) to eliminate deflection. Also, to eliminate scratching while pressing a pin into the hole of a yoke (Fig. 6.2, *f*), the mating surfaces of the parts should be made stepped, the width of the hole A of the yoke should be greater than the width of the hole B ( $b_1 > b_2$ )

Screws and nuts to increase assembly productivity should be tightened with socket wrenches. To make this possible, sufficient distance from the screw (nut) to the wall of the body portion should be provided (Fig. 6.2, *g*). In multi-bolt (multi-screw, multi-stud) joining, the distance between the axes of the threaded parts should be sufficient for application of multi-spindle tightening devices. Nuts positioned on inner surfaces of parts, should be locked with split pins for reliable retaining, nut located on the outer surfaces can be installed with spring washers, which simplifies assembly.

Automatic assembly makes additional demands to the design of a product. Components should be of simple symmetrical shape, which simplifies

task of their orientation and feeding by the bowl feeder to working position of the automatic assembling machine. Design of components should also prevent them from interlocking. It is advisable to apply standard or normalized components as much as possible, in order to limit the types of assembly devices used. It is advisable to replace temporary joints by the permanent ones, using riveting, beading, etc. The assembly should be performed with simple (mainly, linear) motions of the automatic machine actuator without turning the product. To improve reliability of the automatic assembly machines, it is advantageous to increase accuracy of the components in some cases.

An important step in manufacturing inspection, is tolerance analysis of the product design. The choice of methods to ensure required accuracy of resulting dimensions of dimensional chains, calculation of tolerances and limit deviations of the component dimensions is performed by a design engineer. Manufacturing engineer checks these decisions. Such verification implies analysis of validity of the methods adopted to achieve accuracy of resulting dimensions in dimensional chains of subunits and product as a whole, and solution of inverse tasks for these chains.

On the basis of manufacturing inspection of assembly drawings and components drawings, a list of comments and proposals on product redesigning and adjustment of accuracy parameters of parts is composed, this list is submitted to designer's approval. Engineering designer after analyzing these comments and suggestions can make changes in product design to enhance its manufacturability during assembly.

### **6.3.3 Design of Assembly Sequence. Assembling Process Design**

Assembly sequence is determined by construction of the product and methods adopted to ensure accuracy of resulting dimensions of dimensional chains.

The overall assembly begins with the mounting of a base component, which usually is a frame, bed, base, etc. The base component is placed in a position convenient for assembly. If this component is not rigid enough, it is set (often with alignment) in a rigid fixture and, in case of continuous assembly, is transferred together with this fixture. Assembly of any unit starts with the installation of the base component. After the base component is secured, all components and subunits are mounted on this component.

Design of assembly sequence is guided by the following general recommendations.

1. The sequence of parts mounting should be such that the previously assembled parts do not hamper the mounting of the following parts.
2. Ensure minimum partial dismantling of the previously assembled units during the process of assembling.
3. Assembling complexity of most components should be approximately the same.
4. If accuracy of resulting dimensions is ensured by fitting, then the fitting work should be performed out of the product being assembled.

The sequence of assembly can be conveniently presented in the form of diagrams (Figure 6.3), which are developed based on the assembly drawings of the product. Firstly, diagram of the overall assembly is composed (Fig. 6.3, *a*), and then diagrams of subassemblies are made (Figure 6.3, *b*). Components and units on assembly diagrams are depicted as rectangles. Rectangles of a component indicate its name, item number and quantity. Subassembly unit is designated according to the base component, from which this unit is assembled, adding before the item number of the part code "Un.". Assembly diagrams may contain inscriptions, explaining the nature of the assembly work (Fig. 6.3, *b*).

Assembly diagrams are the documents, according to which workers of the assembly shops familiarize with the product assembly sequence and content of assembly work, organize assembly process, prepare and supply components and units in a certain sequence to the assembly.

Assembly process is designed on the basis of the assembly diagrams. Engineers form operations, select or design and manufacture means for the assembly process, determine standard times needed to perform assembly operations.

Norms for assembly works are defined using the standard times for fitting and assembly work, which contain standard operation time for the most common assembly actions.

Composition of assembly operations depends on the method of production and corresponding organizational form of assembly.

In non-synchronous stationary assembly, it is desired to compose an operation of a set of activities, the implementation of which could be performed by a worker or a group of workers who specialize in performing this type of work. Commonly, an operation is an assembly of a unit.

In non-synchronous continuous assembly, synchronous stationary assembly and synchronous continuous assembly, duration of operations must be equal to or a multiple of the Takt time. If duration of an operation is an integer times higher than the Takt time, the operation must be performed in multiple lines. Synchronization of assembly operations in a synchronous assembly can be achieved by altering content of operations, finding more effi-

cient assembly methods, by the use of equipment and fixtures that is more efficient, as well as by changing parameters of equipment operation.




Fig. 6.3 Assembly diagrams: a – overall; b – subassembly

Figure 6.4 shows, as an example, a sketch of a unit (hub), Fig. 6.5 shows a diagram of its assembly. The assembly process begins with the pulley assembly (Un. 8). This process involves successive installation of a seal ring 10, the first bearing 7, bushing 9 and the second bearing 7 inside the pulley 8. After that, a pulley (Un. 8) is pressed onto the hub 11, after which the

retaining ring 3 is installed. Next, the flange (Un. 5) is assembled, for doing this the flange 5 is mounted onto the cover 1 and secured with the screws 2, then the gasket 6 is set. Then the assembled flange (Un. 5) is fastened by the screws 4 to the partially assembled hub, thus the unit is assembled (Un. 11).




Fig. 6.4 Sketch of a unit (hub)

Name and contents of the hub assembly operations Наименование are given in Table 6.2.

Таблица 6.2.

*Hub assembly process*

№ operation	Name of the operation	Operation content (sequence)
005	Pulley assembly (Un. 8)	<ol style="list-style-type: none"> <li>1. Clamp the pulley 8 in a fixture.</li> <li>2. Set the ring 10.</li> <li>3. Lubricate and set the bearing 7.</li> <li>4. Wipe and install the bushing 9.</li> <li>5. Lubricate and set the bearing 7.</li> </ol>
010	Pulley mounting (Un. 8)	<ol style="list-style-type: none"> <li>1. Secure the hub 11 in a fixture.</li> <li>2. Mount the pulley (Un. 8) onto the hub 11.</li> <li>3. Set the retaining ring 3.</li> </ol>
015	Flange assembly (Un. 5)	<ol style="list-style-type: none"> <li>1. Secure the flange 5 in a fixture.</li> <li>2. Install the cover 1.</li> <li>3. Fasten the cover by the screw 2.</li> <li>4. Set the gasket 6.</li> </ol>
020	Flange mounting (Un. 5)	<ol style="list-style-type: none"> <li>1. Mount the flange (Un. 5).</li> <li>2. Fasten the flange (Un. 5) with screws 4.</li> </ol>
025	Inspection	<ol style="list-style-type: none"> <li>1. Check the ease of rotation of the pulley 8.</li> <li>2. Check run-out of the surface B with respect to the surface A.</li> </ol>




Fig. 6.5 Diagram of a hub assembly

## **Review Questions**

1. Give classification of assembling processes according to stages of the assembly process and level of mechanization and automation.
2. Name the basic forms of assembly organization and characterize them.
3. What is the sequence of design of an assembly process?
4. What does the manufacturing inspection of assembly drawings include?
5. What are the requirements that the part design must comply with for manufacturability during assembly?
6. How are assembly diagrams constructed?
7. How is content of the assembly operations defined?

## References

1. Altan, T., Ngaile, G. and Shen G., Cold and Hot Forging: Fundamentals and Application, ASM International, 2004
2. Baudin, M., Lean Assembly, Productivity Press, 2002
3. Brown, J., Advanced Machining Technology Handdbook, McGraw-Hill, 1998
4. Connor, J., Six Sigma and other Continuous Improvement Tools for the Small Shop, Society of Manufacturing Engineers, 2001
5. Darbyshire, Alan. Mechanical Engineering. BTEC National Option Units / A. Darbyshire. — Oxford : Newnes, 2003. — 411 p. : ил. — Index: p. 407-411. — ISBN 0-7506-5761-8.
6. Drake P. Dimensioning and tolerancing handbook. McGraw-Hill, New York, 1999.
7. Encyclopedia of production and manufacturing management / Editor Paul M. Swamidass. Kluwer Academic Publishers, 2000.
8. Erdel, B., High-Speed Machining, Society of Manufacturing Engineers, 2003
9. Foster L.W. Geometrics III: The application of geometric and tolerancing technique. Addison-Wesley, 1994.
10. Handbook of Surface Treatment and Coatings, ASME Press, 2003
11. Heine R., Principles of Metal Casting, McGraw-Hill, 1999
12. Lange, K., Handbook of Metalforming, McGraw-Hill, 1985
13. Machinery's Handbook, Industrial Press, revised periodically
14. Manufacturing Engineering and Technology. Fifth edition. Serope Kalpakjian, Steven R. Schmid, 2006
15. Quensenberry, C.P., SPC Methods for Quality Improvement, Wiley, 1997
16. Shackelford, J.E., Introduction to materials Science fo Engineers, 5th ed., Prentice Hall, 2000
17. Shigley, Joseph E. Mechanical Engineering Design / J. E. Shigley, C. R. Mischke. — 6 Edition. — New York : McGraw-Hill, 2001. — 1248 p. : il. — Index: p. 1237-1248. — ISBN 0-07-365939-8.
18. Stenerson, J. and Curran, K.S., Computer Numerical Control: Operation and Programming, 2nd ed., Prentice Hall, 2000
19. Tozawa, B. Bodek, N., The Idea Generator: Quick and Easy Kaizen, PCS Press, 2001
20. Virtual Machine Shop // <http://www.kanabco.com/vms/index.html>



21. Базирование и базы в машиностроении. Термины и определения. ГОСТ 21495-76. Изд-во стандартов, 1990. –35 с.
22. Базров Б.М. Основы технологии машиностроения: учебник для вузов. – М.: Машиностроение, 2005. –736 с.
23. Замятин В.К. Технология и автоматизация сборки: учебник для машиностроительных специальностей вузов. – М.: Машиностроение, 1993. –464 с.
24. Колесов И.М. Основы технологии машиностроения: учебник для машиностроительных специальностей вузов. – М.: Высшая школа, 1999. –591 с.
25. Маталин А.А. Технология машиностроения: учебник. – СПб.: Издательство «Лань». 2010. –512 с.
26. Обработка металлов резанием: справочник технолога / А.А. Панов, В.В. Аникин, Н.Г. Бойм и др.; под общ. ред. А.А. Панова. – М.: Машиностроение, 2004. –784 с.
27. Основы технологии машиностроения. Под ред. В.С. Корсакова. Учебник для вузов. –М.: Машиностроение, 1977. –416 с.
28. Размерный анализ технологических процессов / В.В. Матвеев, М.М. Тверской, Ф.И. Бойков и др. – М.: Машиностроение, 1982. –264 с.
29. Суслов А.Г. Технология машиностроения: учебник для студентов машиностроительных специальностей вузов. – М.: Машиностроение, 2004. –400 с.
30. Суслов А.Г., Дальский А.М. Научные основы технологии машиностроения. –М.:Машиностроение, 2002. –684 с.
31. Справочник технолога-машиностроителя. В 2-х т. Т. 1 / Под ред. А.М. Дальского, А.Г. Косиловой, Р.К. Мещерякова, А.Г. Сулова. –М.: Машиностроение-1, 2003. –912 с.
32. Справочник технолога-машиностроителя. В 2-х т. Т. 2 / Под ред. А.М. Дальского, А.Г. Сулова, А.Г. Косиловой, Р.К. Мещерякова. –М.: Машиностроение-1, 2003. –944 с.
33. Технология машиностроения. В 2 т. Т. 1. Основы технологии машиностроения: учебник для вузов / В.М. Бурцев, А.С. Васильев, А.М. Дальский и др.; под ред. А.М. Дальского. – М.: Изд-во МГТУ им. Н.Э. Баумана, 1997. – 564 с.
34. Цепи размерные. Основные понятия, методы расчета линейных и угловых цепей: Методические указания РД 50-635-87 / И.М. Колесов, Е.И. Луцков, А.И. Кубарев и др. –М.: Изд-во стандартов, 1987. –45 с.

Educational Edition

Национальный исследовательский  
Томский политехнический университет

СКВОРЦОВ Владимир Федорович

## ОСНОВЫ ТЕХНОЛОГИИ МАШИНОСТРОЕНИЯ

Учебное пособие

Издательство Томского политехнического университета, 2013

На английском языке

**Published in author's version**

Translator *A.B. Kim*

Linguistic Advisor Senior lecturer  
*A.I. Chudinova*

**Printed in the TPU Publishing House in full accordance  
with the quality of the given make up page**

Signed for the press 00.00.2009. Format 60x84/16. Paper "Snegurochka".  
Print XEROX. Arbitrary printer's sheet 000. Publisher's signature 000.  
Order XXX. Size of print run XXX.



Tomsk Polytechnic University  
Quality management system  
of Tomsk Polytechnic University was certified by  
NATIONAL QUALITY ASSURANCE on BS EN ISO 9001:2008



**TPU PUBLISHING HOUSE.** 30, Lenina Ave, Tomsk, 634050, Russia  
Tel/fax: +7 (3822) 56-35-35, [www.tpu.ru](http://www.tpu.ru)